

Inspections Damaged Pole Report

Service Request 26-00705607 Sector Gateway Primary Primary
 Location on Service Request 200 Grundy St
 Grid : 4010340 LLC: 7148

Descriptive Location and Comments:

Street: Grundy St
 Side of Street: N/S E/S S/S W/S ✓
 Pole location: 1" 2" ✓ 3" 4" 5" 6" Other
 Direction : N/O ✓ E/O S/O W/O
 Street or Landmark: Gough St

Condition of Pole:

Deteriorated
 Missing ✓
 Damaged
 Arm/Fixture Missing
 Other

Pole Size :

11'6"
 12' ✓
 15' ✓
 30'
 40'
 Other

Type of Pole:

Aluminum ✓
 Steel
 Galvanized Steel
 Fiberglass
 Bolton Mill
 Otterbein
 Homeland
 Wooden
 Other

**NEEDS
NEW
BASE**

Fixture Type:

Cobra Head ✓
 PMA
 Otterbein
 Homeland
 Bolton Mill
 Victorian Acorn
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide ✓
 LED ✓
 Other

Wattage:

100
 150
 175
 200
 250 ✓
 400
 1000

Arm:

6' ✓
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing ✓

Pedestal Base:

Yes ✓
 No

Base Condition:

Bolts ✓
 Wires ✓
 Conduit ✓

Good

✓
✓
✓

Bad:

Base Type:

Metal ✓
 Concrete

Date: 8/3/2026 Inspector's Signature T. Blackman

