

Inspections: Damaged Pole Report

Service Request: 26-00706227 Sector: Gateway: Primary:

Location on Service Request: 901 Woodson Rd

Grid: 2060140 LLC: 7098

Descriptive Location and Comments:

Street: Woodson Rd

Side of Street: N/S ✓ E/S S/S W/S

Pole location: 1st 2nd ✓ 3rd 4th 5th 6th Other

Direction: N/O E/O ✓ S/O W/O

Street or Landmark: Cedarcroft Rd

Condition of Pole:

Deteriorated ✓
Missing ✓
Damaged
Arm/Fixture Missing
Other

Pole Size:

11'6"
12'
25' ✓
30'
40'
Other

Type of Pole:

Aluminum ✓
Steel
Galvanized Steel
Fiberglass
Bolton Mill
Otterbein
Homeland
Wooden
Other

**NEEDS
New
Base**

Fixture Type:

Cobra Head ✓
PMA
Otterbein
Homeland
Bolton Mill
Victorian Acorn
Other

Lamp Type:

HPS Vapor
Mercury Vapor
Metal Halide
LED ✓
Other

Wattage:

100
150
175
200
250 ✓
400
1000

Arm:

6' ✓
10'
15'
20'
Other

Arm Condition:

Damaged
Missing ✓

Pedestal Base:

Yes
No ✓


Base Condition:

Good ✓
Bad:
Bolts
Wires
Conduit

Base Type:

Aleral
Concrete ✓

Date: 8/13/2026 Inspector's Signature: T. Blackman



25 Foot Aluminum
pole
cobra head
LED