

Inspections - Damaged Pole Report

Service Request 26-00709405 ctor. Gateway Primary Orleans St & N. Wolfe St
 Location on Service Request: Orleans St & N. Wolfe St
 Grid : 4010210 LLC: 5026

Descriptive Location and Comments:

Street: Orleans St
 Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐
 Pole location: 1" ☒ 2nd ☐ 3rd ☐ 4th ☐ 5th ☐ 6th ☐ Other ☐
 Direction : N/O ☐ E/O ☐ S/O ☐ W/O ☒
 Street or Landmark: Wolfe St


Condition of Pole:	Pole Size:	Type of Pole:
Deteriorated ☒	11'6" ☒	Aluminum ☐
Missing ☒	12' ☒	Steel ☐
Damaged ☐	25' ☐	Galvanized Steel ☐
Arm/Fixture Missing ☐	30' ☐	Fiberglass ☐
Other ☐	40' ☐	Bolton MH ☐
	Other ☐	Otterbein ☐
		Homeland ☒
		Wooden ☐
		Other ☐

Work order #
21112715

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☐	HPS Vapor ☐	100 ☐	6' ☐	Damaged ☐
PMA ☐	Mercury Vapor ☐	150 ☒	10' ☐	Missing ☐
Otterbein ☐	Metal Halide ☐	175 ☐	15' ☐	
Homeland ☐	LED ☒	200 ☐	20' ☐	
Bolton MH ☐	Other ☐	250 ☐	Other ☐	
Victorian Acorn ☒		400 ☐		
Other ☐		1000 ☐		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ☒	Bolts ☒	☒	☐	Aleral ☒
No ☐	Wires ☒	☒	☐	Concrete ☐
	Conduit ☒	☒	☐	

Date: 8/3/2026 Inspector's Signature: T. Blackman



HomeLand
Acorn Fixture