

Inspections: Damaged Pole Report

Service Request 26-00760260 Sector 5+ Gateway Primary

Location on Service Request: 1101 W. LAWRAHE ST

Grid : 1010240 LLC: 7416

Descriptive Location and Comments:

Street: W. LAWRAHE ST

Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐

Pole location: 1" ☒ 2" ☐ 3" ☐ 4" ☐ 5" ☐ 6" ☐ Other ☐

Direction : N/O ☐ E/O ☐ S/O ☐ W/O ☒

Street or Landmark: No Arlington Ave

Condition of Pole:

Deteriorated ☐
Missing ☒
Damaged ☐
Arm/Fixture Missing ☐
Other ☐

Pole Size :

11'6" ☐
12' ☐
25' ☒
30' ☐
40' ☐
Other ☐

Type of Pole:

Aluminum ☐
Steel ☒
Galvanized Steel ☐
Fiberglass ☐
Bolton Hill ☐
Otterbein ☐
Homeland ☐
Wooden ☐
Other ☐

**NEEDS
New
Base**

Fixture Type:

Cobra Head ☒
PMA ☐
Otterbein ☐
Homeland ☐
Bolton Hill ☐
Victorian Acorn ☐
Other ☐

Lamp Type:

HPS Vapor ☐
Mercury Vapor ☐
Metal Halide ☐
LED ☒
Other ☐

Wattage:

100 ☐
150 ☐
175 ☐
200 ☐
250 ☒
400 ☐
1000 ☐

Arm:

6' ☒
10' ☐
15' ☐
20' ☐
Other ☐

Arm Condition:

Damaged ☐
Missing ☒

Pedestal Base:

Yes ☒
No ☐

Base Condition:

Good ☒
Bad ☐
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete ☐

Date: 8/17/2026 Inspector's Signature: T. Blackman

