

Inspections Damaged Pole Report

Service Request 26-00759494 for Gateway Primary
 Location on Service Request. 3601 Lucille Ave
 Grid : 10 40 440 LLC: 7040

Descriptive Location and Comments:

Street: Lucille Ave
 Side of Street: N/S E/S S/S W/S ✓
 Pole location: 1" 2" ✓ 3" 4" 5" 6" Other
 Direction : N/O ✓ E/O S/O W/O
 Street or Landmark: Registerstown Ky

Condition of Pole:

Deteriorated
 Missing ✓
 Damaged
 Arm/Fixture Missing
 Other

Pole Size :

11'6" ✓
 12'
 25'
 30'
 40'
 Other

Type of Pole:

Aluminum ✓
 Steel
 Galvanized Steel
 Fiberglass
 Bolton Mill
 Otterbein
 Homeland
 Wooden
 Other

**NEEDS
New
Base**

Fixture Type:

Cobra Head
 PMA ✓
 Otterbein
 Homeland
 Bolton Mill
 Victorian Acorn
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide
 LED ✓
 Other

Wattage:

100
 150 ✓
 175
 200
 250
 400
 1000

Arm:

6'
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing

Pedestal Base:

Yes
 No ✓


Base Condition:

Good
 Bad ✓
 Bolts
 Wires
 Conduit

Base Type:

Metal ✓
 Concrete

Date: 8/19/2026 Inspector's Signature: T. Blackman



PMA
LED