

Inspections: Damaged Pole Report

Service Request 26-0077255 to Gateway, Prim Rd
 Location on Service Request: 3400 Edgewood
 Grid : 1020420 LLC: 7174

Descriptive Location and Comments:

Street: Edgewood Rd
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓
 Pole location: 1" ✓ 2" _____ 3" _____ 4" _____ 5" _____ 6" _____ Other _____
 Direction : N/O ✓ E/O _____ S/O _____ W/O _____
 Street or Landmark: Liberty Heights Ave

Condition of Pole:

Deteriorated _____
 Missing ✓
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" ✓
 12' _____
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum _____
 Steel ✓
 Galvanized Steel _____
 Fiberglass _____
 Bolton Mill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

NEEDS
NEW
BASE

Fixture Type:

Cobra Head ✓
 PMA ✓
 Otterbein _____
 Homeland _____
 Bolton Mill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide ✓
 LED ✓
 Other _____

Wattage:

100 _____
 150 ✓
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No _____

Base Condition:

Bolts _____
 Wires _____
 Conduit _____


Good

Bad:

Base Type:

Almetal _____
 Concrete _____

Date: 8/19/2026 Inspector's Signature: T. Blackman



PMA
LED