

Inspections - Damaged Pole Report

Service Request 26-00786099 Sector Gateway Primary
 Location on Service Request: S. HIGHLAND Ave & SCHUCK St
 Grid : 4010346 LLC: 7218

Descriptive Location and Comments:

Street: S. HIGHLAND Ave
 Side of Street: N/S E/S S/S W/S
 Pole location: 1" ✓ 2nd 3rd 4th 5th 6th Other
 Direction : N/O E/O S/O W/O ✓
 Street or Landmark: Fleet St

Condition of Pole:

Deteriorated
 Missing ✓
 Damaged
 Arm/Fixture Missing
 Other

Pole Size :

11'6"
 12'
 25' ✓
 30'
 40'
 Other

Type of Pole:

Aluminum
 Steel ✓
 Galvanized Steel
 Fiberglass
 Bolton Mill
 Otterbein
 Homeland
 Wooden
 Other

**NEEDS
New
Base**

Fixture Type:

Cobra Head ✓
 PMA
 Otterbein
 Homeland
 Bolton Mill
 Victorian Acorn
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide
 LED ✓
 Other

Wattage:

100
 150
 175
 200
 250 ✓
 400
 1000

Arm:

6' ✓
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing ✓

Pedestal Base:

Yes
 No


Base Condition:

Good Bad:
 Bolts
 Wires
 Conduit

Base Type:

Alural
 Concrete

Date: 8/24/2026 Inspector's Signature: T. Blackman



25 Foot
steel pole
cobra head
LED