

Inspections Damaged Pole Report

Service Request 26-00792632 for Gateway Primary 4805 Eastern Ave
 Location on Service Request: 4805 Eastern Ave
 Grid : 4010430 LLC: 6366

Descriptive Location and Comments:

Street: Eastern Ave
 Side of Street: N/S E/S S/S ✓ W/S
 Pole location: 1" ✓ 2" 3" 4" 5" 6" Other
 Direction : N/O E/O ✓ S/O W/O
 Street or Landmark: Oldham St

Condition of Pole:

Deteriorated
 Missing ✓
 Damaged
 Arm/Fixture Missing
 Other

Pole Size :

11'6"
 12' ✓
 25'
 30'
 40'
 Other

Type of Pole:

Aluminum
 Steel
 Galvanized Steel
 Fiberglass
 Bolton Mill
 Otterbein
 Homeland ✓
 Wooden
 Other

Fixture Type:

Cobra Head
 PMA
 Otterbein
 Homeland
 Bolton Mill
 Victorian Acorn ✓
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide ✓
 LED ✓
 Other

Wattage:

100
 150 ✓
 175
 200
 250
 400
 1000

Arm:

6'
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing

Pedestal Base:

Yes
 No

Base Condition:

Bolts ✓
 Wires ✓
 Conduit ✓


Good

Bad:

Base Type:

Alcral ✓
 Concrete

Date: 8/25/2026 Inspector's Signature T. Blackman



HomeIwud
Acorn Fextone