

Inspections: Damaged Pole Report

Service Request 26-00798183 Nor Gateway Primary
 Location on Service Request 442 E. North Ave
 Grid : 2010110 LLC: 5031

Descriptive Location and Comments:

Street: North Ave
 Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐
 Pole location: 1st ☐ 2nd ☒ 3rd ☐ 4th ☐ 5th ☐ 6th ☐ Other ☐
 Direction : N/O ☐ E/O ☐ S/O ☐ W/O ☒
 Street or Landmark: Greenmont Ave

Condition of Pole:

Deteriorated ☐
 Missing ☒
 Damaged ☐
 Arm/Fixture Missing ☐
 Other ☐

Pole Size :

11'6" ☐
 12' ☒
 25' ☐
 30' ☐
 40' ☐
 Other ☐

Type of Pole:

Aluminum ☐
 Steel ☐
 Galvanized Steel ☐
 Fiberglass ☐
 Bolton Hill ☐
 Otterbein ☐
 Homeland ☒
 Wooden ☐
 Other ☐

Fixture Type:

Cobra Head ☐
 PMA ☐
 Otterbein ☐
 Homeland ☐
 Bolton Hill ☐
 Victorian Acorn ☒
 Other ☐

Lamp Type:

HPS Vapor ☐
 Mercury Vapor ☐
 Metal Halide ☒
 LED ☒
 Other ☐

Wattage:

100 ☐
 150 ☒
 175 ☐
 200 ☐
 250 ☐
 400 ☐
 1000 ☐

Arm:

6' ☐
 10' ☐
 15' ☐
 20' ☐
 Other ☐

Arm Condition:

Damaged ☐
 Missing ☐

Pedestal Base:

Yes ☒
 No ☐

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒


Bad:

☐
☐
☐

Base Type:

Metal ☒
 Concrete ☐

Date: 8/26/2026 Inspector's Signature: T. Blackman



HomeLand
Acorn Fixture