

Inspections - Damaged Pole Report

Service Request 26-00800 473 Gateway Primary
 Location on Service Request: 1930 Heathfield Rd
 Grid : 2040220 LLC: 7411

Descriptive Location and Comments:


Street: Perry Pkwy
 Side of Street: N/S ✓ E/S ✓ S/S ✓ W/S ✓
 Pole location: 1st ✓ 2nd ✓ 3rd ✓ 4th ✓ 5th ✓ 6th ✓ Other ✓
 Direction : N/O ✓ E/O ✓ S/O ✓ W/O ✓
 Street or Landmark: Heathfield

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated <u>✓</u>	11'6" <u>✓</u>	Aluminum <u>✓</u>
Missing <u>✓</u>	12' <u>✓</u>	Steel <u>✓</u>
Damaged <u>✓</u>	25' <u>✓</u>	Galvanized Steel <u>✓</u>
Arm/Fixture Missing <u>✓</u>	30' <u>✓</u>	Fiberglass <u>✓</u>
Other <u>✓</u>	40' <u>✓</u>	Bolton Hill <u>✓</u>
	Other <u>✓</u>	Otterbein <u>✓</u>
		Homeland <u>✓</u>
		Wooden <u>✓</u>
		Other <u>✓</u>

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head <u>✓</u>	HPS Vapor <u>✓</u>	100 <u>✓</u>	6' <u>✓</u>	Damaged <u>✓</u>
PMA <u>✓</u>	Mercury Vapor <u>✓</u>	150 <u>✓</u>	10' <u>✓</u>	Missing <u>✓</u>
Otterbein <u>✓</u>	Metal Halide <u>✓</u>	175 <u>✓</u>	15' <u>✓</u>	
Homeland <u>✓</u>	LED <u>✓</u>	200 <u>✓</u>	20' <u>✓</u>	
Bolton Hill <u>✓</u>	Other <u>✓</u>	250 <u>✓</u>	Other <u>✓</u>	
Viktorian Acorn <u>✓</u>		400 <u>✓</u>		
Other <u>✓</u>		1000 <u>✓</u>		

Pedestal Base: Base Condition: Good ✓ Bad: ✓ Base Type: Metal ✓ Concrete ✓

Date: 8/27/2026 Inspector's Signature: T. Blackman



30 Foot
Aluminum w
pole
cobra Head
LED