

Inspections: Damaged Pole Report

Service Request: 26-00753 262 Gateway: Primary
 Location on Service Request: 900 Fell St
 Grid: 4020210 LLC: 7208

Descriptive Location and Comments:

Street: Fell St
 Side of Street: N/S E/S ✓ S/S W/S
 Pole location: 1st ✓ 2nd 3rd 4th 5th 6th Other
 Direction: N/O E/O S/O ✓ W/O
 Street or Landmark: THAMES ST

Condition of Pole:

Deteriorated
 Missing ✓
 Damaged
 Arm/Fixture Missing
 Other

Pole Size:

11'6"
 12' ✓
 25'
 30'
 40'
 Other

Type of Pole:

Aluminum
 Steel
 Galvanized Steel
 Fiberglass
 Bolton Hill
 Otterbein ✓
 Homeland
 Wooden
 Other

Fixture Type:

Cobra Head
 PMA
 Otterbein ✓
 Homeland
 Bolton Hill
 Victorian Acorn
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide
 LED ✓
 Other

Wattage:

100
 150 ✓
 175
 200
 250
 400
 1000

Arm:

6'
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing

Pedestal Base:

Yes
 No ✓

Base Condition:

Bolts
 Wires
 Conduit

Good


✓

Bad:

Base Type:

Metal ✓
 Concrete

Date: 8/28/2026 Inspector's Signature: T. Blackman



Otterbein
Otterbein fixture