

Inspections Damaged Pole Report

Service Request 26-00812479 for Gateway Prime St
 Location on Service Request: 720 ALICE ANNA
 Grid : 4010140 UIC: 6287

Descriptive Location and Comments:

Street: Alice ANNA St
 Side of Street: N/S E/S ✓ S/S W/S
 Pole location: 1st 2nd 3rd 4th ✓ 5th 6th Other
 Direction : N/O E/O S/O ✓ W/O
 Street or Landmark: Fleet St

Condition of Pole:

Deteriorated
 Missing
 Damaged
 Arm/Fixture Missing
 Other

Pole Size :

11'6" ✓
 12' ✓
 25'
 30'
 40'
 Other

Type of Pole:

Aluminum
 Steel
 Galvanized Steel
 Fiberglass
 Bolton Hill
 Otterbein ✓
 Homeland
 Wooden
 Other

Fixture Type:

Cobra Head
 PMA
 Otterbein ✓
 Homeland
 Bolton Hill
 Victorian Acorn
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide ✓
 LED ✓
 Other

Wattage:

100
 150 ✓
 175
 200
 250
 400
 1000

Arm:

6'
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing

Pedestal Base:

Yes ✓
 No

Base Condition:

Bolts
 Wires
 Conduit

Good


✓
✓

Bad:

Base Type:

Metal ✓
 Concrete

Date: 9/1/2026 Inspector's Signature: T. Blackman



Otterbein
Otterbein Postcard