

Inspections Damaged Pole Report

Service Request 26-00823071 for Gateway Primary 211 FALLSWAY
 Location on Service Request: 4010110 LLC: 7005

Descriptive Location and Comments:

Street: GAY ST
 Side of Street: N/S ✓ E/S ✓ S/S ✓ W/S ✓
 Pole location: 1" ✓ 2" ✓ 3" ✓ 4" ✓ 5" ✓ 6" ✓ Other ✓
 Direction : N/O ✓ E/O ✓ S/O ✓ W/O ✓
 Street or Landmark: FALLSWAY

Condition of Pole:

Deteriorated ✓
 Missing ✓
 Damaged ✓
 Arm/Fixture Missing ✓
 Other ✓

Pole Size :

11'6" ✓
 12' ✓
 25' ✓
 30' ✓
 40' ✓
 Other ✓

Type of Pole:

Aluminum ✓
 Steel ✓
 Galvanized Steel ✓
 Fiberglass ✓
 Bolton Mill ✓
 Otterbein ✓
 Homeland ✓
 Wooden ✓
 Other ✓

NEEDS
New
Pedestal
BASE

Fixture Type:

Cobra Head ✓
 PMA ✓
 Otterbein ✓
 Homeland ✓
 Bolton Mill ✓
 Victorian Acorn ✓
 Other ✓

Lamp Type:

HPS Vapor ✓
 Mercury Vapor ✓
 Metal Halide ✓
 LED ✓
 Other ✓

Wattage:

100 ✓
 150 ✓
 175 ✓
 200 ✓
 250 ✓
 400 ✓
 1000 ✓

Arm:

6' ✓
 10' ✓
 15' ✓
 20' ✓
 Other ✓

Arm Condition:

Damaged ✓
 Missing ✓

Pedestal Base:

Yes ✓
 No ✓

Base Condition:

Bolts ✓
 Wires ✓
 Conduit ✓

Good

✓
✓
✓


Bad:

✓
✓
✓

Base Type:

Metal ✓
 Concrete ✓

Date: 9/11/2026 Inspector's Signature: T. Blackman



30 Foot Aluminum
pole
Cobra Head
LED