

Inspections Damaged Pole Report

Service Request 26-00818719 Sector E. Madison St & E. Monument St Gate 7384 Primary 7384
 Location on Service Request: E. Madison St & E. Monument St
 Grid : 2010330 LLC: 7384

Descriptive Location and Comments:

Street: Highland Ave
 Side of Street: N/S E/S ✓ S/S W/S
 Pole location: 1" ✓ 2" 3" 4" 5" 6" Other
 Direction : N/O E/O S/O ✓ W/O
 Street or Landmark: Monument St

Condition of Pole:

Deteriorated
 Missing ✓
 Damaged
 Arm/Fixture Missing
 Other

Pole Size :

11'6"
 12'
 25'
 30' ✓
 45'

Type of Pole:

Aluminum ✓
 Steel
 Galvanized Steel
 Fiberglass
 Bolton MH
 Otterbein
 Homeland
 Wooden
 Other

work order # 21164157

Fixture Type:

Cobra Head ✓
 PMA
 Otterbein
 Homeland
 Bolton MH
 Victorian Acorn
 Other

Lamp Type:

HPS Vapor
 Mercury Vapor
 Metal Halide ✓
 LED ✓
 Other

Wattage:

100
 150
 175
 200
 250
 400 ✓
 1000

Arm

6' ✓
 10'
 15'
 20'
 Other

Arm Condition:

Damaged
 Missing ✓

Pedestal Base:

Yes ✓
 No

Base Condition:

Good ✓
 Bad
 Bolts ✓
 Wires
 Conduit

Base Type:

Alural
 Concrete ✓

Date: 9/11/2026 Inspector's Signature: T. Blackman