

Inspections: Damaged Pole Report

Service Request: 26-00832833 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 813 No Washington

Grid : 2010230 LLC: 7605

Descriptive Location and Comments:

Street: Washington

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Madison St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other ☒

Otterbein _____

Homeland _____

Wooden _____

Other Clapper Mill ☒

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED _____

250 _____

20' _____

Bolton Hill _____

Other _____

400 ☒

Other _____

Victorian Acorn _____

1000 _____

Other Clapper Mill Fixture ☒

Other _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes

No ☒

Bolts

Wires

Conduit

☒
☒
☒


Metal

Concrete ☒

Date: 9-3-26

Inspector's Signature

Dyann Blackman



Clapper MP11
Clapper MP11 Fixture