

Inspections: Damaged Pole Report

Service Request: 26-00850535 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2300 Cyburn Ave

Grid : 1050 340 UC: 7112

Descriptive Location and Comments:

Street: Cyburn Ave

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th ☒ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: W. Northern Pkwy

Condition of Pole:

Deteriorated _____

Missing _____

Damaged _____

Arm/Fixture Missing ☒

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Arm + Fixture only

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing ☒

Pedestal Base:

Yes ☒
No _____


Base Condition:

Good ☒
Bad: _____
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete _____

Date: 9/8/2026 Inspector's Signature: G. Crowder 8512



25th JULY

Service Request Summary Report
26-00850535

Printed Date: Sep 8, 2026 - 3:50:41 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00850535
Priority: Standard
Status: Pending
Status Date: Sep 08, 2026 3:50:37 PM
Created Date: Sep 08, 2026 3:45:00 PM
Overdue on: Nov 10, 2026 2:45:00 PM
Closed on:

Location: 2300 BLK CYLBURN AVE, Baltimore City,
21209

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		9/8/2026 3:45 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1050340
Assign inspector	LLC / POLE #	7112
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	Arm and fixture only
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created for missing Gregory Crowder 6ft Arm with cobra head LED light fixture only	Gregory Crowder	9/8/2026 3:50 PM	Private
Assign inspector : missing pole report created for missing Gregory Crowder	Gregory Crowder	9/8/2026 3:50 PM	Public