

Inspections: Damaged Pole Report

Service Request: 26-00843585 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 6100 Fenwick Ave

Grid : 2050220 LLC: 7158

Descriptive Location and Comments:

Street: Fenwick Ave

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Northern PKWY

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☒

11'6" _____

Aluminum _____

Missing ☒

12' _____

Steel ☒

Damaged _____

25' ☒

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

**NEEDS
NEW
BASE**

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing ☒

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

250 ☒

20' _____

Bolton Hill _____

Other _____

400 _____

Other _____

Victorian Acorn _____

1000 _____

Other _____

Other _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ☒
No ☒

Bolts
Wires
Conduit

☒
☒
☒

Metal ☒
Concrete _____

Date: 9-9-26 Inspector's Signature: Dyann Blachman

