

Inspections: Damaged Pole Report

Service Request: 26-00846954 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1703 ALICEANNA St

Grid : 4010230 LLC: 7204

Descriptive Location and Comments:

Street: ALICEANNA St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____


Street or Landmark: S. Broadway

<u>Condition of Pole:</u>	<u>Pole Size :</u>	<u>Type of Pole:</u>
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' ☒	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

<u>Fixture Type:</u>	<u>Lamp Type:</u>	<u>Wattage:</u>	<u>Arm:</u>	<u>Arm Condition:</u>
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing ☒
Otterbein _____	Metal Halide ☒	175 _____	15' _____	
Homeland _____	LED ☒	250 ☒	20' _____	
Bolton Hill _____	Other _____	400 _____	Other _____	
Victorian Acorn _____		1000 _____		
Other _____		Other _____		

<u>Pedestal Base:</u>	<u>Base Condition:</u>	<u>Good</u>	<u>Bad:</u>	<u>Base Type:</u>
Yes _____	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 9-9-26 Inspector's Signature: [Signature]



25 Foot
Aluminum
pole
Cobra Head
LED