

already in system
WO#
21164222

Inspections: Damaged Pole Report

Service Request: 26-'60 858940 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: Wabash Ave w/ Patterson Ave
Grid: 1040510 LLC: 2070

Descriptive Location and Comments:

Street: Patterson Park Ave
Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction: N/O ☒ E/O _____ S/O _____ W/O _____
Street or Landmark: Wabash Ave


Condition of Pole:	Pole Size:	Type of Pole:
Deteriorated ☒	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
<u>Arm/Fixture Missing</u> ☒	30' ☒	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Arm + Fixture missing only

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete ☒
	Conduit ☒	☒	_____	

Date: 9/10/2026 Inspector's Signature: G. Crowder 8512



Airt Fictio only

25 ft CA UED