

Inspections: Damaged Pole Report

Service Request: 26-0086299 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2826 Rosalind Ave
 Grid : 1040 330 LLC: 7254

Descriptive Location and Comments:

Street: Rosalind Ave
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th ☒ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O _____
 Street or Landmark: Canal Ave

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' ☒	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ☒	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 9/11/2026 Inspector's Signature: G. Crowder 8512

