

Inspections: Damaged Pole Report

Service Request: 26-00881892 :ctor: _____ Gateway: _____ Primary: _____

Location on Service Request: 1105 S. Charles St

Grid : 4020110 LLC: 7535

Descriptive Location and Comments:

Street: CROSS St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd _____ 3rd ☒ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: S. Charles St

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn ☒

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

250 _____

400 _____

1000 _____

Other _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition:

Good _____

Bad: _____

Base Type:

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 9-17-26 Inspector's Signature: Dyann Blackman

