

# Inspections: Damaged Pole Report

Service Request: 26-00890455 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 700 W. FRANKLIN ST

Grid : 3010110 LLC: 7175

## Descriptive Location and Comments:

Street: W. FRANKLIN ST

Side of Street: N/S ☒ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_

Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> ☒ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O \_\_\_\_\_ W/O ☒

Street or Landmark: N. FREMONT AVE

### Condition of Pole:

### Pole Size :

### Type of Pole:

Deteriorated \_\_\_\_\_

11'6" \_\_\_\_\_

Aluminum ☒

Missing ☒

12' \_\_\_\_\_

Steel \_\_\_\_\_

Damaged \_\_\_\_\_

25' ☒

Galvanized Steel \_\_\_\_\_

Arm/Fixture Missing \_\_\_\_\_

30' \_\_\_\_\_

Fiberglass \_\_\_\_\_

Other \_\_\_\_\_

40' \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Other \_\_\_\_\_

Otterbein \_\_\_\_\_

Homeland \_\_\_\_\_

Wooden \_\_\_\_\_

Other \_\_\_\_\_

wo# 2120 3717

### Fixture Type:

### Lamp Type:

### Wattage:

### Arm:

### Arm Condition:

Cobra Head ☒

HPS Vapor \_\_\_\_\_

100 \_\_\_\_\_

6' ☒

Damaged \_\_\_\_\_

PMA \_\_\_\_\_

Mercury Vapor \_\_\_\_\_

150 \_\_\_\_\_

10' \_\_\_\_\_

Missing \_\_\_\_\_

Otterbein \_\_\_\_\_

Metal Halide \_\_\_\_\_

175 \_\_\_\_\_

15' \_\_\_\_\_

Homeland \_\_\_\_\_

LED ☒

200 \_\_\_\_\_

20' \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Other \_\_\_\_\_

250 \_\_\_\_\_

Other \_\_\_\_\_

Victorian Acorn \_\_\_\_\_

400 ☒

Other \_\_\_\_\_

1000 \_\_\_\_\_

### Pedestal Base:

### Base Condition:

Good

Bad:

### Base Type:

Yes ☒  
No \_\_\_\_\_

Bolts  
Wires  
Conduit

☒  
☒  
☒

Metal ☒  
Concrete \_\_\_\_\_

Date: 9-19-20 Inspector's Signature [Signature]

