

Inspections: Damaged Pole Report

Service Request: 26-00890809 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 241 So Exeter St
 Grid : 4010140 LLC: 7228

Descriptive Location and Comments:

Street: So Exeter St
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O ☒ E/O _____ S/O _____ W/O _____
 Street or Landmark: Fawn St

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 250 ☒
 400 _____
 1000 _____
 Other _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing ☒

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts _____
 Wires _____
 Conduit _____

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 9-22-26 Inspector's Signature: [Signature]



25 Foot pole
counter top
LED