

Inspections: Damaged Pole Report

Service Request: 20-00905934 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 6700 Popping PKWY
 Grid : 2060310 LLC: 7180

Descriptive Location and Comments:

Street: POPPING PKWY
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ✓
 Pole location: 1st _____ 2nd _____ 3rd _____ 4th 4 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ✓ W/O _____
 Street or Landmark: CROZIER DR

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ✓

Missing ✓

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' ✓

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

NO # 20363099

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ✓

HPS Vapor _____

100 _____

6' ✓

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ✓

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 ✓

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes

No ✓

Bolts

Wires

Conduit ✓


Metal

Concrete ✓

Date: 9-24-20

Inspector's Signature

[Signature]



STREETLIGHT DETAILS

We are aware of a problem on this streetlight.

Status:

Pending Repair

Pole Number:

20503107180

Order Number:

20363699

Date Reported:

7/27/2025 9:27 PM EDT

Estimated Time of Repair:

08/22/2025

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Subscribe to Incident Alerts

Enter your email. For multiple emails, separate with semicolon (;).