

Inspections: Damaged Pole Report

Service Request: 26-00936386 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3010 Evergreen Ave

Grid : 2040320 LLC: 7170

Descriptive Location and Comments:

Street: Evergreen Ave

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: Richard Ave

Condition of Pole:

Deteriorated ☐

Missing ☒

Damaged ☐

Arm/Fixture Missing ☐

Other ☐

Pole Size :

11'6" ☒

12' ☐

25' ☐

30' ☐

40' ☐

Other ☐

Type of Pole:

Aluminum ☐

Steel ☒

Galvanized Steel ☐

Fiberglass ☐

Bolton Hill ☐

Otterbein ☐

Homeland ☐

Wooden ☐

Other ☐

Fixture Type:

Cobra Head ☐

PMA ☒

Otterbein ☐

Homeland ☐

Bolton Hill ☐

Victorian Acorn ☐

Other ☐

Lamp Type:

HPS Vapor ☐

Mercury Vapor ☐

Metal Halide ☒

LED ☐

Other ☐

Wattage:

100 ☐

150 ☒

175 ☐

250 ☐

400 ☐

1000 ☐

Other ☐

Arm:

6' ☐

10' ☐

15' ☐

20' ☐

Other ☐

Arm Condition:

Damaged ☐

Missing ☐

Pedestal Base:

Yes ☐
No ☒

Base Condition:

Bolts ☒
Wires ☒
Conduit ☒

Good

☒
☒
☒

Bad:

☐
☐
☐


Base Type:

Metal ☒
Concrete ☐

Date: 10-5-26 Inspector's Signature: Dyann Blachman

NEEDS
New
Base

Work order #
20786368



Steel
PMA
HPS