

Inspections Damaged Pole Report

Service Request 26-00937823 ctor Gateway Primary
 Location on Service Request. 600 Guilford Ave
 Grid : 4010110 LLC: 7163

Descriptive Location and Comments:


Street: Guilford Ave
 Side of Street: N/S E/S S/S W/S ✓
 Pole location: 1st ✓ 2nd 3rd 4th 5th 6th Other
 Direction : N/O E/O S/O ✓ W/O
 Street or Landmark: E. Monument St

<u>Condition of Pole:</u>	<u>Pole Size :</u>	<u>Type of Pole:</u>
Deteriorated <u> </u>	11'6" <u> </u>	Aluminum <u>✓</u>
Missing <u>✓</u>	12' <u> </u>	Steel <u> </u>
Damaged <u> </u>	25' <u> </u>	Galvanized Steel <u> </u>
Arm/Fixture Missing <u> </u>	30' <u>✓</u>	Fiberglass <u> </u>
Other <u> </u>	40' <u> </u>	Bolton Hill <u> </u>
	Other <u> </u>	Otterbein <u> </u>
		Homeland <u> </u>
		Wooden <u> </u>
		Other <u> </u>

<u>Fixture Type:</u>	<u>Lamp Type:</u>	<u>Wattage:</u>	<u>Arm:</u>	<u>Arm Condition:</u>
Cobra Head <u>✓</u>	HPS Vapor <u> </u>	100 <u> </u>	6' <u>✓</u>	Damaged <u> </u>
PMA <u> </u>	Mercury Vapor <u> </u>	150 <u> </u>	10' <u> </u>	Missing <u>✓</u>
Otterbein <u> </u>	Metal Halide <u> </u>	175 <u> </u>	15' <u> </u>	
Homeland <u> </u>	LED <u>✓</u>	200 <u> </u>	20' <u> </u>	
Bolton Hill <u> </u>	Other <u> </u>	250 <u> </u>	Other <u> </u>	
Victorian Acorn <u> </u>		400 <u>✓</u>		
Other <u> </u>		1000 <u> </u>		

<u>Pedestal Base:</u>	<u>Base Condition:</u>	<u>Good</u>	<u>Bad:</u>	<u>Base Type:</u>
Yes <u>✓</u>	Bolts <u>✓</u>	<u> </u>	<u> </u>	Metal <u> </u>
No <u> </u>	Wires <u>✓</u>	<u> </u>	<u> </u>	Concrete <u>✓</u>
	Conduit <u> </u>	<u> </u>	<u> </u>	

Date: 10/6/2026 Inspector's Signature: T. Blackman



30 Foot
Aluminum
pole
cobra mini
LED