

Inspections: Damaged Pole Report

Service Request: 26-00937387 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1403 Lochner Rd

Grid : 2050230 LLC: 7127

Descriptive Location and Comments:

Street: Lochner Rd

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Woodmont Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" ☒

Aluminum _____

Missing ☒

12' _____

Steel ☒

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

**NEEDS
New
Base**

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 ☒

6' _____

Damaged _____

PMA ☒

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

250 _____

20' _____

Bolton Hill _____

Other _____

400 _____

Other _____

Victorian Acorn _____

1000 _____

Other _____

Other _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes ☒
No ☒

Bolts
Wires
Conduit

☒
☒
☒

Metal ☒
Concrete ☒

Date: 10-6-26 Inspector's Signature: [Signature]



PMA
LED