

Inspections: Damaged Pole Report

Service Request 26-00944060 Gateway Primary

Location on Service Request: 5200 EASTBURY AVE

Grid : 2020410 LLC: 7236

Descriptive Location and Comments:

Street: EASTBURY AVE

Side of Street: N/S ✓ E/S ✓ S/S ✓ W/S ✓

Pole location: 1" ✓ 2" ✓ 3" ✓ 4" ✓ 5" ✓ 6" ✓ Other ✓

Direction : N/O ✓ E/O ✓ S/O ✓ W/O ✓

Street or Landmark: SONCLIFF AVE

Condition of Pole:

Deteriorated ✓

Missing ✓

Damaged ✓

Arm/Fixture Missing ✓

Other ✓

Pole Size :

11'6" ✓

12' ✓

25' ✓

30' ✓

40' ✓

Other ✓

Type of Pole:

Aluminum ✓

Steel ✓

Galvanized Steel ✓

Fiberglass ✓

Bolton Hill ✓

Otterbein ✓

Homeland ✓

Wooden ✓

Other ✓

NEEDS
NEW
BASE

WORK ORDER #
20260250

Fixture Type:

Cobra Head ✓

PMA ✓

Otterbein ✓

Homeland ✓

Bolton Hill ✓

Victorian Acorn ✓

Other ✓

Lamp Type:

HPS Vapor ✓

Mercury Vapor ✓

Metal Halide ✓

LED ✓

Other ✓

Wattage:

100 ✓

150 ✓

175 ✓

200 ✓

250 ✓

400 ✓

1000 ✓

Arm:

6' ✓

10' ✓

15' ✓

20' ✓

Other ✓

Arm Condition:

Damaged ✓

Missing ✓

Pedestal Base:

Yes ✓

No ✓

Base Condition:

Good ✓

Bad ✓


Base Type: ✓

Base Type:

Metal ✓

Concrete ✓

Date: 10/8/2026 Inspector's Signature: T. Blackman



25 Foot
Aluminum
pole
Cobon Thread
LED