

Inspections: Damaged Pole Report

Service Request 210-00952988 Sector Dillon St & S. Fagley St Gateway Primary
 Location on Service Request: Dillon St & S. Fagley St
 Grid: 4020320 LLC: 7009

Descriptive Location and Comments:

Street: Dillon St
 Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐
 Pole location: 1" ☒ 2nd ☐ 3rd ☐ 4th ☐ 5th ☐ 6th ☐ Other ☐
 Direction: N/O ☐ E/O ☒ S/O ☐ W/O ☐
 Street or Landmark: S. Fagley St


<u>Condition of Pole:</u>	<u>Pole Size:</u>	<u>Type of Pole:</u>
Deteriorated ☐	11'6" ☐	Aluminum ☒
Missing ☒	12' ☐	Steel ☐
Damaged ☐	25' ☒	Galvanized Steel ☐
Arm/Fixture Missing ☐	30' ☐	Fiberglass ☐
Other ☐	40' ☐	Bolton Hill ☐
	Other ☐	Otterbein ☐
		Homeland ☐
		Wooden ☐
		Other ☐

**NEEDS
NEW
BASE**

<u>Fixture Type:</u>	<u>Lamp Type:</u>	<u>Wattage:</u>	<u>Arm:</u>	<u>Arm Condition:</u>
Cobra Head ☒	HPS Vapor ☐	100 ☐	6' ☒	Damaged ☐
PMA ☐	Mercury Vapor ☐	150 ☐	10' ☐	Missing ☒
Otterbein ☐	Metal Halide ☐	175 ☐	15' ☐	
Homeland ☐	LED ☒	200 ☐	20' ☐	
Bolton Hill ☐	Other ☐	250 ☒	Other ☐	
Viktorian Acorn ☐		400 ☐		
Other ☐		1000 ☐		

<u>Pedestal Base:</u>	<u>Base Condition:</u>	<u>Good</u>	<u>Bad:</u>	<u>Base Type:</u>
Yes ☒	Bolts ☒	☒	☐	Metal ☒
No ☐	Wires ☒	☐	☐	Concrete ☐
	Conduit ☒	☒	☐	

Date: 10/13/2026 Inspector's Signature: T. Blackman



25 Foot
Aluminum
pole
cobra head
LED