

Inspections Damaged Pole Report

Service Request 26-00959530 Gateway Primary
 Location on Service Request: Cardenas Ave & Mayfield Ave
 Grid : 2020310 LLC: 7165

Descriptive Location and Comments:

Street: Cardenas Ave
 Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐
 Pole location: 1" ☒ 2nd ☐ 3rd ☐ 4th ☐ 5th ☐ 6th ☐ Other ☐
 Direction : N/O ☐ E/O ☒ S/O ☐ W/O ☐
 Street or Landmark: Mayfield Ave


Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated ☐	11'6" ☒	Aluminum ☒
Missing ☒	12' ☐	Steel ☐
Damaged ☐	25' ☐	Galvanized Steel ☐
Arm/Fixture Missing ☐	30' ☐	Fiberglass ☐
Other ☐	40' ☐	Bolton Hill ☐
	Other ☐	Otterbein ☐
		Homeland ☐
		Wooden ☐
		Other ☐

Work Order #
 21247195

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☐	HPS Vapor ☐	100 ☐	6' ☐	Damaged ☐
PMA ☒	Mercury Vapor ☐	150 ☒	10' ☐	Missing ☐
Otterbein ☐	Metal Halide ☒	175 ☐	15' ☐	
Homeland ☐	LED ☒	200 ☐	20' ☐	
Bolton Hill ☐	Other ☐	250 ☐	Other ☐	
Victorian Acorn ☐		400 ☐		
Other ☐		1000 ☐		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ☒	Bolts ☒	☒	☐	Metal ☒
No ☐	Wires ☒	☐	☐	Concrete ☐
	Conduit ☒	☐	☐	

Date: 10/14/2026 Inspector's Signature: T. Blackman



PMA
CAYLED