

Inspections: Damaged Pole Report

Service Request 26-00962905 Sector _____ Gateway _____ Primary _____

Location on Service Request: Hollen Rd & Ramblewood Rd

Grid : 2050240 LLC: 7197

Descriptive Location and Comments:

Street: Ramblewood Rd

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1" ☒ 2" _____ 3" _____ 4" _____ 5" _____ 6" _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Hollen Rd

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Work Order #
21247392

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Good _____


Bad: _____

Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete _____

Date: 10/14/2026 Inspector's Signature: T. Blackmer



PMA
HPS