

Inspections Damaged Pole Report

Service Request 26-00957836 Sector Gateway Primary

Location on Service Request: 5100 Eastern Ave

Grid : 4010430 LLC: 7279

Descriptive Location and Comments:

Street: Eastern Ave

Side of Street: N/S ☒ E/S ☐ S/S ☐ W/S ☐

Pole location: 1" ☒ 2" ☐ 3" ☐ 4" ☐ 5" ☐ 6" ☐ Other ☐

Direction : N/O ☐ E/O ☐ S/O ☐ W/O ☒

Street or Landmark: Cassell dr

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged ☐

Arm/Fixture Missing ☐

Other ☐

Pole Size :

11'6" ☐

12' ☐

25' ☐

30' ☒

40' ☐

Other ☐

Type of Pole:

Aluminum ☒

Steel ☐

Galvanized Steel ☐

Fiberglass ☐

Bolton Hill ☐

Otterbein ☐

Homeland ☐

Wooden ☐

Other ☐

Work order #
20893507

Fixture Type:

Cobra Head ☒

PMA ☐

Otterbein ☐

Homeland ☐

Bolton Hill ☐

Victorian Acorn ☐

Other ☐

Lamp Type:

HPS Vapor ☐

Mercury Vapor ☐

Metal Halide ☒

LED ☒

Other ☐

Wattage:

100 ☐

150 ☐

175 ☐

200 ☐

250 ☐

400 ☒

1000 ☐

Arm:

6' ☒

10' ☐

15' ☐

20' ☐

Other ☐

Arm Condition:

Damaged ☐

Missing ☒

Pedestal Base:

Yes ☒

No ☐

Base Condition:

Good ☒

Bad: ☐

Base Type:

Bolts ☒


Wires ☒

Conduit ☒

Metal ☐

Concrete ☒

Date: 10/14/2026 Inspector's Signature: T. Blackman



30 Foot
Aluminum
pole
cobrahead
LED