

Inspections: Damaged Pole Report

Service Request: 26-00997300 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3724 FLEETWOOD AVE

Grid : 2050530 LLC: 7152

Descriptive Location and Comments:

Street: FLEETWOOD AVE

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ✓ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ✓ S/O _____ W/O _____

Street or Landmark: WALTHER AVE

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ✓

Missing ✓

12' _____

Steel _____

Damaged _____

25' ✓

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

NEEDS NEW BASE

NO# 21264375

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ✓

HPS Vapor _____

100 _____

6' ✓

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ✓

200 ✓

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ✓
No _____

Bolts
Wires
Conduit

_____ ✓ _____

_____ ✓ _____

Metal ✓
Concrete _____

Date: 10.27.26 Inspector's Signature [Signature]

Google



Keynotes & abstracts Map data ©2015

Subscribe to Incident Alerts