


## Inspection Report (Excavator)

### General Info

Year	2007
Make	Caterpillar
Model	320C
Serial Number	CAT0320CVPAC01289
Hour Meter Reading	7763
Previous Application (e.g., earth moving, mining, demolition, etc)	general construction

### Dimensions

Measurement Guide	
A. Length (ft and inches)	28.7
B. Width (ft and inches)	9.2
C. Height (ft and inches)	9.9
Operational Weight (lbs)	48502

### Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Size (in inches)	48
Blade	No
Additional Attachment(s)	No
Hydraulic Coupler	Yes
Auxiliary Hydraulics	Yes
Hydraulic Thumb	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

### Exterior Walkaround Photos

## Inspection Report (Excavator)

### Exterior 360 Walkaround

<p><b>Instructions</b></p>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul>
<p><b>Exterior Walkaround Photos</b></p>	
	

Inspection Report (Excavator)



### Inspection Report (Excavator)



### Inspection Report (Excavator)



Inspection Report (Excavator)



### Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



### Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)




Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



**Inspection Report (Excavator)**



**General Appearance Inspection Points**

**General Appearance**

### Inspection Report (Excavator)

Front	3 - Normal Wear & Tear
Front Condition	No visible damage
Front Photos	
	
	

**Inspection Report (Excavator)**

	
	
<p><b>Rear</b></p>	<p>4 - Like New, Recently Replaced</p>
<p><b>Rear Condition</b></p>	<p>No visible damage</p>
<p><b>Rear Photos</b></p>	

**Inspection Report (Excavator)**

	
	
<p><b>Left</b></p>	<p>3 - Normal Wear &amp; Tear</p>
<p><b>Left Condition</b></p>	<p>No visible damage</p>
<p><b>Left Photos</b></p>	

Inspection Report (Excavator)



**Inspection Report (Excavator)**

	
	
<p><b>Right</b></p>	<p>4 - Like New, Recently Replaced</p>
<p><b>Right Condition</b></p>	<p>No visible damage</p>
<p><b>Right Photos</b></p>	

### Inspection Report (Excavator)

		
		
Upper	3 - Normal Wear & Tear	
Upper Condition	No visible damage, Other (see comments)	
Comments	a few seps a bit bent but okay	
Upper Photos		

Inspection Report (Excavator)



**Inspection Report (Excavator)**

	
<p><b>Body Panels (Any Rust Damage?)</b></p>	<p>3 - Normal Wear &amp; Tear</p>
<p><b>Body Panel Condition</b></p>	<p>No visible damage, good paint condition and panel fitment</p>
<p><b>Body Panels Photos</b></p>	

**Inspection Report (Excavator)**

	
	
<p><b>Doors / Canopy Latches</b></p>	<p>4 - Like New, Recently Replaced</p>
<p><b>Doors / Canopy Latches Condition</b></p>	<p>No visible damage</p>
<p><b>Doors / Canopy Latches Photos</b></p>	

### Inspection Report (Excavator)

	
	
	
<b>Glass Condition</b>	3 - Normal Wear & Tear
<b>Glass Condition Notes</b>	Other (see comments)
<b>Comments</b>	front cab window slider needs repair to slide up properly

### Inspection Report (Excavator)

<p>Glass Condition Photos</p>	
	
	

### Inspection Report (Excavator)

	
	
	
<b>Mirrors</b>	0
<b>Lighting System</b>	3 - Normal Wear & Tear
<b>Lighting System Condition</b>	No visible damage, lighting system is operational

## Inspection Report (Excavator)

Lighting System Photos		
		
		


### Control Station Inspection Points

Control Station

### Inspection Report (Excavator)

<p>Serial Number Plate Photo</p>	
<p>Operator Cabin Overall</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Operator Cabin Overall Condition</p>	<p>Good cabin appearance, solid floors, panels, and ceiling</p>
<p>Operator Cabin Photos</p>	
	

Inspection Report (Excavator)



Inspection Report (Excavator)



### Inspection Report (Excavator)

	
	
	
<b>Operator's Seat &amp; Arm Rests</b>	3 - Normal Wear & Tear
<b>Operator's Seat &amp; Arm Rests Condition</b>	Seat(s) have minor surface staining or small tears

### Inspection Report (Excavator)

Operator's Seat & Arm Rests  
Photos



## Inspection Report (Excavator)

	
<b>Seat Belt</b>	3 - Normal Wear & Tear
<b>Seat Belt Condition</b>	Seat belt secures properly. Belt is intact and in good condition
<b>Seat Belt Photos</b>	
<b>Cabin Lights</b>	3 - Normal Wear & Tear
<b>Cabin Lights Condition</b>	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
<b>Cabin Lights Photos</b>	
<b>Safety Lock Out / Stop</b>	4 - Like New, Recently Replaced
<b>Safety Lock Out / Stop Condition</b>	Safety lock out device is present, in good condition, and functional

## Inspection Report (Excavator)

<p>Safety Lock Out / Stop Photos</p>	
	
<p><b>Controls &amp; Switches</b></p>	<p>4 - Like New, Recently Replaced</p>
<p><b>Controls &amp; Switches Condition</b></p>	<p>All switches are installed and functional</p>

### Inspection Report (Excavator)

Controls & Switches Photos



Inspection Report (Excavator)



## Inspection Report (Excavator)

	
<b>Hour Meter Activity</b>	4 - Like New, Recently Replaced
<b>Hour Meter Condition</b>	Hour meter is functional and in good condition
<b>Hour Meter Activity Photos</b>	
<b>Other Gauge Activity</b>	4 - Like New, Recently Replaced
<b>Other Gauge Condition</b>	All cockpit gauges are functional and in good condition
<b>Heater &amp; A/C</b>	3 - Normal Wear & Tear
<b>Heater &amp; A/C Condition</b>	Other (see comments)
<b>Comments</b>	heater ok, ac working but not at full potential
<b>Fans / Vents</b>	3 - Normal Wear & Tear
<b>Fans / Vents Condition</b>	Fan vents are functional, in good condition, and move through a full adjustable range of motion

### Inspection Report (Excavator)

<p>Fans / Vents Photos</p>		
		
		

## Inspection Report (Excavator)



Travel Alarm	4 - Like New, Recently Replaced
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	4 - Like New, Recently Replaced
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

## Engine Inspection Points

### Engine


Engine Type (Make, Model, Cylinders, Hp)	3066
Engine Serial Number	MAE14981
Engine Fuel Type	Diesel

## Inspection Report (Excavator)

Engine Photos



Inspection Report (Excavator)



## Inspection Report (Excavator)

		
		
<b>Blow-by (Visual Observation Check)</b>	No	
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No	
<b>Unusual Noise Notes</b>	No unusual noises heard	
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No	
<b>Engine Smoke Notes</b>	No engine smoke issues observed	
<b>Engine Exhaust Color</b>	Clear	
<b>Battery</b>	3 - Normal Wear & Tear	
<b>Battery Condition</b>	Clean & dry appearance, tight connections, Other (see comments)	
<b>Comments</b>	machine started right up after sitting for a week	
<b>Radiator</b>	3 - Normal Wear & Tear	
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks	

## Inspection Report (Excavator)

<b>Radiator Photos</b>	
	
<b>Belts</b>	3 - Normal Wear & Tear
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension
<b>Belt Photos</b>	
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks

## Inspection Report (Excavator)

Hose Photos	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Appropriate oil level, Clean oil appearance, no signs of cross contamination, Signs of water, coolant, or fuel contamination observed
Comments	fluids need to be topped off
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	N/A
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry, Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Just one seepage leak (normal) top engine breather

## Drivetrain Inspection Points

## Inspection Report (Excavator)

### Drivetrain

Transmission	0
Clutch	0
Shift Lever	0
Foot Brake	0
Inching Brake	0
Parking Brake	0


### Chassis Inspection Points

Instructions	<p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced  3 = Normal Wear &amp; Tear  2 = Above Average Wear  1 = Service Required</p>
Boom Condition	4 - Like New, Recently Replaced
Boom Photos	

Inspection Report (Excavator)




Inspection Report (Excavator)



Inspection Report (Excavator)



### Inspection Report (Excavator)

		
<b>Stick Condition</b>	4 - Like New, Recently Replaced	
<b>Stick Photos</b>		
		

Inspection Report (Excavator)



**Inspection Report (Excavator)**

	
<p><b>Boom Base Pin &amp; Bushings</b></p>	<p>3 - Normal Wear &amp; Tear</p>
<p><b>Boom Base Pin &amp; Bushings Photos</b></p>	
	

**Inspection Report (Excavator)**

		
		
<p><b>Boom to Stick Pin &amp; Bushings</b></p>	<p>3 - Normal Wear &amp; Tear</p>	
<p><b>Boom to Stick Pin &amp; Bushings Photos</b></p>		

**Inspection Report (Excavator)**

		
<p>Stick to Bucket Pin &amp; Bushings</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Stick to Bucket Pin &amp; Bushings Photos</p>		
		

**Inspection Report (Excavator)**

	
	
<p><b>Turntable Bearing</b></p>	<p>3 - Normal Wear &amp; Tear</p>
<p><b>Turntable Bearing Photos</b></p>	

**Inspection Report (Excavator)**

		
		
<p><b>Bottom Covers</b></p>	<p>3 - Normal Wear &amp; Tear</p>	
<p><b>Bottom Covers Photos</b></p>		

### Inspection Report (Excavator)



## Inspection Report (Excavator)

		
Overall Chassis	3 - Normal Wear & Tear	

### Undercarriage Inspection Points

Instructions	<p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced          3 = Normal Wear &amp; Tear          2 = Above Average Wear          1 = Service Required</p>	
Undercarriage Overall Condition	3 - Normal Wear & Tear	
Comments	1 r/s track pad bent rest is okay	
Undercarriage Overall Photos		

Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Inspection Report (Excavator)



Pin & Bushings

3 - Normal Wear & Tear

### Inspection Report (Excavator)

<p>Pin &amp; Bushings Photos</p>		
<p>Tracks</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Tracks Photos</p>		
		

### Inspection Report (Excavator)

		
		
		
<b>Left Side: Link Bushings / Drive Sprocket / Shoe Condition</b>	3 - Normal Wear & Tear	
<b>Left Side: Upper &amp; Lower Roller / Front Idler Condition</b>	3 - Normal Wear & Tear	
<b>Track Condition: Left Front</b>	50%	
<b>Track Condition: Left Rear</b>	50%	

## Inspection Report (Excavator)

<p><b>Undercarriage Left Side Photo Instructions</b></p>	<p>Take photos of the undercarriage of this piece of equipment.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Roller Frame (left)</li> <li>- Track Tensioner (left)</li> <li>- Track Pads (left)</li> <li>- Grouser Height (left)</li> <li>- Track Links (left)</li> <li>- Track Bushings (left)</li> <li>- Carrier Rollers (left)</li> <li>- Track Rollers (left)</li> <li>- Idler (left)</li> <li>- Sprocket (left)</li> </ul>
<p><b>Undercarriage Left Side Photos</b></p>	
	
	

## Inspection Report (Excavator)

Right Side: Link Bushings / Drive Sprocket / Shoe Condition	3 - Normal Wear & Tear
Right Side: Upper & Lower Roller / Front Idler Condition	3 - Normal Wear & Tear
Track Condition: Right Front	50%
Track Condition: Right Rear	50%
Undercarriage Right Side Photo Instructions	<p>Take photos of the undercarriage of this piece of equipment.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Roller Frame (right)</li> <li>- Track Tensioner (right)</li> <li>- Track Pads (right)</li> <li>- Grouser Height (right)</li> <li>- Track Links (right)</li> <li>- Track Bushings (right)</li> <li>- Carrier Rollers (right)</li> <li>- Track Rollers (right)</li> <li>- Idler (right)</li> <li>- Sprocket (right)</li> </ul>
Undercarriage Right Side Photos	
	

## Inspection Report (Excavator)



### Hydraulics Overall Inspection Points

#### Hydraulics Overall

Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Appearance of Hydraulic Lines / Fittings Photos	
	

### Inspection Report (Excavator)

	
	
	
Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation
External Controls / Levers	0

### Hydraulics Cylinders Inspection Points

Boom Cylinder	Check the boom cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Boom Cylinder: Mounting Pin	3
Boom Cylinder: Oil Leaks	No

## Inspection Report (Excavator)

<p>Boom Cylinder Photos</p>	
	
	
<p><b>Stick Cylinder</b></p>	<p>Check the stick cylinder. Note any wear, pitting, discoloration, etc. Take photos.</p>
<p><b>Stick Cylinder: Mounting Pin</b></p>	<p>3</p>
<p><b>Stick Cylinder: Oil Leaks</b></p>	<p>No</p>
<p><b>Comments</b></p>	<p>possible seepage no major leaks</p>

## Inspection Report (Excavator)

Stick Cylinder Photos	
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Bucket Cylinder: Mounting Pin	3
Bucket Cylinder: Oil Leaks	No
Bucket Cylinder Photos	
Blade	Check the blade. Note any wear, pitting, discoloration, etc. Take photos.
Blade	0

## Bucket Inspection Points

Instructions	<p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced  3 = Normal Wear &amp; Tear  2 = Above Average Wear  1 = Service Required</p>
Bucket Condition	3 - Normal Wear & Tear

### Inspection Report (Excavator)

<p>Bucket Photos</p>		
		
		

**Inspection Report (Excavator)**

	
	
	
<p><b>Bucket Hose &amp; Fittings</b></p>	<p>3 - Normal Wear &amp; Tear</p>

## Inspection Report (Excavator)

<b>Bucket Hose &amp; Fittings Photos</b>	
	
<b>Bucket Cylinder</b>	3 - Normal Wear & Tear

### Additional Attachment Inspection Points

#### Additional Attachment(s)

#### Additional Attachments

<b>Attachment Type</b>	hydraulic thumb
<b>Attachment Make</b>	M & W
<b>Attachment Size / Specs</b>	24"
<b>Attachment Condition</b>	3 - Normal Wear & Tear

## Inspection Report (Excavator)

Attachment Photos	
	

## Functional Test

<b>Instructions</b>	<p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced 3 = Normal Wear &amp; Tear 2 = Above Average Wear 1 = Service Required</p> <p>Things to look for: &lt;Samir to edit&gt;</p>
<b>Forward &amp; Reverse</b>	4 - Like New, Recently Replaced
<b>Swing Table Rotation</b>	4 - Like New, Recently Replaced
<b>Boom Lift / Angle / Tilt</b>	4 - Like New, Recently Replaced
<b>Overall Functional Test Comments</b>	Overall entire machine operating well with no abnormal sounds. All implements work well.
<b>Operating Video</b>	<a href="#">Click to Download</a>

## Overall Assessment

<b>Overall Assessment</b>	
<b>Exterior Rating</b>	3
<b>Interior Rating</b>	3



## Inspection Report (Excavator)

<b>Safety Rating</b>	4
<b>Quality Rating</b>	4
<b>Functionality Rating</b>	4
<b>Overall Rating</b>	4
<b>What's Great About the Machine</b>	Machine is in great condition for 15 years in service. No major repairs required at this time. This excavator is ready to hit the ground running!
<b>What Needs Work</b>	Right side track segment bent (qty.1), valve cover breather needs attention, a/c needs a service, front cab window slide up function not working properly, top off coolant, engine oil and hydraulic. Bucket thumb pins and linkages worn/loose, may need new bushings.
<b>Any Additional Info from the Seller?</b>	No
<b>Inspector's Name</b>	Mario Ramirez
<b>Date/Time</b>	08-04-2022