

## Inspection Report (On-Highway Flatbed Truck)

### General Info

|  |   |
|--|---|
| Year   | 2012  |
| Make   | Kenworth  |
| Model  | T800  |
| Serial Number  | 1XKDDP9X7CJ300183                                 |
| Truck Odometer Reading   | 348200miles 20,887 hours                          |
| Current Inspection / State Cert / DOT                              | Annual Inspection Performed 04/2022 per 49CFR-396 |
| Previous Application (e.g., earth moving, mining, demolition, etc) | Rental Equipment Transportation                   |

### Dimensions

|                           |  |
|---------------------------|--|
| Dimensions                | Please enter in or verify (if pre-populated) the following dimensions. |
| Length (ft and inches)    | 26'  |
| Width (ft and inches)     | 8' 3"  |
| Height (ft and inches)    | 10'7"  |
| Wheelbase (ft and inches) | 15' 4" (184")  |
| GVWR (lbs)                | 52,350   |

### Features and Configuration

|                                     |  |
|-------------------------------------|--|
| Features                            | Enter in and/or verify the following information regarding the features of this equipment. |
| Heat                                | Yes  |
| A/C                                 | Yes  |
| Radio                               | Yes  |
| Backup Camera                       | No   |
| Cruise Control                      | No   |
| PTO                                 | Yes  |
| PTO Details                         | Okay   |
| Engine Break                        | Yes  |
| Differential Lock                   | Yes  |
| OMM (Operator & Maintenance Manual) | Yes  |
| Telematics                          | No   |
| Auxiliary Engine                    | No   |
| Liftgate                            | No   |

### Exterior 360 Walkaround

### Exterior 360 Walkaround

## Inspection Report (On-Highway Flatbed Truck)

|                                   |   |
|-----------------------------------|---|
| <b>Instructions</b>               | <p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul> |
| <b>Exterior Walkaround Photos</b> |    |
|                                   |   |


**Inspection Report (On-Highway Flatbed Truck)**



**Inspection Report (On-Highway Flatbed Truck)**



## Inspection Report (On-Highway Flatbed Truck)



### General Appearance Inspection Points

#### General Appearance

|                 |   |
|-----------------|---|
| Front           | 3 - Normal Wear & Tear  |
| Front Condition | No visible damage, Other (see comments)   |
| Comments        | Normal paint wear, front tires 11r22.5 have 40 to 50 % tread life left  |
| Front Photos    |   |

Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                       |  |
|-----------------------|--|
|                       |    |
| <b>Rear</b>           | 3 - Normal Wear & Tear   |
| <b>Rear Condition</b> | No visible damage, Other (see comments)  |
| <b>Comments</b>       | Rear tires are 11r22.5 have 40 to 50 % tread life left                               |
| <b>Rear Photos</b>    |   |
|                       |  |

Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                       |  |  |
|-----------------------|--|--|
|                       |    |  |
| <b>Left</b>           | 3 - Normal Wear & Tear   |  |
| <b>Left Condition</b> | No visible damage  |  |
| <b>Left Photos</b>    |   |  |
|                       |  |  |

Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                     |  |  |
|---------------------|--|--|
|                     |    |  |
| <p>Right</p>        | <p>3 - Normal Wear &amp; Tear</p>  |  |
| <p>Right Photos</p> |   |  |
|                     |  |  |

Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                 |  |
|-----------------|--|
|                 |    |
| Upper           | 3 - Normal Wear & Tear   |
| Upper Condition | No visible damage  |
| Upper Photos    |   |
|                 |  |

**Inspection Report (On-Highway Flatbed Truck)**

|  |  |  |
|--|--|--|
|  |    |  |
|  |   |  |
| <p><b>Body Panels (Any Rust Damage?)</b></p> | <p>3 - Normal Wear &amp; Tear</p>  |  |
| <p><b>Body Panels Photos</b></p>             |  |  |

### Inspection Report (On-Highway Flatbed Truck)

|   |  |  |
|---|--|--|
|   |    |  |
|   |   |  |
| <b>Doors / Canopy Latches</b>           | 3 - Normal Wear & Tear   |  |
| <b>Doors / Canopy Latches Condition</b> | No visible damage  |  |
| <b>Doors / Canopy Latches Photos</b>    |  |  |

### Inspection Report (On-Highway Flatbed Truck)

|                              |  |
|------------------------------|--|
|                              |    |
|                              |   |
|                              |  |
| <b>Glass Condition</b>       | 3 - Normal Wear & Tear   |
| <b>Glass Condition Notes</b> | Glass intact, no visible damage, Minor chips or cracks observed                      |

### Inspection Report (On-Highway Flatbed Truck)

Glass Condition Photos



### Inspection Report (On-Highway Flatbed Truck)

|                              |  |  |
|------------------------------|--|--|
|                              |    |  |
|                              |   |  |
| <p><b>Mirrors</b></p>        | <p>3 - Normal Wear &amp; Tear</p>  |  |
| <p><b>Mirrors Photos</b></p> |  |  |

Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                                  |  |  |
|----------------------------------|--|--|
|                                  |    |  |
| <b>Lighting System</b>           | 3 - Normal Wear & Tear   |  |
| <b>Lighting System Condition</b> | No visible damage, lighting system is operational                                    |  |
| <b>Lighting System Photos</b>    |   |  |
|                                  |  |  |

Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



## Inspection Report (On-Highway Flatbed Truck)



### Cab Inspection Points

#### On Highway - Cab


|                                  |  |
|----------------------------------|--|
| <b>Instructions</b>              | <p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced<br/>         3 = Normal Wear &amp; Tear<br/>         2 = Above Average Wear<br/>         1 = Service Required</p> <p>Take close-up photos of and leave comments.</p> |
| <b>Serial Number Plate Photo</b> |    |
| <b>Operator Cabin</b>            | 3 - Normal Wear & Tear   |

### Inspection Report (On-Highway Flatbed Truck)


Operator Cabin Photos



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



**Inspection Report (On-Highway Flatbed Truck)**

|  |  |  |
|--|--|--|
|  |    |  |
| <p><b>Operator's Seat &amp; Arm Rests</b></p>        | <p>3 - Normal Wear &amp; Tear</p>  |  |
| <p><b>Operator's Seat &amp; Arm Rests Photos</b></p> |   |  |
|  |  |  |

Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                  |  |  |
|------------------|--|--|
|                  |    |  |
|                  |   |  |
|                  |  |  |
| <b>Seat Belt</b> | 3 - Normal Wear & Tear   |  |
| <b>Comments</b>  | Passenger seat belt inop   |  |

### Inspection Report (On-Highway Flatbed Truck)

Seat Belt Photos



**Inspection Report (On-Highway Flatbed Truck)**



Cabin Lights

3 - Normal Wear & Tear

Cabin Lights Photos



**Inspection Report (On-Highway Flatbed Truck)**

|                                       |  |  |
|---------------------------------------|--|--|
|                                       |    |  |
|                                       |   |  |
|                                       |  |  |
| <p><b>Controls &amp; Switches</b></p> | <p>3 - Normal Wear &amp; Tear</p>  |  |

### Inspection Report (On-Highway Flatbed Truck)

Controls & Switches Photos



### Inspection Report (On-Highway Flatbed Truck)

|                                 |  |  |
|---------------------------------|--|--|
|                                 |    |  |
| <b>Odometer Activity</b>        | 3 - Normal Wear & Tear   |  |
| <b>Odometer Activity Photos</b> |   |  |
|                                 |  |  |
| <b>Other Gauge Activity</b>     | 3 - Normal Wear & Tear   |  |

## Inspection Report (On-Highway Flatbed Truck)

|                                    |  |
|------------------------------------|--|
| <p>Other Gauge Activity Photos</p> |    |
|                                    |   |
| <p>Heater &amp; A/C</p>            | <p>3 - Normal Wear &amp; Tear</p>  |
| <p>Heater &amp; A/C Photos</p>     |  |
| <p>Fans / Vents</p>                | <p>3 - Normal Wear &amp; Tear</p>  |

### Inspection Report (On-Highway Flatbed Truck)

|                               |  |
|-------------------------------|--|
| Fans / Vents Photos           |    |
|                               |   |
|                               |  |
| Horn                          | 3 - Normal Wear & Tear   |
| Reverse Alarm / Backup Signal | 7  |
| Backup Camera                 | 0  |

## Inspection Report (On-Highway Flatbed Truck)

|                                |  |
|--------------------------------|--|
| Other Electronic Device Photos |   |
| Fire Extinguisher              | 3 - Normal Wear & Tear   |
| Fire Extinguisher Photos       |  |
| First Aid Kit                  | 0  |

## Engine Inspection Points

### Engine


|  |  |
|--|--|
| Engine Type (Make, Model, Cylinders, Hp) | PACCAR MX-13 - 6 CYL. - 12.9L - 430 HP |
| Engine Serial Number                     | Y002331                                |
| Engine Fuel Type                         | Diesel                                 |

### Inspection Report (On-Highway Flatbed Truck)

Engine Photos



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|   |   |  |
|---|---|--|
|   |   |  |
|   |  |  |
| <b>Blow-by (Visual Observation Check)</b>             | No  |  |
| <b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b> | No  |  |
| <b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>   | No  |  |
| <b>Engine Smoke Notes</b>                             | No engine smoke issues observed   |  |
| <b>Engine Exhaust Color</b>                           | Clear   |  |
| <b>Battery</b>  | 3 - Normal Wear & Tear  |  |
| <b>Battery Condition</b>                              | Other (see comments), Dusty & dirty appearance                                      |  |
| <b>Comments</b>                                       | Batteries look okay just dusty  |  |

### Inspection Report (On-Highway Flatbed Truck)

|                                 |  |
|---------------------------------|--|
| <p>Battery Condition Photos</p> |    |
|                                 |   |
|                                 |  |
| <p>Radiator</p>                 | <p>3 - Normal Wear &amp; Tear</p>  |

### Inspection Report (On-Highway Flatbed Truck)

Radiator Photos



Inspection Report (On-Highway Flatbed Truck)




Inspection Report (On-Highway Flatbed Truck)




### Inspection Report (On-Highway Flatbed Truck)

|                       |  |
|-----------------------|--|
|                       |    |
| <b>Belts</b>          | 3 - Normal Wear & Tear   |
| <b>Belt Condition</b> | Belts appear in good condition & alignment with proper tension                       |
| <b>Belt Photos</b>    |   |
|                       |  |

Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                    |  |  |
|--------------------|--|--|
|                    |    |  |
| <p>Hoses</p>       | <p>3 - Normal Wear &amp; Tear</p>  |  |
| <p>Hose Photos</p> |   |  |
|                    |  |  |

Inspection Report (On-Highway Flatbed Truck)



### Inspection Report (On-Highway Flatbed Truck)

|                                       |  |
|---------------------------------------|--|
|                                       |    |
|                                       |   |
| <b>Water Pump</b>                     | 3 - Normal Wear & Tear   |
| <b>Water Pump Condition</b>           | No unusual pump noises heard, Other (see comments                                    |
| <b>Comments</b>                       | Recently replaced  |
| <b>Water Pump Photos</b>              |  |
| <b>Cooling System Leaks</b>           | No   |
| <b>Coolant Color / Appearance</b>     | 3 - Normal Wear & Tear   |
| <b>Coolant Color/Appearance Notes</b> | Normal Translucent appearance, no visual signs of contamination                      |
| <b>Oil Leaks</b>                      | No   |

## Inspection Report (On-Highway Flatbed Truck)

|   |   |
|---|---|
| Oil Color / Appearance                        | 3 - Normal Wear & Tear  |
| Oil Color / Appearance Notes                  | Clean oil appearance, no signs of cross contamination, Appropriate oil level                      |
| Fuel Leaks                                    | No  |
| Equipped with DPF (Diesel Particulate Filter) | Yes   |
| DPF Condition                                 | 3 - Normal Wear & Tear  |
| DPF Condition Notes                           | Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated |
| DPF Photos                                    |                |
| Requires DEF (Diesel Exhaust Fluid)           | Yes   |
| DEF Tank                                      | 3 - Normal Wear & Tear  |

## Inspection Report (On-Highway Flatbed Truck)

|                           |  |
|---------------------------|--|
| DEF Tank Photos           |    |
|                           |   |
|                           |    |
| Overall Engine Appearance | Clean & dry  |
| Overall Engine Comments   | Engine looks well serviced and unkept. Signs of various components replaced to keep the engine running strong and healthy. No fluid leaks or obvious, major repairs needed from a visual standpoint. |

### Aux. Engine Inspection Points

## Inspection Report (On-Highway Flatbed Truck)

|                     |  |
|---------------------|--|
| <b>Instructions</b> | Assess the condition of the aux. engine / power unit.<br><br>For items on a 4 point scale, evaluate using the following criteria:<br><br>4 = Like New, Recently Replaced<br>3 = Normal Wear & Tear<br>2 = Above Average Wear<br>1 = Service Required |
|---------------------|--|

### Drivetrain Inspection Points

#### Drivetrain

|                                       |   |
|---------------------------------------|---|
| <b>Transmission Info (Make/Model)</b> | Eaton Fuller 13 speed (RTLO)  |
| <b>Drive Type</b>                     | 4X2   |
| <b>Overdrive</b>                      | No  |
| <b>Transmission</b>                   | 3 - Normal Wear & Tear  |
| <b>Transmission Condition Photos</b>  |  |
| <b>Clutch</b>                         | 3 - Normal Wear & Tear  |
| <b>Clutch Condition</b>               | Clutch is functioning as expected   |
| <b>Shift Lever</b>                    | 3 - Normal Wear & Tear  |

## Inspection Report (On-Highway Flatbed Truck)

|                                    |  |
|------------------------------------|--|
| <b>Shift Lever Photos</b>          |    |
|                                    |   |
| <b>Differential</b>                | Check condition of the differential(s). Take photos and notes as relevant.           |
| <b>Rear Differential</b>           | 3 - Normal Wear & Tear   |
| <b>Rear Differential Condition</b> | Dry housing appearance, no unusual noises heard during operation                     |
| <b>Rear Differential Photos</b>    |  |

### Inspection Report (On-Highway Flatbed Truck)

|                                  |  |  |
|----------------------------------|--|--|
|                                  |    |  |
| <p>Front Differential</p>        | <p>3 - Normal Wear &amp; Tear</p>  |  |
| <p>Front Differential Photos</p> |   |  |
|                                  |  |  |

### Inspection Report (On-Highway Flatbed Truck)

|  |  |  |
|--|--|--|
|  |    |  |
| <b>Brake System Type</b>                 | Air Brakes   |  |
| <b>Air Brakes Build Correct Pressure</b> | Yes  |  |
| <b>Air Brake System Leaks</b>            | No   |  |
| <b>Comments</b>                          | Brake shoes look recently replaced   |  |
| <b>Air Brake Hose Condition</b>          | 3 - Normal Wear & Tear   |  |
| <b>Air Brake System Photos</b>           |  |  |
|  |  |  |

Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)



**Inspection Report (On-Highway Flatbed Truck)**

|                   |  |  |
|-------------------|--|--|
|                   |    |  |
|                   |   |  |
|                   |  |  |
| <p>Foot Brake</p> | <p>3 - Normal Wear &amp; Tear</p>  |  |

## Inspection Report (On-Highway Flatbed Truck)

|                            |   |
|----------------------------|---|
| Foot Brake Photos          |   |
| Engine Brake Configuration | 2 Position  |
| Engine Brake               | 3 - Normal Wear & Tear  |
| Parking Brake              | 3 - Normal Wear & Tear  |
| Parking Brake Photos       |  |

## Chassis & Axle Inspection Points

### Sub-Form

#### Frame

|                 |   |
|-----------------|---|
| Frame Condition | 3 |
|-----------------|---|

#### Suspension

|            |   |
|------------|---|
| Suspension | 3 |
|------------|---|

#### Steering

|                      |   |
|----------------------|---|
| Steering Components  | 3 |
| Steer Axle Condition | 3 |

#### Wheels & Tires

|                        |                                 |
|------------------------|---------------------------------|
| Wheels & Hub Condition | 3                               |
| Wheel Seal Leaks       | No                              |
| Tire Brand             | General (front) Sumitomo (rear) |


## Inspection Report (On-Highway Flatbed Truck)

|                                    |          |
|------------------------------------|----------|
| Tire Size                          | 11R 22.5 |
| Front Left Tire - Ratio Remaining  | 50%      |
| Front Right Tire - Ratio Remaining | 50%      |
| Rear Right Tire - Ratio Remaining  | 50%      |
| Rear Left Tire - Ratio Remaining   | 50%      |

### Brake Components

|                      |                                    |
|----------------------|------------------------------------|
| Brake Shoe Thickness | 90%                                |
| Comments             | Brake shoes look recently replaced |

### Overall Chassis Condition

|  |   |
|--|---|
| Overall Chassis                        | 3   |
| Overall Chassis Comments               | Overall suspension, wheels, brakes and front axle in good condition with 40 to 50% of overall tire tread and 80 to 90% of brake shoe material left. |
| Overall Chassis & Undercarriage Photos |    |
| Additional Axles                       | Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.                                |

### Functional Test

|              |   |
|--------------|---|
| Instructions | <p>Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):</p> <p>4 = Like New, Recently Replaced<br/>         3 = Normal Wear &amp; Tear<br/>         2 = Above Average Wear<br/>         1 = Service Required</p> |
|--------------|---|

## Inspection Report (On-Highway Flatbed Truck)

|                   |                                   |
|-------------------|-----------------------------------|
| Forward & Reverse | 3 - Normal Wear & Tear            |
| Steering          | 3 - Normal Wear & Tear            |
| Engine            | 3 - Normal Wear & Tear            |
| Controls          | 3 - Normal Wear & Tear            |
| Operating Video   | <a href="#">Click to Download</a> |

### Inspection Summary

|                                |   |
|--------------------------------|---|
| Exterior Rating                | 3 - Normal Wear & Tear  |
| Interior Rating                | 3 - Normal Wear & Tear  |
| Safety Rating                  | 3 - Normal Wear & Tear  |
| Quality Rating                 | 3 - Normal Wear & Tear  |
| Functionality Rating           | 3 - Normal Wear & Tear  |
| Overall Rating                 | 3 - Normal Wear & Tear  |
| What's Great About the Machine | Tractor is well maintained and no major repairs required. This truck is ready to be put to work.                              |
| What Needs Work                | Some tires need to be replaced soon, some exterior marker lamps not functioning and passenger seat belt not working properly. |
| Inspector's Name               | Mario Ramirez   |
| Date/Time                      | 09-01-2022  |