


## Inspection Report (Vibratory Compactor)

### General Info

Year	2016
Make	HAMM
Model	HD 12 VV
Serial Number	H2300767
Hour Meter Reading	881.2
Previous Application (e.g., earth moving, mining, demolition, etc)	Equipment Rental

### Dimensions

Measurement Guide	
A. Length (ft and inches)	8'3"
B. Width (ft and inches)	4'2"
C. Height (ft and inches)	5'8"
D. Drum Diameter (ft and inches)	2'4"
E. Wheelbase (ft and inches)	5'6"
Operational Weight (lbs)	7,519lbs.

### Features and Configuration

Control Station Type	Canopy
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No
Drum System	Dual Drum
Padfoot Roller?	No
Vibration Frequency (Hz)	Front & Rear (same) stage 1 = 3,900VPM / stage 2 = 3,060VPM
Centrifugal Force - Low/High (lbs)	Front & Rear (same) stage 1 = 8,550lbs / stage 2 = 5,175lbs
Water Spray System	Yes

## Inspection Report (Vibratory Compactor)

Water Spray System Capacity	47 1/2 G.P.M.
Other Configuration Details / Notes	OMM manual not in English

### OMM Specifications

### OMM Specifications

Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
-----------------------	--

### Exterior 360 Walkaround

### Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul>
--------------	---

Exterior Walkaround Photos	 
----------------------------	---

Inspection Report (Vibratory Compactor)



## Inspection Report (Vibratory Compactor)



### General Appearance Inspection Points

#### General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Visible chipped paint or dents, Other (see comments)
Comments	Normal wear and tear no major damage

### Inspection Report (Vibratory Compactor)

Front Photos



### Inspection Report (Vibratory Compactor)

	
<b>Rear</b>	3 - Normal Wear & Tear
<b>Rear Condition</b>	No visible damage, Visible chipped paint or dents
<b>Comments</b>	Normal wear and tear no major damage
<b>Rear Photos</b>	
	
<b>Left</b>	3 - Normal Wear & Tear
<b>Left Condition</b>	No visible damage, Visible chipped paint or dents, Other (see comments)
<b>Comments</b>	Normal wear and tear minor scuff marks

### Inspection Report (Vibratory Compactor)

Left Photos	
	
<b>Right</b>	3 - Normal Wear & Tear
<b>Right Condition</b>	No visible damage, Visible chipped paint or dents, Other (see comments)
<b>Comments</b>	Normal wear and tear scuff marks
<b>Right Photos</b>	

### Inspection Report (Vibratory Compactor)

	
	
<b>Body Panels (Any Rust Damage?)</b>	3 - Normal Wear & Tear
<b>Body Panel Condition</b>	No visible damage, good paint condition and panel fitment, Other (see comments)
<b>Comments</b>	Small crack on front left side of hood and scuff marks on some panels but most minor scratches
<b>Body Panels Photos</b>	

Inspection Report (Vibratory Compactor)



### Inspection Report (Vibratory Compactor)

		
		
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	
Glass Condition	0	
Mirrors	0	
Lighting System	3 - Normal Wear & Tear	
Lighting System Condition	No visible damage, lighting system is operational	
Lighting System Photos		

### Control Station Inspection Points

## Inspection Report (Vibratory Compactor)

### Control Station

<p>Serial Number Plate Photo</p>	
<p>Operator Cabin Overall</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Operator Cabin Overall Condition</p>	<p>Good cabin appearance, solid floors, panels, and ceiling, Minor cosmetic wear to cabin surfaces, floors, panels, and ceiling</p>
<p>Operator Cabin Photos</p>	
	

Inspection Report (Vibratory Compactor)



Inspection Report (Vibratory Compactor)



Inspection Report (Vibratory Compactor)



Inspection Report (Vibratory Compactor)



### Inspection Report (Vibratory Compactor)

	
<b>Operator's Seat &amp; Arm Rests</b>	3 - Normal Wear & Tear
<b>Operator's Seat &amp; Arm Rests Condition</b>	Seat(s) in good condition, no stains or tears in upholstery, Seat(s) have minor surface staining or small tears, Other (see comments)
<b>Comments</b>	Top of seat cushion torn
<b>Operator's Seat &amp; Arm Rests Photos</b>	

### Inspection Report (Vibratory Compactor)

	
	
<b>Seat Belt</b>	3 - Normal Wear & Tear
<b>Seat Belt Condition</b>	Seat belt secures properly. Belt is intact and in good condition
<b>Cabin Lights</b>	0
<b>Safety Lock Out / Stop</b>	0
<b>Controls &amp; Switches</b>	3 - Normal Wear & Tear
<b>Controls &amp; Switches Condition</b>	All switches are installed and functional

## Inspection Report (Vibratory Compactor)

<p>Controls &amp; Switches Photos</p>	
	
<p>Hour Meter Activity</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Hour Meter Condition</p>	<p>Hour meter is functional and in good condition</p>

## Inspection Report (Vibratory Compactor)

Hour Meter Activity Photos	
Other Gauge Activity	0
Heater & A/C	0
Fans / Vents	0
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

## Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Kubota - 1.7L - 3cyl. - 25HP
Emissions Tier	Other (see comments)
Comments	Under 75 hp Aftertreatment not required
Engine Serial Number	H2300767
Engine Fuel Type	Diesel

### Inspection Report (Vibratory Compactor)

Engine Photos



## Inspection Report (Vibratory Compactor)

		
		
<b>Blow-by (Visual Observation Check)</b>	No	
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No	
<b>Unusual Noise Notes</b>	No unusual noises heard	
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No	
<b>Engine Smoke Notes</b>	No engine smoke issues observed	
<b>Engine Exhaust Color</b>	Clear	
<b>Battery</b>	3 - Normal Wear & Tear	
<b>Battery Condition</b>	Like new, recently replaced	

## Inspection Report (Vibratory Compactor)

<b>Battery Condition Photos</b>	
<b>Radiator</b>	3 - Normal Wear & Tear
<b>Radiator Condition</b>	Radiator fins & components appear to be in good working order, no signs of damage or leaks
<b>Radiator Photos</b>	
	
<b>Belts</b>	3 - Normal Wear & Tear
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension

## Inspection Report (Vibratory Compactor)

<b>Belt Photos</b>	
	
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks
<b>Hose Photos</b>	

Inspection Report (Vibratory Compactor)



Inspection Report (Vibratory Compactor)



## Inspection Report (Vibratory Compactor)

		
		
<b>Water Pump</b>	3 - Normal Wear & Tear	
<b>Water Pump Condition</b>	No unusual pump noises heard	
<b>Cooling System Leaks</b>	No	
<b>Coolant Color / Appearance</b>	3 - Normal Wear & Tear	
<b>Coolant Color/Appearance Notes</b>	Normal Translucent appearance, no visual signs of contamination	
<b>Oil Leaks</b>	No	
<b>Oil Color / Appearance</b>	3 - Normal Wear & Tear	
<b>Oil Color / Appearance Notes</b>	Clean oil appearance, no signs of cross contamination, Appropriate oil level	
<b>Fuel Leaks</b>	No	
<b>Equipped with DPF (Diesel Particulate Filter)</b>	No	
<b>Requires DEF (Diesel Exhaust Fluid)</b>	No	
<b>Overall Engine Appearance</b>	Clean & dry	
<b>Overall Engine Comments</b>	Overall engine looks and sounds good. No leaks found and engine looks well maintained. No obvious major repairs required on engine.	

### Drivetrain Inspection Points

#### Drivetrain


## Inspection Report (Vibratory Compactor)

Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Other (see comments)
Comments	Hydrostatic driven
Drive Motors	2 - Above Average Wear
Comments	In good shape
Drive Motor Photos	
	
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall machine functions well in both directions and stops safely.

## Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Comments	No issues found with frame

### Inspection Report (Vibratory Compactor)

<p>Frame Photos</p>	
	
	

### Inspection Report (Vibratory Compactor)

		
<b>Level Stance</b>	3 - Normal Wear & Tear	
<b>Comments</b>	Machine sits normal	
<b>Level Stance Photos</b>		
<b>Drum(s) Condition</b>	3 - Normal Wear & Tear	
<b>Comments</b>	Drums in great condition	
<b>Drum(s) Photos</b>		


Inspection Report (Vibratory Compactor)




**Inspection Report (Vibratory Compactor)**

		
		
<p>Vibratory Rubber Mounts (Front &amp; Rear)</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Vibratory Rubber Mounts (Front &amp; Rear) Photos</p>		

Inspection Report (Vibratory Compactor)



Inspection Report (Vibratory Compactor)

		
<p>Drum Scraper</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Drum Scraper Photos</p>		
		

## Inspection Report (Vibratory Compactor)

	
<b>Overall Chassis</b>	4 - Like New, Recently Replaced
<b>Overall Chassis Comments</b>	Overall chassis in great condition with no immediate repairs needed.

## Hydraulics Overall Inspection Points

### Hydraulics Overall

<b>Wet or Damp Hydraulic Lines / Fittings</b>	No
<b>Appearance of Hydraulic Lines / Fittings</b>	3
<b>Hydraulic Lines / Fittings Condition</b>	Hydraulic lines & fittings are clean and in good condition
<b>Appearance of Hydraulic Lines / Fittings Photos</b>	

Inspection Report (Vibratory Compactor)



Inspection Report (Vibratory Compactor)



### Inspection Report (Vibratory Compactor)

		
<b>Unusual Noises (Hydraulic Pump)</b>	No	
<b>Hydraulic Pump Notes</b>	No unusual noises heard during operation	
<b>External Controls / Levers</b>	3	
<b>External Controls / Levers Condition</b>	Good function & condition of hydraulic controls	
<b>External Controls / Levers Photos</b>		
		

## Inspection Report (Vibratory Compactor)



### Hydraulics Cylinders Inspection Points

Steering Cylinders	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinders: Mounting Pin	3
Steering Cylinders: Oil Leaks	No
Steering Cylinders Photos	
	

### Functional Test

## Inspection Report (Vibratory Compactor)

<b>Instructions</b>	Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate):  4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required
<b>Forward &amp; Reverse</b>	4 - Like New, Recently Replaced
<b>Steering</b>	4 - Like New, Recently Replaced
<b>Vibratory System</b>	3 - Normal Wear & Tear
<b>Front Drum</b>	3 - Normal Wear & Tear
<b>Rear Drum</b>	3 - Normal Wear & Tear
<b>Overall Functional Test Comments</b>	Overall machine operates well in every direction and vibratory system functions great.
<b>Operating Video</b>	<a href="#">Click to Download</a>

## Overall Assessment

### Overall Assessment

<b>Exterior Rating</b>	3
<b>Interior Rating</b>	3
<b>Safety Rating</b>	3
<b>Quality Rating</b>	4
<b>Functionality Rating</b>	4
<b>Overall Rating</b>	3
<b>What's Great About the Machine</b>	The machine has low hours and it shows. Well maintained unit with no major issues found. All functions working properly.
<b>What Needs Work</b>	Machine has minor damage to frontside of hood and some other cosmetic repairs could be performed to make the machine look better.
<b>Any Additional Info from the Seller?</b>	N/a
<b>Date/Time</b>	09-07-2022