

Inspection Report (On-Highway Dump Truck)

General Info

Year	2013
Make	International
Model	4300
Serial Number	3HAMMAAL4DL198252
Truck Odometer Reading	281,798
Current Inspection / State Cert / DOT	N/A
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	25'
Width (ft and inches)	8'8" box width (widest section)
Height (ft and inches)	8'5"
Wheelbase (ft and inches)	16'
GVWR (lbs)	25,500



Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans mounted (Muncie PTO)
Engine Brake	No
Differential Lock	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Dump Truck)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



General Appearance Inspection Points

General Appearance




Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Other (see comments)
Comments	Small paint chips lower hood area

Inspection Report (On-Highway Dump Truck)

Front Photos



Inspection Report (On-Highway Dump Truck)




	
	
	
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage, Other (see comments)
Comments	Small dent bottom of dump body

Inspection Report (On-Highway Dump Truck)


Rear Photos






Inspection Report (On-Highway Dump Truck)

		
Left	3 - Normal Wear & Tear	
Left Condition	No visible damage	
Left Photos		
		

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




	
	
	
Right	3 - Normal Wear & Tear
Right Condition	No visible damage

Inspection Report (On-Highway Dump Truck)




Right Photos





Inspection Report (On-Highway Dump Truck)

		
Upper	3 - Normal Wear & Tear	
Upper Condition	No visible damage, Other (see comments)	
Comments	Small dent on dump body	
Upper Photos		
		

Inspection Report (On-Highway Dump Truck)

	
	
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Body Panels Photos	


Inspection Report (On-Highway Dump Truck)

	
	
	
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage




Inspection Report (On-Highway Dump Truck)

Doors / Canopy Latches Photos	
	
Glass Condition	3 - Normal Wear & Tear
Glass Condition Notes	Glass intact, no visible damage
Glass Condition Photos	


Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

	
	
	
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

	
	
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational, One or more exterior lights are non-operational, Other (see comments)
Comments	Front l/s headlight inop
Lighting System Photos	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

Operator Cabin	3 - Normal Wear & Tear
Comments	R/S Dash Fuse Panel Cover Loose
Operator Cabin Photos	
	
	

Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)






Operator's Seat & Arm Rests

3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)

<p>Operator's Seat & Arm Rests Photos</p>		
		
		
<p>Seat Belt</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (On-Highway Dump Truck)

<p>Seat Belt Photos</p>	
	
	
<p>Cabin Lights</p>	<p>3 - Normal Wear & Tear</p>




Inspection Report (On-Highway Dump Truck)

Cabin Lights Photos	 A photograph of a rectangular, recessed interior light fixture in the ceiling of a truck's cabin. The light is illuminated, casting a warm orange glow. The surrounding plastic housing is light-colored and shows some signs of use.
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Photos	 A close-up photograph of a control panel on the dashboard. It features several buttons: a 'WIP' button, a 'P-C' button with a sun icon and 'OFF' below it, and two 'PANEL' buttons with arrows pointing up and down.
	 A close-up photograph of another control panel on the dashboard. It features two buttons: 'FOG LIGHT' and 'PARK RESC' (Park Rescue), both with 'ON' indicators above them.

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Odometer Activity	3 - Normal Wear & Tear
Odometer Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Activity Photos	
Heater & A/C	2 - Above Average Wear
Comments	A/C inop Heater operation okay
Heater & A/C Photos	
Fans / Vents	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)

Fans / Vents Photos



Inspection Report (On-Highway Dump Truck)

		
Horn	3 - Normal Wear & Tear	
Reverse Alarm / Backup Signal	0	
Comments	No back up alarm heard	
Backup Camera	0	
Other Electronic Devices	0	
Fire Extinguisher	1 - Service Required	
Comments	2&1/2lbs extinguisher empty	
Fire Extinguisher Photos		
First Aid Kit	0	


Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Max force - Inline 6 - 7.6L - 215HP
Emissions Tier	Tier 4i
Engine Serial Number	466HM2U3334080
Engine Fuel Type	Diesel

Inspection Report (On-Highway Dump Truck)



Engine Photos






Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	3 - Normal Wear & Tear	
Battery Condition	Clean & dry appearance, tight connections, Other (see comments)	
Comments	Battery cover missing	




Inspection Report (On-Highway Dump Truck)

Battery Condition Photos	
	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	

Inspection Report (On-Highway Dump Truck)

	
	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension, Other (see comments)
Comments	Slight worn cracks starting to appear
Belt Photos	




Inspection Report (On-Highway Dump Truck)

		
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Hose Photos		
		


Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)

	
	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear




Inspection Report (On-Highway Dump Truck)

Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Engine well kept



Drivetrain Inspection Points

Drivetrain	
Transmission Info (Make/Model)	Allison Automatic
Drive Type	4X2
Overdrive	No
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
Transmission Condition Photos	

Inspection Report (On-Highway Dump Truck)

	
	
	
Clutch	0
Shift Lever	3 - Normal Wear & Tear
Shift Lever Condition	Good forward and reverse function

Inspection Report (On-Highway Dump Truck)



Shift Lever Photos	
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Rear Differential Photos	
Front Differential	0
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	No
Air Brake System Leaks	No
Air Brake Hose Condition	3 - Normal Wear & Tear
Comments	Air brake stops building psi at 118psi should be 120

Inspection Report (On-Highway Dump Truck)

Air Brake System Photos



Inspection Report (On-Highway Dump Truck)

	
Foot Brake	3 - Normal Wear & Tear
Foot Brake Condition	Good brake function
Foot Brake Photos	
Engine Brake Configuration	N/A
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function

Chassis & Axle Inspection Points

Chassis

Frame

Frame Condition	3
-----------------	---

Inspection Report (On-Highway Dump Truck)

Frame Photos




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Suspension

Suspension	3
Suspension Photos	



Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)





Steering

Steering Components	3
Steering Components Photos	
	

Inspection Report (On-Highway Dump Truck)

		
		
		
<p>Steer Axle Condition</p>	<p>3</p>	




Inspection Report (On-Highway Dump Truck)

Steer Axle Photos		
		




Wheels & Tires

Wheels & Hub Condition	3	
Wheels & Hub Photos		




Inspection Report (On-Highway Dump Truck)

	
	
	
Wheel Seal Leaks	No
Tire Brand	(Front) Firestone (rear) Generic recap brands
Tire Size	11r 22.5
Front Left Tire - Ratio Remaining	50%


Inspection Report (On-Highway Dump Truck)

<p>Front Left Tire Photos</p>	
	
<p>Front Right Tire - Ratio Remaining</p>	<p>70%</p>
<p>Front Right Tire Photos</p>	


Inspection Report (On-Highway Dump Truck)

		
Rear Right Tire - Ratio Remaining	70%	
Rear Right Tire Photos		
		
Rear Left Tire - Ratio Remaining	50%	


Inspection Report (On-Highway Dump Truck)

Rear Left Tire Photos	
	


Brake Components

Brake Shoe Thickness	70%
Comments	Rear shoes have 50% of material left front have 70% left
Brake Shoe Photos	


Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)



Overall Chassis Condition

Overall Chassis	3
Overall Chassis & Undercarriage Photos	

Inspection Report (On-Highway Dump Truck)

		
		
		
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.	




Additional Inspection Points

On Highway - Dump Truck

Additional Inspection Points: Dump Body, Tailgate, Support & Tarp

Dump Body, Tailgate, Support & Tarp	Check the condition of the dump body, tailgate, support & tarp. Note any damage or wear. Take photos.	
Dump Body Make & Material	Mickey Dump Body	

Inspection Report (On-Highway Dump Truck)




Dump Body Length (ft and inches)	16'
Dump Body Height (ft and inches)	6'
Bed Body	3 - Normal Wear & Tear
Comments	Dump body in good condition
Bed Body Photos	
	
	
Tailgate	3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)




Tailgate Photos






Inspection Report (On-Highway Dump Truck)

		
<p>Tailgate Latch</p>	<p>3 - Normal Wear & Tear</p>	
<p>Tailgate Latch Photos</p>		
		
<p>Support Frame</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (On-Highway Dump Truck)

<p>Support Frame Photos</p>	
	
	
<p>Hinge Points</p>	<p>3 - Normal Wear & Tear</p>




Inspection Report (On-Highway Dump Truck)

Hinge Point Photos	
	
Tarp	3 - Normal Wear & Tear
Tarp Photos	




Additional Inspection Points: Dump Hydraulics

Hydraulics	Check the condition of the hydraulics. Check lines, hoses, fittings, leaks, function, etc. Note any damage or wear. Take photos.
Hydraulic Tank	3 - Normal Wear & Tear



Inspection Report (On-Highway Dump Truck)

Hydraulic Tank Photos	
Hoses	3 - Normal Wear & Tear
Hose Photos	
	

Inspection Report (On-Highway Dump Truck)

		
Hydraulic Cylinders	3 - Normal Wear & Tear	
Cylinder Pins and Bushings	3 - Normal Wear & Tear	
Cylinder Pins and Bushings Photos		
		

Inspection Report (On-Highway Dump Truck)

		
		
Hydraulic Function	3 - Normal Wear & Tear	

Functional Test

Instructions	Evaluate the following on a 4 point scale (leave comments where an explanation is appropriate): 4 = Like New, Recently Replaced 3 = Normal Wear & Tear 2 = Above Average Wear 1 = Service Required
Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Engine	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Operating Video	Click to Download

Inspection Summary

Exterior Rating	3 - Normal Wear & Tear
Interior Rating	3 - Normal Wear & Tear
Safety Rating	3 - Normal Wear & Tear
Quality Rating	3 - Normal Wear & Tear



Inspection Report (On-Highway Dump Truck)

Functionality Rating	3 - Normal Wear & Tear
Overall Rating	3 - Normal Wear & Tear
What's Great About the Machine	Dump truck has good appearance and engine sounds healthy. Dump body and lift function works well. Truck is in good working condition with no active leaks found.
What Needs Work	Tires will need to be replaced soon. Battery compartment
Inspector's Name	Mario Ramirez
Date/Time	09-27-2022