

Location: Apex Contr acting+Consultng

Fallbrook, CA

TRUCK AND EQUIPMENT CONSULTING LLC - DUMP TRUCK

Date
(Y/M/D) 10/20/2022

Inspector
Initials D.K.

(Basic Information)	
(Make)	Ford
(Model)	F550 S.Duty XL Reg Cab 4x4 Dualie Rear
(Serial Number)	1FDAF57R19EA72115
(Year of Manufacturing/Origin)	2009 (built 3/09)
(Color)	White / Gray
(Mileage)	67,904 miles
(Engine)	PowerStroke 6.4L 325Hp V8 TurboDiesel
(Transmission)	Automatic 5 Spd
(Dump Body)	8 Ft x 12 Ft

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions	
GVWR	Rated 19,500 lbs / Class 6
Body	Stake Type Wood Slat Sides / Steel Bed Floor
DOT	CALIF THRU 2022
Brake	Hydraulic
Front / Rear Axle	Front =6500 lbs / Rear =14,700 lbs
Tires	Hankook 225/70R 19.5
Dump Body	Wired Hand Held Controls Miramar Dump Body
Rear	4.88
Wheelbase	141 inch
Origin	USA
Other	New Engine Installed 2018 Est 12K miles Rear commercial hitch, (2) 48 in Tool Boxes

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)		X	X			Level Stance. Upper front bumper trim missing. Cosmetic only No damage
	(General Appearance-Rear)			X			Rear slats wear+tear upper slats damage, open hole on back wood slat
	(General Appearance-Right)		X	X			Good Right side body panels+gaps, frame straight Side wood slats worn
	(General Appearance-Left)		X	X			Good Left side body panels+gaps, frame straight Side wood slats worn
	(General Appearance-Upper)		X				Good appearance hood, roof, upper body panels
	(Major / Minor Surface Rust)		X				No rust issues or rust damage Some surface rust front hubs+backboard
	(Body Panels / Covers - Rust Damage / Cancer)		X				No rust cancer Minor surface rust+backboard scrapes No rust damage
	(Visible Weld Repairs / Stress Cracks)		X				None seen
	(Glass Condition)		X				Good Glass
	(Chassis / Undercarriage Damage)		X	X			No damage Top of hydraulic resevoir+dump hinge damp dried seepage
OPERATOR'S COCKPIT	(Operator Cabin)		X				Good appearance No damage some surface scratches dash cosmetic only
	(Operator Controls and Switches)		X				Complete Good function No broken switches or controls
	(Odometer Activity)		X				Working
	(Other Gauge Activity)			X			Working Check Engine Light Lit
	(Door / Canopy Latches)		X				Good Hood + Door latch function
	(Safety - Horn / First Aid Kit)		X				Horn Working
	(Operator Seat Condition)		X				Seats Good condition
	(Other)		X				Hand Held Wired Dump Controls Good appearance and Good function
ENGINE	(Oil Color / Fluid Appearance)		X				Good Appearance No Blow-By at operating temp
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		X				Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color - White / Blue / Black / Clear)		X				Clear / Clear at Temperature
	(Oil Leaks)		X				No dampness or wet areas Dry appearance
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		X				No smoke issues
	(Coolant Color / Fluid Appearance)		X				Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		X				No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)		X				None seen Some dented radiator fins
	(Overall Engine Appearance Clean / Wet / Dry)		X				Engine Good + Dry appearance No rust No dried seepages seen

ELECTRICAL	(Lighting System Condition)	X	X			Working a couple lower side marker lights broken
	(Reverse Alarm / Backup Signal)					N/A
	(Battery Condition)	X				Good appearance Newer battery + battery terminals
	(Other Electric Device Condition)	X				Accessories Working Good function
TIRES	FRONT TRACTOR TIRES	X				Front Tires =B Good appearance No damage / Hubs =B- Surface rust
	TRAILER TIRES X4	X				Rear Tires X4 =B Good appearance No damage / Hubs =B
	OTHER	X				Good Tires Minimal Wear Inner Hubs Dry Some minor surface rust only
TRANSMISSION	(Clutch Noise / Function)	X				No unusual transmission noises or vibrations
	(Transmission Noise / Function)	X				Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	X				Good Shifter function
	(Other Remarks)	X				Pedals Good appearance No damage from wear or tear
DIFFERENTIAL	(Rear Diff - Noises ?)	X				No Rear Diff Noises heard Dry appearance
B R A K E S	(Foot Brake)	X				Good Brake Function
	(AIR BRAKE)					N/A
	(Parking Brake)	X				Good function
DUMP and HYDRAULICS	LIFT + DUMP	X				Good Lift + Drop function
	HYDRAULICS	X				Working
OPERATION	TARP					N/A
	PUMP PERFORMANCE	X				Good function No unusual noises
	FORWARD & REVERSE	X				Good Forward and Reverse function
	STEERING + BRAKES	X				Good Steering and Brakes function
	ENGINE	X				Engine Smooth Idle Good Response
	CONTROLS	X				Driver Controls + Switches Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	X	X			Straight body+ Interior Some wear+tear Rear Slats worn Check Eng Light
	COMMENTS	X	X			Surface rust cosmetics, wear+tear, Upper hydraulic tank dried seepage
	OVERALL PERFORMANCE INSPECTION	X				Good travel performance Good steering+brakes Good engine response
	COMMENTS	X				Good dump lift and drop function + performance

TIRES

OVERALL EXTERIOR RATING: B-/C+ QUALITY: C+

OVERALL INTERIOR RATING: B/B- SAFETY: B

OVERALL PERFORMANCE: B FUNCTIONALITY: B

OVERALL CONDITION GRADE: **B - / C+**

FLUID SAMPLE REQUEST (Y/N) n OIL n COOLANT n

*A:Remaining Ratio 90% or more
 *B:Remaining Ratio 70% or more
 *C:Remaining Ratio 50% or more
 *D:Remaining Ratio 20% or more
 *E:Remaining Ratio 20% or less