


Inspection Report (Wheel Loader)

General Info

| | |
|--|----------------------|
| Year | 1979 |
| Make | CAT |
| Model | 930B unit 15-104 |
| Serial Number | 41K9005 |
| Hour Meter Reading | 2,408 |
| Previous Application (e.g., earth moving, mining, demolition, etc) | General Construction |

Dimensions

| | |
|-------------------------------------|---|
| Measurement Guide |  |
| A. Length (ft and inches) | 20' |
| B. Width (ft and inches) | 7'8" |
| C. Height (ft and inches) | 10'4" |
| D. Attachment Width (ft and inches) | 7' |
| Operational Weight (lbs) | 21,208 |

Features and Configuration

| | |
|-------------------------------------|--------|
| Control Station Type | Canopy |
| Bucket | No |
| Auxiliary Hydraulics | Yes |
| Heat | No |
| A/C | No |
| Radio | No |
| Backup Camera | No |
| OMM (Operator & Maintenance Manual) | No |
| Telematics | No |

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (Wheel Loader)

| | |
|--|---|
| <p>Instructions</p> | <p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background |
| <p>Exterior Walkaround Photos</p> |  |
| |  |

Inspection Report (Wheel Loader)



Inspection Report (Wheel Loader)



Inspection Report (Wheel Loader)



General Appearance Inspection Points

General Appearance

| | |
|-----------------|--|
| Front | 3 - Normal Wear & Tear |
| Front Condition | No visible damage |
| Front Photos |  |

Inspection Report (Wheel Loader)

| | |
|----------------|--|
| |  |
| |  |
| |  |
| Rear | 3 - Normal Wear & Tear |
| Rear Condition | No visible damage |

Inspection Report (Wheel Loader)

| | |
|----------------|--|
| Rear Photos |  |
| Left | 3 - Normal Wear & Tear |
| Left Condition | No visible damage |
| Left Photos |  |
| |  |

Inspection Report (Wheel Loader)

| | |
|-------------------------------|--|
| |  |
| |  |
| |  |
| <p>Right</p> | <p>3 - Normal Wear & Tear</p> |
| <p>Right Condition</p> | <p>No visible damage</p> |

Inspection Report (Wheel Loader)

| | |
|----------------------------------|--|
| Right Photos |  |
| |  |
| |  |
| Upper | 3 - Normal Wear & Tear |
| Upper Condition | No visible damage |
| Body Panels (Any Rust Damage?) | 3 - Normal Wear & Tear |
| Body Panel Condition | No visible damage, good paint condition and panel fitment |
| Doors / Canopy Latches | 3 - Normal Wear & Tear |
| Doors / Canopy Latches Condition | No visible damage |
| Steps / Ladders | 3 - Normal Wear & Tear |

Inspection Report (Wheel Loader)

| | |
|---------------------------|--|
| Steps / Ladders Condition | Steps/ladders are fully intact and appear structurally sound |
| Steps / Ladders Photos |  |
| |  |
| |  |
| Handrails | 3 - Normal Wear & Tear |
| Handrails Condition | Handrails are fully intact and appear structurally sound |
| Glass Condition | 3 - Normal Wear & Tear |
| Glass Condition Notes | Glass intact, no visible damage |


Inspection Report (Wheel Loader)

| | |
|---------------------------|--|
| Glass Condition Photos |  |
| Mirrors | 3 - Normal Wear & Tear |
| Mirror Condition Notes | Mirrors present and intact, no visible damage |
| Mirrors Photos |  |
| Lighting System | 1 - Service Required |
| Lighting System Condition | Overall lighting system is non-operational |
| Lighting System Photos |  |
| |  |

Control Station Inspection Points

Inspection Report (Wheel Loader)

Control Station

| | |
|----------------------------------|--|
| Serial Number Plate Photo |  |
| Operator Cabin Overall | 3 - Normal Wear & Tear |
| Operator Cabin Overall Condition | Good cabin appearance, solid floors, panels, and ceiling |
| Operator Cabin Photos |  |
| |  |

Inspection Report (Wheel Loader)



Inspection Report (Wheel Loader)

| | |
|--|--|
| |  |
| |  |
| |  |
| Operator's Seat & Arm Rests | 3 - Normal Wear & Tear |
| Operator's Seat & Arm Rests Condition | Seat(s) is damaged due to sun exposure; fading, cracking observed |

Inspection Report (Wheel Loader)

| | |
|---|--|
| <p>Operator's Seat & Arm Rests Photos</p> |  |
| |  |
| <p>Seat Belt</p> | <p>3 - Normal Wear & Tear</p> |
| <p>Seat Belt Condition</p> | <p>Seat belt secures properly. Belt is intact and in good condition</p> |
| <p>Cabin Lights</p> | <p>0</p> |
| <p>Safety Lock Out / Stop</p> | <p>0</p> |
| <p>Controls & Switches</p> | <p>2 - Above Average Wear</p> |
| <p>Controls & Switches Condition</p> | <p>One or more switches are inoperative or missing</p> |
| <p>Controls & Switches Photos</p> |  |

Inspection Report (Wheel Loader)

| | | |
|----------------------------|--|--|
| |  | |
| Hour Meter Activity | 3 - Normal Wear & Tear | |
| Hour Meter Condition | Hour meter is functional and in good condition, Other (see comments) | |
| Comments | Hour meter has been replaced (actual hours unknown) | |
| Hour Meter Activity Photos |  | |

Inspection Report (Wheel Loader)

| | |
|-----------------------------|---|
| Other Gauge Activity | 3 - Normal Wear & Tear |
| Other Gauge Condition | All cockpit gauges are functional and in good condition |
| Other Gauge Activity Photos |  |
| Heater & A/C | 0 |
| Fans / Vents | 0 |
| Travel Alarm | 3 - Normal Wear & Tear |
| Travel Alarm Condition | Travel alarm is installed and functioning as expected |
| Horn | 0 |
| Backup Camera | 0 |
| Fire Extinguisher | 0 |
| First Aid Kit | 0 |

Engine Inspection Points

| Engine | |
|--|------------------------|
| Engine Type (Make, Model, Cylinders, Hp) | CAT 3304 - 4CYL - 95HP |
| Emissions Tier | Tier 0 |
| Engine Serial Number | 43V21988 |
| Engine Fuel Type | Diesel |

Inspection Report (Wheel Loader)

Engine Photos




Inspection Report (Wheel Loader)



Inspection Report (Wheel Loader)

| | | |
|---|---|--|
| |  | |
| |  | |
| Blow-by (Visual Observation Check) | Yes | |
| Comments | Minor blowby | |
| Unusual Noises (Upon Start-up, Idle, Shutdown) | No | |
| Unusual Noise Notes | No unusual noises heard | |
| Engine Smoke (Upon Start-up, Idle, Shutdown) | Yes | |
| Engine Smoke Notes | Other (see comments) | |
| Comments | Minor smoke under load | |
| Engine Exhaust Color | Clear, Black puffs observed under throttle | |
| Battery | 3 - Normal Wear & Tear | |
| Battery Condition | Clean & dry appearance, tight connections, Dusty & dirty appearance | |

Inspection Report (Wheel Loader)

| | | |
|---------------------------------|--|--|
| Battery Condition Photos |  | |
| Radiator | 3 - Normal Wear & Tear | |
| Radiator Condition | Radiator fins & components appear to be in good working order, no signs of damage or leaks | |
| Radiator Photos |  | |
| |  | |
| Belts | 3 - Normal Wear & Tear | |
| Belt Condition | Belts appear in good condition & alignment with proper tension | |

Inspection Report (Wheel Loader)

| | |
|--------------------------------|--|
| Belt Photos |  |
| Hoses | 3 - Normal Wear & Tear |
| Hose Condition | Firm, pliant hoses with no signs of wear or leaks |
| Water Pump | 3 - Normal Wear & Tear |
| Water Pump Condition | No unusual pump noises heard |
| Cooling System Leaks | No |
| Coolant Color / Appearance | 3 - Normal Wear & Tear |
| Coolant Color/Appearance Notes | Normal Translucent appearance, no visual signs of contamination |
| Oil Leaks | Yes |
| Oil Leak Notes | Dried oil seepages seen, Other (see comments) |
| Comments | Minor oil leak bottom left side of engine oil pan |

Inspection Report (Wheel Loader)

| | |
|--|--|
| <p>Oil Leak Photos</p> |  |
|  | |
| <p>Oil Color / Appearance</p> | <p>3 - Normal Wear & Tear</p> |
| <p>Oil Color / Appearance Notes</p> | <p>Clean oil appearance, no signs of cross contamination, Appropriate oil level</p> |
| <p>Fuel Leaks</p> | <p>No</p> |
| <p>Equipped with DPF (Diesel Particulate Filter)</p> | <p>No</p> |
| <p>Requires DEF (Diesel Exhaust Fluid)</p> | <p>No</p> |
| <p>Overall Engine Appearance</p> | <p>Clean & dry</p> |
| <p>Overall Engine Comments</p> | <p>Overall engine well maintained and no obvious major leaks present. Minor oil leak at oil pan. Engine sounds healthy and works well.</p> |

Drivetrain Inspection Points

Inspection Report (Wheel Loader)

| Drivetrain | |
|---------------------------------------|---|
| Hydrostatic Transmission? | No |
| Transmission Info (Make/Model/Speeds) | Powershift 4 speed |
| Transmission | 3 - Normal Wear & Tear |
| Transmission Condition | No unusual noises or vibrations, Leaking transmission fluid observed, Other (see comments) |
| Comments | Transmission showing signs of small leaks |
| Transmission Photos |    |

Inspection Report (Wheel Loader)

| | | |
|-----------------------|--|--|
| |  | |
| Clutch | 0 | |
| Shift Lever | 3 - Normal Wear & Tear | |
| Shift Lever Condition | Good forward and reverse function | |
| Shift Level Photos |  | |
| Foot Brake | 3 - Normal Wear & Tear | |
| Foot Brake Condition | Good brake function | |
| Foot Brake Photos |  | |
| Inching Brake | 0 | |
| Parking Brake | 3 - Normal Wear & Tear | |

Inspection Report (Wheel Loader)

| | |
|-----------------------------|-----------------------------------|
| Parking Brake Condition | Good brake function |
| Overall Drivetrain Comments | Overall drivetrain operates okay. |

Chassis Inspection Points

| | |
|--------------|--|
| Frame | 3 - Normal Wear & Tear |
| Frame Photos |  |
| |  |
| |  |

Inspection Report (Wheel Loader)

| | |
|----------------------|--|
| |  |
| |  |
| |  |
| <p>Stance</p> | <p>3 - Normal Wear & Tear</p> |

Inspection Report (Wheel Loader)

| | |
|------------------------------|--|
| Stance Photos |  |
| Front Axle Appearance | 3 - Normal Wear & Tear |
| Front Axle Appearance Photos |  |
| |  |

Inspection Report (Wheel Loader)

| | | |
|---|--|--|
| |  | |
| |  | |
| <p>Rear Axle Appearance</p> | <p>3 - Normal Wear & Tear</p> | |
| <p>Rear Axle Appearance Photos</p> |  | |

Inspection Report (Wheel Loader)

| | | |
|---|--|--|
| |  | |
| |  | |
| <p>Articulating Center Pin Appearance</p> | <p>3 - Normal Wear & Tear</p> | |
| <p>Articulating Center Pin Appearance Photos</p> |  | |

Inspection Report (Wheel Loader)

| | | |
|-----------------------------------|--|--|
| |  | |
| Tire Brand | Loadmaster | |
| Tire Size | 17.5 - 25 | |
| Front Left Tire - Ratio Remaining | 70% | |
| Front Left Tire Photos |  | |
| |  | |
| Rear Left Tire - Ratio Remaining | 50% | |

Inspection Report (Wheel Loader)

| | |
|---|--|
| <p>Rear Left Tire Photos</p> |  |
| |  |
| <p>Front Right Tire - Ratio Remaining</p> | <p>30%</p> |
| <p>Front Right Tire Photos</p> |  |

Inspection Report (Wheel Loader)

| | | |
|--|--|--|
| |  | |
| <p>Rear Right Tire - Ratio Remaining</p> | <p>30%</p> | |
| <p>Rear Right Tire Photos</p> |  | |
| <p>Lift Arm</p> | <p>3 - Normal Wear & Tear</p> | |
| <p>Lift Arm Photos</p> |  | |

Inspection Report (Wheel Loader)

| | |
|--|--|
| |  |
| |  |
| <p>Chassis to Arm Pins</p> | <p>3 - Normal Wear & Tear</p> |
| <p>Chassis to Arm Pins Photos</p> |  |

Inspection Report (Wheel Loader)

| | | |
|---------------------------------------|--|--|
| |  | |
| <p>Tilt Linkage</p> | <p>3 - Normal Wear & Tear</p> | |
| <p>Tilt Linkage Photos</p> |  | |
| |  | |
| <p>Tilt Linkage Pins and Bushings</p> | <p>3 - Normal Wear & Tear</p> | |

Inspection Report (Wheel Loader)

Tilt Linkage Pins and Bushings
Photos



Inspection Report (Wheel Loader)

| | | |
|--|--|--|
| |  | |
| <p>Quick Coupler</p> | <p>3 - Normal Wear & Tear</p> | |
| <p>Quick Coupler Photos</p> |  | |
| |  | |
| <p>Quick Coupler to Arms Pins</p> | <p>3 - Normal Wear & Tear</p> | |

Inspection Report (Wheel Loader)

| | | |
|--|---|--|
| <p>Quick Coupler to Arms Pins Photos</p> |  | |
| |  | |
| <p>Overall Chassis</p> | <p>3 - Normal Wear & Tear</p> | |
| <p>Overall Chassis Comments</p> | <p>Overall chassis in good condition with no obvious major repairs needed.</p> | |

Hydraulics Overall Inspection Points

| <h3>Hydraulics Overall</h3> | |
|---|---|
| <p>Wet or Damp Hydraulic Lines / Fittings</p> | <p>Yes</p> |
| <p>Appearance of Hydraulic Lines / Fittings</p> | <p>3</p> |
| <p>Hydraulic Lines / Fittings Condition</p> | <p>Hydraulic lines & fittings are clean and in good condition</p> |

Inspection Report (Wheel Loader)

Appearance of Hydraulic Lines /
Fittings Photos



Inspection Report (Wheel Loader)

| | | |
|--------------------------------------|--|--|
| |  | |
| Unusual Noises (Hydraulic Pump) | No | |
| Hydraulic Pump Notes | No unusual noises heard during operation | |
| External Controls / Levers | 3 | |
| External Controls / Levers Condition | Good function & condition of hydraulic controls | |
| External Controls / Levers Photos |  | |
| |  | |

Hydraulics Cylinders Inspection Points

| | | |
|-----------------------------|---|--|
| Lift Cylinder | Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos. | |
| Lift Cylinder: Mounting Pin | 3 | |

Inspection Report (Wheel Loader)

| | |
|--------------------------|--|
| Lift Cylinder: Oil Leaks | Yes |
| Comments | Seepage leaks at rod seal |
| Lift Cylinder Photos |  |
| |  |
| |  |

Inspection Report (Wheel Loader)




Inspection Report (Wheel Loader)

| | | |
|--------------------------------------|--|--|
| |  | |
| Bucket Cylinder | Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos. | |
| Bucket Cylinder: Mounting Pin | 3 | |
| Bucket Cylinder: Oil Leaks | Yes | |
| Comments | Oil seepage at rod seals | |
| Bucket Cylinder Photos |  | |
| |  | |

Inspection Report (Wheel Loader)

| | | |
|--|---|--|
| |  | |
| |  | |
| Steering Cylinder | Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos. | |
| Steering Cylinder: Mounting Pin | 3 | |
| Steering Cylinder: Oil Leaks | Yes | |
| Comments | Oil seepage at rod seals | |
| Steering Cylinder Photos |  | |

Inspection Report (Wheel Loader)



Bucket Inspection Points

| | |
|--------------------------|---|
| Bucket | 0 |
| Bucket Edge/Shanks/Teeth | 0 |

Functional Test

| | |
|----------------------------------|-----------------------------------|
| Forward & Reverse | 3 - Normal Wear & Tear |
| Turning | 3 - Normal Wear & Tear |
| Lift / Tilt | 3 - Normal Wear & Tear |
| Bucket Functionality | 0 |
| Overall Functional Test Comments | Overall machine functions well. |
| Operating Video | Click to Download |

Overall Assessment

| Overall Assessment | |
|--------------------|---|
| Exterior Rating | 3 |
| Interior Rating | 3 |
| Safety Rating | 3 |
| Quality Rating | 3 |



Inspection Report (Wheel Loader)

| | |
|---------------------------------------|---|
| Functionality Rating | 3 |
| Overall Rating | 3 |
| What's Great About the Machine | Machine well kept and all functions work okay. |
| What Needs Work | Possible engine oil leak at l/s of oil pan. Most cylinders have seepage oil leaks at rod seals. |
| Date/Time | 10-17-2022 |