


Inspection Report (Compact Track Loader)

General Info

Year	2012
Make	CAT
Model	299D
Serial Number	NLC00387
Hour Meter Reading	5,567
Previous Application (e.g., earth moving, mining, demolition, etc)	Pipeline / Electrical Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	10'2"
B. Width (ft and inches)	6'6"
C. Height (ft and inches)	6'11"
Operational Weight (lbs)	11,063



Features and Configuration

Control Station Type	Cab
Bucket	Yes
Bucket Specs	78" wide
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (Compact Track Loader)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)






General Appearance Inspection Points

General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage
Front Photos	

Inspection Report (Compact Track Loader)




	
	
	
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage

Inspection Report (Compact Track Loader)





Rear Photos






Inspection Report (Compact Track Loader)

		
		
<p>Left</p>	<p>3 - Normal Wear & Tear</p>	
<p>Left Condition</p>	<p>No visible damage</p>	
<p>Left Photos</p>		




Inspection Report (Compact Track Loader)

	
	
	
	
Right	3 - Normal Wear & Tear
Right Condition	No visible damage




Inspection Report (Compact Track Loader)

Right Photos	
	
	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage




Inspection Report (Compact Track Loader)

Upper Photos	
	
	
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage

Inspection Report (Compact Track Loader)

Doors / Canopy Latches Photos	
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound, Other (see comments)
Comments	Front step slightly bent
Steps / Ladders Photos	
	

Inspection Report (Compact Track Loader)

		
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	
Handrail Photos		
Glass Condition	3 - Normal Wear & Tear	
Glass Condition Notes	Glass intact, no visible damage	
Glass Condition Photos		




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
Mirrors	3 - Normal Wear & Tear	
Mirror Condition Notes	Mirrors present and intact, no visible damage	
Mirrors Photos		
Lighting System	3 - Normal Wear & Tear	
Lighting System Condition	No visible damage, lighting system is operational	
Lighting System Photos		

Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)



Control Station Inspection Points

Control Station

Serial Number Plate Photo	 <p> MODEL NUMBER 299DXHP PRODUCT IDENTIFICATION NUMBER *CAT0299DKNLC00387* CATERPILLAR INC. PEORIA, IL 61659 USA </p>
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Cabin Photos	 <p> A photograph showing the interior of the operator's cabin. The view is from the operator's perspective, looking forward through the windshield. The cabin features a white ceiling, control panels on either side, and a large window with a blue-tinted grid pattern. </p>

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)

	
	
Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Condition	Seat(s) in good condition, no stains or tears in upholstery
Operator's Seat & Arm Rests Photos	
Seat Belt	3 - Normal Wear & Tear
Seat Belt Condition	Seat belt secures properly. Belt is intact and in good condition
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly




Inspection Report (Compact Track Loader)

Cabin Lights Photos	
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional
Controls & Switches Photos	
	




Inspection Report (Compact Track Loader)

	
	
	
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition

Inspection Report (Compact Track Loader)


Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Other Gauge Activity Photos	
	
Heater & A/C	3 - Normal Wear & Tear
Heater & A/C Condition	Heater and A/C work and transition through full temperature range
Fans / Vents	3 - Normal Wear & Tear
Fans / Vents Condition	Fan vents are functional, in good condition, and move through a full adjustable range of motion

Inspection Report (Compact Track Loader)

Fans / Vents Photos	
	
	
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0



Inspection Report (Compact Track Loader)

Engine Inspection Points




Engine	
Engine Type (Make, Model, Cylinders, Hp)	CAT - 3.8L - 4CYL. - 110HP -
Emissions Tier	Tier 4i
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)

Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Clean & dry appearance, tight connections
Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	

Inspection Report (Compact Track Loader)

		
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Hose Photos		
		

Inspection Report (Compact Track Loader)

	
	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear

Inspection Report (Compact Track Loader)

Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine in great condition with no active leaks found. Engine has been well maintained and sounds healthy.

Drivetrain Inspection Points


Drivetrain

Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in great condition and functioning well. No obvious major issues found.




Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Frame Photos	




Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)

		
		
		
<p>Stance</p>	<p>3 - Normal Wear & Tear</p>	




Inspection Report (Compact Track Loader)

<p>Stance Photos</p>	
<p>Lift Arm</p>	<p>3 - Normal Wear & Tear</p>
<p>Lift Arm Photos</p>	
	




Inspection Report (Compact Track Loader)

		
		
		
Chassis to Arm Pins	3 - Normal Wear & Tear	
Comments	Right side lift arm to center support bracket pin not locked in place	

Inspection Report (Compact Track Loader)

<p>Chassis to Arm Pins Photos</p>		
		
		

Inspection Report (Compact Track Loader)




	
Quick Coupler	3 - Normal Wear & Tear
Quick Coupler Photos	
	
Quick Coupler to Arms Pins	3 - Normal Wear & Tear
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Overall chassis in solid condition, well maintained with no issues found.

Undercarriage Inspection Points





Rubber Track Undercarriage

Roller Frames	3 - Normal Wear & Tear
---------------	------------------------




Inspection Report (Compact Track Loader)

<p>Roller Frames Photos</p>	
	
<p>Track Belt</p>	<p>3 - Normal Wear & Tear</p>
<p>Track Belt Photos</p>	





Inspection Report (Compact Track Loader)

	
	
	
<p>Rubber Belt Drive Lugs</p>	<p>3 - Normal Wear & Tear</p>
<p>Rubber Belt Drive Lugs Photos</p>	




Inspection Report (Compact Track Loader)

		
Track Tensioners	3 - Normal Wear & Tear	
Front Idlers	3 - Normal Wear & Tear	
Front Idlers Photos		
		
Rear Idlers	0	
Track Rollers	3 - Normal Wear & Tear	

Inspection Report (Compact Track Loader)

<p>Track Rollers Photos</p>	
	
	
	
<p>Sprockets</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (Compact Track Loader)

Sprockets Photos		
		
		

Hydraulics Overall Inspection Points

Hydraulics Overall


Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition

Inspection Report (Compact Track Loader)

Appearance of Hydraulic Lines /
Fittings Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)

		
		
Unusual Noises (Hydraulic Pump)	No	
Hydraulic Pump Notes	No unusual noises heard during operation	
External Controls / Levers	3	
External Controls / Levers Condition	Good function & condition of hydraulic controls	
External Controls / Levers Photos		

Inspection Report (Compact Track Loader)






Hydraulics Cylinders Inspection Points

Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder: Mounting Pin	3
Lift Cylinder: Oil Leaks	No
Lift Cylinder Photos	



Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)

		
		
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Bucket Cylinder: Mounting Pin	3	
Bucket Cylinder: Oil Leaks	No	
Bucket Cylinder Photos		

Inspection Report (Compact Track Loader)

	
	
Steering Cylinder	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinder: Mounting Pin	0
Steering Cylinder: Oil Leaks	No

Bucket Inspection Points

Bucket	3 - Normal Wear & Tear
Bucket Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
Bucket Edge / Deflectors	3 - Normal Wear & Tear

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Turning	3 - Normal Wear & Tear
Lift / Tilt	3 - Normal Wear & Tear
Bucket Functionality	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall machine works great. No issues found and all functions operate normal.
Operating Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Machine in solid condition and has been well maintained. Any items that required repairs were fixed by Owner. Machine sounds and runs strong.
What Needs Work	Rear grill minor dents, scuff marks on rear bumper. Some bucket teeth need to be replaced soon. Right side loader arms bracket pin not bolted. Mount plate on pin broke off and pin needs to be replaced. Front step bent.
Date/Time	10-27-2022