


Inspection Report (Compact Track Loader)

General Info

Year	2016
Make	John Deere
Model	333E
Serial Number	296619
Hour Meter Reading	1,335
Previous Application (e.g., earth moving, mining, demolition, etc)	Pipeline / Electrical Construction

Dimensions

Measurement Guide	
A. Length (ft and inches)	12'11"
B. Width (ft and inches)	6'9"
C. Height (ft and inches)	7'1"
Operational Weight (lbs)	11,800 lbs.

Features and Configuration

Control Station Type	Canopy
Bucket	Yes
Bucket Specs	83" wide
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No



OMM Specifications

OMM Specifications


Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
-----------------------	--

Inspection Report (Compact Track Loader)

OMM Spec Photos



Inspection Report (Compact Track Loader)



Exterior 360 Walkaround

Exterior 360 Walkaround

Instructions

Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.

Must have shots to capture:


- Front
- 45 degree corner shot of left front
- 45 degree corner shot of right front
- Left side
- Right side
- Rear
- 45 degree corner shot of left rear
- 45 degree corner shot of right rear

Tips for good photos:

- Move the equipment into a open area without any visual distractions or other equipment in the background

Inspection Report (Compact Track Loader)

Exterior Walkaround Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)





General Appearance Inspection Points

General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage

Inspection Report (Compact Track Loader)

Front Photos



Inspection Report (Compact Track Loader)

	
	
	
Rear	3 - Normal Wear & Tear
Rear Condition	No visible damage

Inspection Report (Compact Track Loader)

Rear Photos



Inspection Report (Compact Track Loader)

	
	
Left	3 - Normal Wear & Tear
Left Condition	No visible damage
Left Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
Right	3 - Normal Wear & Tear
Right Condition	No visible damage
Right Photos	
	

Inspection Report (Compact Track Loader)

	
	
	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment

Inspection Report (Compact Track Loader)

Body Panels Photos	
	
	
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage

Inspection Report (Compact Track Loader)

Doors / Canopy Latches Photos	
Steps / Ladders	0
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Handrail Photos	
Glass Condition	0
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage

Inspection Report (Compact Track Loader)

Mirrors Photos	
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational
Lighting System Photos	
	

Inspection Report (Compact Track Loader)



Control Station Inspection Points

Control Station

Serial Number Plate Photo




Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling, Other (see comments)
Comments	Top cabin sunroof window missing half (broken)

Inspection Report (Compact Track Loader)

Operator Cabin Photos



Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
	
Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Condition	Seat(s) have minor surface staining or small tears, Other (see comments)
Comments	Seat in good shape minor tear
Operator's Seat & Arm Rests Photos	

Inspection Report (Compact Track Loader)

	
	
	
Seat Belt	3 - Normal Wear & Tear
Seat Belt Condition	Seat belt shows limited functionality or does not secure properly

Inspection Report (Compact Track Loader)

Seat Belt Photos	
	
Cabin Lights	3 - Normal Wear & Tear
Cabin Lights Condition	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
Cabin Lights Photos	
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional, Other (see comments)
Comments	Electrical lockout switches functioning properly

Inspection Report (Compact Track Loader)

<p>Safety Lock Out / Stop Photos</p>	
	
<p>Controls & Switches</p>	<p>3 - Normal Wear & Tear</p>
<p>Controls & Switches Condition</p>	<p>All switches are installed and functional</p>
<p>Controls & Switches Photos</p>	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

	
	
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition
Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition

Inspection Report (Compact Track Loader)

Other Gauge Activity Photos	
	
	
Heater & A/C	0
Fans / Vents	0
Travel Alarm	2 - Above Average Wear
Travel Alarm Condition	System is configured but not operating correctly
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0

Inspection Report (Compact Track Loader)

Fire Extinguisher	0
First Aid Kit	0

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Yanmar- 4TNV94CHT - 4 Cyl. - 96 HP.
Emissions Tier	Tier 4i
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
		
		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	

Inspection Report (Compact Track Loader)


Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	
	

Inspection Report (Compact Track Loader)


		
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Belt Photos		
		
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	

Inspection Report (Compact Track Loader)

Hose Photos



Inspection Report (Compact Track Loader)

	
	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear

Inspection Report (Compact Track Loader)

Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine well maintained and engine compartment looks clean. No obvious major defects found.

Drivetrain Inspection Points

Drivetrain

Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear

Inspection Report (Compact Track Loader)

Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain works well.

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Frame Photos	
	
	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
		
<p>Stance</p>	<p>3 - Normal Wear & Tear</p>	
<p>Stance Photos</p>		


Inspection Report (Compact Track Loader)

		
Lift Arm	3 - Normal Wear & Tear	
Lift Arm Photos		
		

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)



Chassis to Arm Pins

3 - Normal Wear & Tear

Inspection Report (Compact Track Loader)

Chassis to Arm Pins Photos



Inspection Report (Compact Track Loader)

		
		
Quick Coupler	3 - Normal Wear & Tear	
Comments	Right side tilt cylinder pin to quick coupler loose	
Quick Coupler Photos		
		

Inspection Report (Compact Track Loader)

Quick Coupler to Arms Pins	2 - Above Average Wear
Comments	Right side pin needs attention
Quick Coupler to Arms Pins Photos	
	
	
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Overall machines chassis intact and no major issues found.

Undercarriage Inspection Points

Rubber Track Undercarriage

Roller Frames	3 - Normal Wear & Tear
---------------	------------------------

Inspection Report (Compact Track Loader)

Roller Frames Photos	
	
Track Belt	3 - Normal Wear & Tear
Comments	Track belts have less than 50% tread left
Track Belt Photos	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
Rubber Belt Drive Lugs	3 - Normal Wear & Tear	
Rubber Belt Drive Lugs Photos		
		
Track Tensioners	3 - Normal Wear & Tear	
Front Idlers	3 - Normal Wear & Tear	

Inspection Report (Compact Track Loader)

<p>Front Idlers Photos</p>		
		
		
		
<p>Rear Idlers</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (Compact Track Loader)

<p>Rear Idlers Photos</p>		
		
		

Inspection Report (Compact Track Loader)

		
<p>Track Rollers</p>	<p>3 - Normal Wear & Tear</p>	
<p>Track Rollers Photos</p>		
		
<p>Sprockets</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (Compact Track Loader)

Sprockets Photos



Inspection Report (Compact Track Loader)



Hydraulics Overall Inspection Points

Hydraulics Overall

Wet or Damp Hydraulic Lines / Fittings	Yes
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Appearance of Hydraulic Lines / Fittings Photos	
	

Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)

		
Unusual Noises (Hydraulic Pump)	No	
Hydraulic Pump Notes	No unusual noises heard during operation	
External Controls / Levers	3	
External Controls / Levers Condition	Good function & condition of hydraulic controls	
External Controls / Levers Photos		
		

Inspection Report (Compact Track Loader)



Hydraulics Cylinders Inspection Points

Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder: Mounting Pin	3
Lift Cylinder: Oil Leaks	Yes
Comments	Right side lift cylinder showing signs of seepage, oil dirt buildup, (no active leaks seen)
Lift Cylinder Photos	 

Inspection Report (Compact Track Loader)

	
	
	
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Bucket Cylinder: Mounting Pin	3
Bucket Cylinder: Oil Leaks	No

Inspection Report (Compact Track Loader)

Bucket Cylinder Photos



Inspection Report (Compact Track Loader)

	
	
Steering Cylinder	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinder: Mounting Pin	0
Steering Cylinder: Oil Leaks	No
Comments	Boom steer cylinder

Bucket Inspection Points

Bucket	3 - Normal Wear & Tear
Bucket Photos	

Inspection Report (Compact Track Loader)

		
		
Bucket Edge / Deflectors	3 - Normal Wear & Tear	

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Turning	3 - Normal Wear & Tear
Lift / Tilt	3 - Normal Wear & Tear
Bucket Functionality	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall all machines functions work well with no obvious issues found.
Operating Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3



Inspection Report (Compact Track Loader)

What's Great About the Machine	Machine well taken care of (serviced frequently as required). All main functions work properly and no major repairs needed to put this machine to work. No active leaks found from engine, hydraulics or drive system. Undercarriage in solid condition. Implements l'm great shape.
What Needs Work	Right side main lift cylinder showing signs of seepage. (May need to be resealed soon). Track tread below 50% and will need to be replaced soon. Right side bucket tilt cylinder to coupler loose. Engine service recommended based on time not hours. Top sunroof cover needs to be repaired.
Date/Time	10-27-2022