


## Inspection Report (Compact Track Loader)

### General Info

Year	2015
Make	John Deere
Model	333E
Serial Number	279331
Hour Meter Reading	1,704
Previous Application (e.g., earth moving, mining, demolition, etc)	Pipeline / Electrical Construction

### Dimensions

Measurement Guide	
A. Length (ft and inches)	12'11"
B. Width (ft and inches)	6'9"
C. Height (ft and inches)	7'1"
Operational Weight (lbs)	11,800 LBS.



### Features and Configuration

Control Station Type	Canopy
Bucket	Yes
Bucket Specs	84" wide
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

### Exterior 360 Walkaround

### Exterior 360 Walkaround

## Inspection Report (Compact Track Loader)

<b>Instructions</b>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul>
<b>Exterior Walkaround Photos</b>	
	

### Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




### Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




## Inspection Report (Compact Track Loader)



### General Appearance Inspection Points

#### General Appearance




Front	3 - Normal Wear & Tear
Front Condition	No visible damage
Front Photos	

**Inspection Report (Compact Track Loader)**








### Inspection Report (Compact Track Loader)

		
Rear	3 - Normal Wear & Tear	
Rear Condition	No visible damage	
Rear Photos		
		

Inspection Report (Compact Track Loader)






### Inspection Report (Compact Track Loader)

	
	
<b>Left</b>	3 - Normal Wear & Tear
<b>Left Condition</b>	No visible damage
<b>Left Photos</b>	




Inspection Report (Compact Track Loader)






### Inspection Report (Compact Track Loader)

	
<b>Right</b>	3 - Normal Wear & Tear
<b>Right Condition</b>	No visible damage
<b>Right Photos</b>	
	




### Inspection Report (Compact Track Loader)

	
	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage
Upper Photos	

## Inspection Report (Compact Track Loader)




	
<b>Body Panels (Any Rust Damage?)</b>	3 - Normal Wear & Tear
<b>Body Panel Condition</b>	Some panel misalignment observed, Visible chipped paint or dents, Other (see comments)
<b>Comments</b>	Rear engine body panels bent on top side and slightly misaligned
<b>Body Panels Photos</b>	
	

## Inspection Report (Compact Track Loader)


	
<b>Doors / Canopy Latches</b>	3 - Normal Wear & Tear
<b>Doors / Canopy Latches Condition</b>	No visible damage
<b>Doors / Canopy Latches Photos</b>	
<b>Steps / Ladders</b>	3 - Normal Wear & Tear
<b>Steps / Ladders Condition</b>	Steps/ladders are fully intact and appear structurally sound
<b>Steps / Ladders Photos</b>	
<b>Handrails</b>	3 - Normal Wear & Tear
<b>Handrails Condition</b>	Handrails are fully intact and appear structurally sound



## Inspection Report (Compact Track Loader)

Handrail Photos	
	
Glass Condition	0
Mirrors	0
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational
Lighting System Photos	

## Inspection Report (Compact Track Loader)



### Control Station Inspection Points

#### Control Station

Serial Number Plate Photo	
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

### Inspection Report (Compact Track Loader)

Operator Cabin Photos






Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)






## Inspection Report (Compact Track Loader)

Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Condition	Seat(s) have minor surface staining or small tears
Operator's Seat & Arm Rests Photos	
	
	
Seat Belt	3 - Normal Wear & Tear
Seat Belt Condition	Seat belt secures properly. Belt is intact and in good condition

## Inspection Report (Compact Track Loader)




<b>Seat Belt Photos</b>	
<b>Cabin Lights</b>	3 - Normal Wear & Tear
<b>Cabin Lights Condition</b>	Cabin lights are installed with all light covers in place, bulbs are installed and working properly
<b>Cabin Lights Photos</b>	
<b>Safety Lock Out / Stop</b>	3 - Normal Wear & Tear
<b>Safety Lock Out / Stop Condition</b>	Safety lock out device is present, in good condition, and functional
<b>Safety Lock Out / Stop Photos</b>	

### Inspection Report (Compact Track Loader)



	
<b>Controls &amp; Switches</b>	3 - Normal Wear & Tear
<b>Controls &amp; Switches Condition</b>	All switches are installed and functional
<b>Controls &amp; Switches Photos</b>	
	



### Inspection Report (Compact Track Loader)

	
	
	
<b>Hour Meter Activity</b>	3 - Normal Wear & Tear
<b>Hour Meter Condition</b>	Hour meter is functional and in good condition




## Inspection Report (Compact Track Loader)

Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Other Gauge Activity Photos	
Heater & A/C	0
Fans / Vents	0
Travel Alarm	3 - Normal Wear & Tear
Travel Alarm Condition	Travel alarm is installed and functioning as expected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

## Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Yanmar - 4TNV94CHT - 4 CYL. - 96HP
Emissions Tier	Tier 4i
Engine Serial Number	CH4K31H006312

### Inspection Report (Compact Track Loader)

Engine Fuel Type	Diesel
Engine Photos	
	
	

Inspection Report (Compact Track Loader)





Inspection Report (Compact Track Loader)






Inspection Report (Compact Track Loader)



## Inspection Report (Compact Track Loader)


	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks

## Inspection Report (Compact Track Loader)



Radiator Photos	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Belt Photos	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Hose Photos	



Inspection Report (Compact Track Loader)



## Inspection Report (Compact Track Loader)

Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry, Dusty & dry

## Inspection Report (Compact Track Loader)



<b>Overall Engine Comments</b>	Overall engine well maintained, sounds healthy and no active leaks found. Engine has been serviced periodically as needed. Check engine light observed 3719.16, related to DPF filter being restricted.
--------------------------------	---

### Drivetrain Inspection Points




#### Drivetrain

<b>Hydrostatic Transmission?</b>	Yes
<b>2 Speed?</b>	Yes
<b>Hydrostatic Drive Configuration</b>	Split Transmission
<b>Drive Motors</b>	2 - Above Average Wear
<b>Hydrostatic Parking Brake</b>	3 - Normal Wear & Tear
<b>Hydrostatic Parking Brake Condition</b>	Good brake function
<b>Overall Drivetrain Comments</b>	Overall drivetrain in good condition. All drivetrain components working well with no obvious major repairs needed.




### Chassis Inspection Points

<b>Frame</b>	3 - Normal Wear & Tear
<b>Frame Photos</b>	
	

**Inspection Report (Compact Track Loader)**

	
	
	
<p><b>Stance</b></p>	<p>3 - Normal Wear &amp; Tear</p>

### Inspection Report (Compact Track Loader)

<p>Stance Photos</p>	
	
<p>Lift Arm</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Lift Arm Photos</p>	




Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




### Inspection Report (Compact Track Loader)




	
<p>Chassis to Arm Pins</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Chassis to Arm Pins Photos</p>	
	






Inspection Report (Compact Track Loader)




**Inspection Report (Compact Track Loader)**

		
<p><b>Quick Coupler</b></p>	<p>3 - Normal Wear &amp; Tear</p>	
<p><b>Quick Coupler Photos</b></p>		
		

**Inspection Report (Compact Track Loader)**



		
		
<p><b>Quick Coupler to Arms Pins</b></p>	<p>3 - Normal Wear &amp; Tear</p>	
<p><b>Quick Coupler to Arms Pins Photos</b></p>		

## Inspection Report (Compact Track Loader)

	
<b>Overall Chassis</b>	3 - Normal Wear & Tear
<b>Overall Chassis Comments</b>	Overall chassis is solid condition. Everything is holding together with no obvious major repairs needed.

## Undercarriage Inspection Points

### Rubber Track Undercarriage

<b>Roller Frames</b>	3 - Normal Wear & Tear
<b>Roller Frames Photos</b>	
	
<b>Track Belt</b>	3 - Normal Wear & Tear
<b>Comments</b>	Tracks like new

## Inspection Report (Compact Track Loader)




Track Belt Photos






Inspection Report (Compact Track Loader)



### Inspection Report (Compact Track Loader)




	
<p>Rubber Belt Drive Lugs</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Rubber Belt Drive Lugs Photos</p>	
	

### Inspection Report (Compact Track Loader)




		
<b>Track Tensioners</b>	3 - Normal Wear & Tear	
<b>Front Idlers</b>	3 - Normal Wear & Tear	
<b>Front Idlers Photos</b>		
		






### Inspection Report (Compact Track Loader)

		
<p>Rear Idlers</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Rear Idlers Photos</p>		
		


### Inspection Report (Compact Track Loader)

		
<p>Track Rollers</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Track Rollers Photos</p>		
		

### Inspection Report (Compact Track Loader)

		
<p>Sprockets</p>	<p>3 - Normal Wear &amp; Tear</p>	
<p>Sprockets Photos</p>		
		

## Inspection Report (Compact Track Loader)



### Hydraulics Overall Inspection Points

#### Hydraulics Overall

Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition

### Inspection Report (Compact Track Loader)

Appearance of Hydraulic Lines /  
Fittings Photos






Inspection Report (Compact Track Loader)



Inspection Report (Compact Track Loader)




### Inspection Report (Compact Track Loader)


		
<b>Unusual Noises (Hydraulic Pump)</b>	No	
<b>Hydraulic Pump Notes</b>	No unusual noises heard during operation	
<b>External Controls / Levers</b>	3	
<b>External Controls / Levers Condition</b>	Good function & condition of hydraulic controls	
<b>External Controls / Levers Photos</b>		
		



## Inspection Report (Compact Track Loader)



### Hydraulics Cylinders Inspection Points

Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder: Mounting Pin	3
Lift Cylinder: Oil Leaks	No
Lift Cylinder Photos	




Inspection Report (Compact Track Loader)




Inspection Report (Compact Track Loader)





### Inspection Report (Compact Track Loader)

	
<b>Bucket Cylinder</b>	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.
<b>Bucket Cylinder: Mounting Pin</b>	3
<b>Bucket Cylinder: Oil Leaks</b>	No
<b>Bucket Cylinder Photos</b>	
	

### Inspection Report (Compact Track Loader)

		
Steering Cylinder	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Steering Cylinder: Mounting Pin	0	

### Bucket Inspection Points

Bucket	3 - Normal Wear & Tear	
Bucket Photos		
		
Bucket Edge / Deflectors	3 - Normal Wear & Tear	

### Functional Test

Forward & Reverse	3 - Normal Wear & Tear	
-------------------	------------------------	--

## Inspection Report (Compact Track Loader)

Turning	3 - Normal Wear & Tear
Lift / Tilt	3 - Normal Wear & Tear
Bucket Functionality	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall machines implement functions operate well. Powertrain works well too. Engine and hydraulics sound healthy.
Operating Video	<a href="#">Click to Download</a>

## Overall Assessment

### Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Machine has a great appearance in and out. This unit has been well maintained and it operates well. The tracks are like new and the undercarriage l'm great condition.
What Needs Work	Rear engine outer panels bent at topside. Active engine codes for dpf may need to be cleared by performing a parked regen or there may be an issue with the after treatment electronics.
Any Additional Info from the Seller?	Seller to confirm active codes gameplan for repairs needed or just a simple parked regen.
Date/Time	10-27-2022