

Inspection Report (On-Highway Dump Truck)

General Info

Year	2011
Make	Peterbilt
Model	367
Serial Number	1NP - TLUOX - 6 - BD127980
Truck Odometer Reading	408,807
Previous Application (e.g., earth moving, mining, demolition, etc)	Asphalt Construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	30'2" (from back of strong arm axle to front bumper)
Width (ft and inches)	8'2"
Height (ft and inches)	12'10"
Wheelbase (ft and inches)	20'8"
GVWR (lbs)	66,000 LBS.



Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans mounted Chelsea Pump
Engine Brake	Yes
Differential Lock	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Dump Truck)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



General Appearance Inspection Points

General Appearance




Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Other (see comments)
Comments	Small front bumper dent at center

Inspection Report (On-Highway Dump Truck)




Front Photos



Inspection Report (On-Highway Dump Truck)

		
		
Rear	3 - Normal Wear & Tear	
Rear Condition	No visible damage, Other (see comments)	
Comments	normal wear and tear	
Rear Photos		

Inspection Report (On-Highway Dump Truck)

		
		
		
Left	3 - Normal Wear & Tear	
Left Condition	No visible damage, Other (see comments)	
Comments	a few paint chipping at front fender	

Inspection Report (On-Highway Dump Truck)




Left Photos



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

		
		
Right	3 - Normal Wear & Tear	
Right Condition	No visible damage, Other (see comments)	
Right Photos		




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




		
Upper	3 - Normal Wear & Tear	
Upper Condition	No visible damage, Other (see comments)	
Comments	asphalt slurry stained	
Upper Photos		
		
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear	
Body Panel Condition	No visible damage, good paint condition and panel fitment	
Doors / Canopy Latches	3 - Normal Wear & Tear	
Doors / Canopy Latches Condition	No visible damage	

Inspection Report (On-Highway Dump Truck)




Doors / Canopy Latches Photos



Inspection Report (On-Highway Dump Truck)

	
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Steps / Ladders Photos	
	

Inspection Report (On-Highway Dump Truck)




	
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Handrail Photos	
	
Glass Condition	3 - Normal Wear & Tear
Glass Condition Notes	Glass intact, no visible damage

Inspection Report (On-Highway Dump Truck)




Glass Condition Photos



Inspection Report (On-Highway Dump Truck)

	
	
	
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage

Inspection Report (On-Highway Dump Truck)

Mirrors Photos	
	
	
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational

Inspection Report (On-Highway Dump Truck)

Lighting System Photos



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Cab Inspection Points

On Highway - Cab

Serial Number Plate Photo



Operator Cabin

3 - Normal Wear & Tear

Inspection Report (On-Highway Dump Truck)

Operator Cabin Photos






Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
		
		
Operator's Seat & Arm Rests	3 - Normal Wear & Tear	




Inspection Report (On-Highway Dump Truck)

<p>Operator's Seat & Arm Rests Photos</p>	
	
	
<p>Seat Belt</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (On-Highway Dump Truck)

<p>Seat Belt Photos</p>	
<p>Cabin Lights</p>	<p>3 - Normal Wear & Tear</p>
<p>Cabin Lights Photos</p>	
	




Inspection Report (On-Highway Dump Truck)

	
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Photos	
	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




		
		
Odometer Activity	3 - Normal Wear & Tear	
Odometer Activity Photos		
Other Gauge Activity	3 - Normal Wear & Tear	

Inspection Report (On-Highway Dump Truck)


Other Gauge Activity Photos



Inspection Report (On-Highway Dump Truck)


		
Heater & A/C	3 - Normal Wear & Tear	
Heater & A/C Photos		
Fans / Vents	3 - Normal Wear & Tear	
Fans / Vents Photos		

Inspection Report (On-Highway Dump Truck)

		
Horn	3 - Normal Wear & Tear	
Reverse Alarm / Backup Signal	3 - Normal Wear & Tear	
Backup Camera	0	
Other Electronic Devices	0	
Fire Extinguisher	0	
First Aid Kit	0	

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	CAT - C13 - 6CYL. - 450HP - 12.5L	
Emissions Tier	Tier 4i	
Engine Serial Number	N/A	
Engine Fuel Type	Diesel	
Engine Photos		

Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

		
		
Blow-by (Visual Observation Check)	No	
Unusual Noises (Upon Start-up, Idle, Shutdown)	No	
Unusual Noise Notes	No unusual noises heard	
Engine Smoke (Upon Start-up, Idle, Shutdown)	No	
Engine Smoke Notes	No engine smoke issues observed	
Engine Exhaust Color	Clear	
Battery	4 - Like New, Recently Replaced	
Battery Condition	Like new, recently replaced	




Inspection Report (On-Highway Dump Truck)

Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	

Inspection Report (On-Highway Dump Truck)

	
	
	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension




Inspection Report (On-Highway Dump Truck)

Belt Photos	
	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Hose Photos	




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)

	
	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard


Inspection Report (On-Highway Dump Truck)

Water Pump Photos	
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	Yes
Oil Leak Notes	Wet areas with drops forming due to oil leakage, Other (see comments)
Comments	small oil leak observed around bell housing & Small oil leak at front left side of engine
Oil Leak Photos	
	

Inspection Report (On-Highway Dump Truck)


		
Oil Color / Appearance	3 - Normal Wear & Tear	
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level	
Fuel Leaks	No	
Equipped with DPF (Diesel Particulate Filter)	Yes	
DPF Condition	3 - Normal Wear & Tear	
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated	
DPF Photos		
		

Inspection Report (On-Highway Dump Truck)




	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry, Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Overall engine well maintained. A few small leaks observed.

Drivetrain Inspection Points




Drivetrain

Transmission Info (Make/Model)	Eaton 10 Speed Manual Transmission
Drive Type	4X2
Overdrive	N/A
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations
Transmission Condition Photos	




Inspection Report (On-Highway Dump Truck)

		
		
		
Clutch	3 - Normal Wear & Tear	
Clutch Condition	Clutch is functioning as expected	
Shift Lever	3 - Normal Wear & Tear	
Shift Lever Condition	Good forward and reverse function	




Inspection Report (On-Highway Dump Truck)

Shift Lever Photos	
	
Differential	Check condition of the differential(s). Take photos and notes as relevant.
Rear Differential	3 - Normal Wear & Tear
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation
Rear Differential Photos	

Inspection Report (On-Highway Dump Truck)

		
		
		
Front Differential	3 - Normal Wear & Tear	
Front Differential Condition	Dry housing appearance, no unusual noises heard during operation	

Inspection Report (On-Highway Dump Truck)




Front Differential Photos		
		
		
Brake System Type	Air Brakes	
Air Brakes Build Correct Pressure	Yes	
Air Brake System Leaks	No	
Air Brake Hose Condition	3 - Normal Wear & Tear	

Inspection Report (On-Highway Dump Truck)


Air Brake System Photos



Inspection Report (On-Highway Dump Truck)

		
		
		
Foot Brake	3 - Normal Wear & Tear	
Foot Brake Condition	Good brake function	


Inspection Report (On-Highway Dump Truck)

Foot Brake Photos	
Engine Brake Configuration	2 Position
Engine Brake	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall all drivetrain components in good shape and no issues found.

Chassis & Axle Inspection Points

Chassis

Frame

Frame Condition	3
Frame Photos	



Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

Suspension

Suspension	3
Suspension Photos	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

Steering

Steering Components	3
Steering Components Photos	




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

	
	
Steer Axle Condition	3
Steer Axle Photos	

Inspection Report (On-Highway Dump Truck)

Wheels & Tires




Wheels & Hub Condition	3
------------------------	---

Inspection Report (On-Highway Dump Truck)




Wheels & Hub Photos






Inspection Report (On-Highway Dump Truck)

		
		
		
Wheel Seal Leaks	No	
Tire Brand	(Front) Yokohama (Rear) generic recaps	
Tire Size	(Front) 315/80R/22.5 (Rear) 11R22.5	
Front Left Tire - Ratio Remaining	10%	




Inspection Report (On-Highway Dump Truck)

Front Left Tire Photos	
	
Front Right Tire - Ratio Remaining	30%
Front Right Tire Photos	

Inspection Report (On-Highway Dump Truck)

		
Rear Right Tire - Ratio Remaining	50%	
Rear Right Tire Photos		
		



Inspection Report (On-Highway Dump Truck)

		
Rear Left Tire - Ratio Remaining	50%	
Rear Left Tire Photos		
		

Inspection Report (On-Highway Dump Truck)





Brake Components

Brake Shoe Thickness	50%
Comments	front left side low rest okay
Brake Shoe Photos	
	


Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




Overall Chassis Condition

Overall Chassis	3
Overall Chassis Comments	Overall all in good condition
Overall Chassis & Undercarriage Photos	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)




		
		
		
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.	

Addition Axle Inspection


Additional Axle

Instructions	Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos.
Axle Description & Position	Rogue Drop down axle
Steerable?	No

Inspection Report (On-Highway Dump Truck)

Drop Axle?	Yes
Super Dump?	Yes
Weight Rating	12,000Lbs
Axle Condition	3 - Normal Wear & Tear
Axle Condition Photos	
	
	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)

		
Wheels & Tires	3 - Normal Wear & Tear	
Wheels & Tires Photos		
		


Inspection Report (On-Highway Dump Truck)

	
Tire Brand	AmeriSteel
Tire Size	11R22.5
Left Tire(s) Ratio Remaining	50%
Right Tire(s) Ratio Remaining	50%

Additional Inspection Points

On Highway - Dump Truck

Additional Inspection Points: Dump Body, Tailgate, Support & Tarp

Dump Body Make & Material	Rogue
Dump Body Length (ft and inches)	15'
Dump Body Height (ft and inches)	5'3"
Bed Body	3 - Normal Wear & Tear
Bed Body Photos	

Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)

		
Tailgate	3 - Normal Wear & Tear	
Tailgate Photos		
		
Tailgate Latch	3 - Normal Wear & Tear	
Support Frame	3 - Normal Wear & Tear	
Hinge Points	3 - Normal Wear & Tear	




Inspection Report (On-Highway Dump Truck)

Hinge Point Photos		
		
Tarp	3 - Normal Wear & Tear	




Additional Inspection Points: Dump Hydraulics

Hydraulics	Check the condition of the hydraulics. Check lines, hoses, fittings, leaks, function, etc. Note any damage or wear. Take photos.	
Hydraulic Tank	3 - Normal Wear & Tear	
Hydraulic Tank Photos		
Hoses	3 - Normal Wear & Tear	


Inspection Report (On-Highway Dump Truck)

Hose Photos	
	
Hydraulic Cylinders	3 - Normal Wear & Tear
Hydraulic Cylinder Photos	

Inspection Report (On-Highway Dump Truck)

	
	
Cylinder Pins and Bushings	3 - Normal Wear & Tear
Cylinder Pins and Bushings Photos	

Inspection Report (On-Highway Dump Truck)

	
Hydraulic Function	3 - Normal Wear & Tear
Comments	Dump bed lift cylinder retract abnormal

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Engine	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear

Inspection Summary

Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	This truck is in excellent condition simply because it has been well maintained bumper to bumper. No obvious major repairs found in powertrain or suspension. The interior is super clean and the exterior looks great.
What Needs Work	Most tires need to be replaced soon. Front brake shoes need to be replaced soon. Dump body lift cylinder should be further inspected to determine possible hydraulic retract problem.
Date/Time	11-14-2022