

## Inspection Report (On-Highway Dump Truck)

### General Info

Year	2011
Make	Peterbilt
Model	367
Serial Number	1NP - TLUOX - 6 - BD127977
Truck Odometer Reading	443,015
Previous Application (e.g., earth moving, mining, demolition, etc)	Asphalt Construction

### Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	30'2"
Width (ft and inches)	8'2"
Height (ft and inches)	12'10"
Wheelbase (ft and inches)	20'8"
GVWR (lbs)	66,000



### Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
PTO Details	Trans Mounted Muncie
Engine Brake	Yes
Differential Lock	Yes
OMM (Operator & Maintenance Manual)	No
Telematics	No

### Exterior 360 Walkaround

### Exterior 360 Walkaround

## Inspection Report (On-Highway Dump Truck)

<b>Instructions</b>	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> <li>- Front</li> <li>- 45 degree corner shot of left front</li> <li>- 45 degree corner shot of right front</li> <li>- Left side</li> <li>- Right side</li> <li>- Rear</li> <li>- 45 degree corner shot of left rear</li> <li>- 45 degree corner shot of right rear</li> </ul> <p>Tips for good photos:</p> <ul style="list-style-type: none"> <li>- Move the equipment into a open area without any visual distractions or other equipment in the background</li> </ul>
<b>Exterior Walkaround Photos</b>	
	

### Inspection Report (On-Highway Dump Truck)



## Inspection Report (On-Highway Dump Truck)



### General Appearance Inspection Points

#### General Appearance




Front	3 - Normal Wear & Tear
Front Condition	No visible damage

## Inspection Report (On-Highway Dump Truck)

Front Photos






### Inspection Report (On-Highway Dump Truck)

	
	
<b>Rear</b>	3 - Normal Wear & Tear
<b>Rear Condition</b>	No visible damage, Other (see comments)
<b>Rear Photos</b>	

Inspection Report (On-Highway Dump Truck)



### Inspection Report (On-Highway Dump Truck)




		
<b>Left</b>	3 - Normal Wear & Tear	
<b>Left Condition</b>	No visible damage	
<b>Left Photos</b>		
		



### Inspection Report (On-Highway Dump Truck)






### Inspection Report (On-Highway Dump Truck)

		
<b>Right</b>	3 - Normal Wear & Tear	
<b>Right Condition</b>	No visible damage	
<b>Right Photos</b>		
		




Inspection Report (On-Highway Dump Truck)






### Inspection Report (On-Highway Dump Truck)

	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage
Upper Photos	
	




### Inspection Report (On-Highway Dump Truck)

		
		
<b>Body Panels (Any Rust Damage?)</b>	3 - Normal Wear & Tear	
<b>Body Panel Condition</b>	No visible damage, good paint condition and panel fitment	
<b>Doors / Canopy Latches</b>	3 - Normal Wear & Tear	
<b>Doors / Canopy Latches Condition</b>	No visible damage	
<b>Doors / Canopy Latches Photos</b>		




### Inspection Report (On-Highway Dump Truck)

	
<b>Steps / Ladders</b>	3 - Normal Wear & Tear
<b>Steps / Ladders Condition</b>	Steps/ladders are fully intact and appear structurally sound
<b>Steps / Ladders Photos</b>	
	

### Inspection Report (On-Highway Dump Truck)




	
	
<b>Handrails</b>	3 - Normal Wear & Tear
<b>Handrails Condition</b>	Handrails are fully intact and appear structurally sound
<b>Handrail Photos</b>	

### Inspection Report (On-Highway Dump Truck)




		
<b>Glass Condition</b>	3 - Normal Wear & Tear	
<b>Glass Condition Notes</b>	Glass intact, no visible damage	
<b>Glass Condition Photos</b>		
		



### Inspection Report (On-Highway Dump Truck)

	
	
<b>Mirrors</b>	3 - Normal Wear & Tear
<b>Mirror Condition Notes</b>	Mirrors present and intact, no visible damage
<b>Mirrors Photos</b>	

### Inspection Report (On-Highway Dump Truck)

		
<b>Lighting System</b>	3 - Normal Wear & Tear	
<b>Lighting System Condition</b>	No visible damage, lighting system is operational	
<b>Lighting System Photos</b>		
		

Inspection Report (On-Highway Dump Truck)






**Inspection Report (On-Highway Dump Truck)**



**Cab Inspection Points**

**On Highway - Cab**




## Inspection Report (On-Highway Dump Truck)

Serial Number Plate Photo	
Operator Cabin	3 - Normal Wear & Tear
Operator Cabin Photos	
	




Inspection Report (On-Highway Dump Truck)



**Inspection Report (On-Highway Dump Truck)**




	
	
<p><b>Operator's Seat &amp; Arm Rests</b></p>	<p>3 - Normal Wear &amp; Tear</p>
<p><b>Operator's Seat &amp; Arm Rests Photos</b></p>	

**Inspection Report (On-Highway Dump Truck)**

	
	
<b>Seat Belt</b>	3 - Normal Wear & Tear
<b>Seat Belt Photos</b>	
<b>Cabin Lights</b>	3 - Normal Wear & Tear



### Inspection Report (On-Highway Dump Truck)




Cabin Lights Photos	
	
	
Controls & Switches	3 - Normal Wear & Tear

## Inspection Report (On-Highway Dump Truck)




Controls & Switches Photos






### Inspection Report (On-Highway Dump Truck)

	
	
<b>Odometer Activity</b>	3 - Normal Wear & Tear
<b>Odometer Activity Photos</b>	
<b>Other Gauge Activity</b>	3 - Normal Wear & Tear

## Inspection Report (On-Highway Dump Truck)


<p>Other Gauge Activity Photos</p>	
	
<p>Heater &amp; A/C</p>	<p>3 - Normal Wear &amp; Tear</p>
<p>Heater &amp; A/C Photos</p>	
<p>Fans / Vents</p>	<p>3 - Normal Wear &amp; Tear</p>

## Inspection Report (On-Highway Dump Truck)




Fans / Vents Photos		
		
		
Horn	3 - Normal Wear & Tear	
Reverse Alarm / Backup Signal	3 - Normal Wear & Tear	
Backup Camera	3 - Normal Wear & Tear	
Other Electronic Devices	0	
Fire Extinguisher	0	
First Aid Kit	0	

## Engine Inspection Points




## Inspection Report (On-Highway Dump Truck)

Engine	
Engine Type (Make, Model, Cylinders, Hp)	CAT - C13 - 470HP - 6CYL -12.5L
Emissions Tier	Tier 4i
Engine Serial Number	N/A
Engine Fuel Type	Diesel
Engine Photos	

### Inspection Report (On-Highway Dump Truck)




		
		
		
<b>Blow-by (Visual Observation Check)</b>	No	
<b>Unusual Noises (Upon Start-up, Idle, Shutdown)</b>	No	
<b>Unusual Noise Notes</b>	No unusual noises heard	
<b>Engine Smoke (Upon Start-up, Idle, Shutdown)</b>	No	
<b>Engine Smoke Notes</b>	No engine smoke issues observed	
<b>Engine Exhaust Color</b>	Clear	

## Inspection Report (On-Highway Dump Truck)




Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Battery Condition Photos	
	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	



### Inspection Report (On-Highway Dump Truck)

	
	
	
<b>Belts</b>	3 - Normal Wear & Tear
<b>Belt Condition</b>	Belts appear in good condition & alignment with proper tension


## Inspection Report (On-Highway Dump Truck)

<b>Belt Photos</b>	
	
<b>Hoses</b>	3 - Normal Wear & Tear
<b>Hose Condition</b>	Firm, pliant hoses with no signs of wear or leaks
<b>Hose Photos</b>	




Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)





### Inspection Report (On-Highway Dump Truck)

	
<b>Water Pump</b>	3 - Normal Wear & Tear
<b>Water Pump Condition</b>	No unusual pump noises heard
<b>Water Pump Photos</b>	
<b>Cooling System Leaks</b>	No
<b>Coolant Color / Appearance</b>	3 - Normal Wear & Tear
<b>Coolant Color/Appearance Notes</b>	Normal Translucent appearance, no visual signs of contamination
<b>Oil Leaks</b>	Yes
<b>Oil Leak Notes</b>	No oil leaks seen, Dried oil seepages seen
<b>Oil Leak Photos</b>	

### Inspection Report (On-Highway Dump Truck)

		
		
		
<b>Oil Color / Appearance</b>	3 - Normal Wear & Tear	
<b>Oil Color / Appearance Notes</b>	Clean oil appearance, no signs of cross contamination, Appropriate oil level	
<b>Fuel Leaks</b>	No	
<b>Equipped with DPF (Diesel Particulate Filter)</b>	Yes	
<b>DPF Condition</b>	3 - Normal Wear & Tear	
<b>DPF Condition Notes</b>	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated	




## Inspection Report (On-Highway Dump Truck)

DPF Photos	
	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry, Areas of dried seepage seen on engine hoses & components
Overall Engine Comments	Engine clean, minor leakage at oil pan, rear housing area

## Drivetrain Inspection Points




Drivetrain	
Transmission Info (Make/Model)	Eaton Fuller 10 Speed
Drive Type	4X2
Overdrive	No
Transmission	3 - Normal Wear & Tear
Transmission Condition	No unusual noises or vibrations

## Inspection Report (On-Highway Dump Truck)




Transmission Condition Photos	
	
	
<b>Clutch</b>	3 - Normal Wear & Tear
<b>Clutch Condition</b>	Clutch is functioning as expected
<b>Shift Lever</b>	3 - Normal Wear & Tear
<b>Shift Lever Condition</b>	Good forward and reverse function
<b>Differential</b>	Check condition of the differential(s). Take photos and notes as relevant.
<b>Rear Differential</b>	3 - Normal Wear & Tear
<b>Rear Differential Condition</b>	Dry housing appearance, no unusual noises heard during operation



## Inspection Report (On-Highway Dump Truck)

<b>Rear Differential Photos</b>	
	
	
<b>Front Differential</b>	3 - Normal Wear & Tear
<b>Front Differential Condition</b>	Dry housing appearance, no unusual noises heard during operation

## Inspection Report (On-Highway Dump Truck)




<b>Front Differential Photos</b>	
	
	
<b>Brake System Type</b>	Air Brakes
<b>Air Brakes Build Correct Pressure</b>	Yes
<b>Air Brake System Leaks</b>	No
<b>Air Brake Hose Condition</b>	3 - Normal Wear & Tear

### Inspection Report (On-Highway Dump Truck)


Air Brake System Photos



### Inspection Report (On-Highway Dump Truck)

	
	
	
<b>Foot Brake</b>	3 - Normal Wear & Tear
<b>Foot Brake Condition</b>	Good brake function


## Inspection Report (On-Highway Dump Truck)

Foot Brake Photos	
Engine Brake Configuration	2 Position
Engine Brake	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain in good condition. Drivetrain well maintained, most major components in great condition.

## Chassis & Axle Inspection Points

### Chassis


### Frame

Frame Condition	3
Frame Photos	

Inspection Report (On-Highway Dump Truck)



### Inspection Report (On-Highway Dump Truck)




### Suspension

Suspension	3
------------	---

### Inspection Report (On-Highway Dump Truck)

Suspension Photos






Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)



**Inspection Report (On-Highway Dump Truck)**

**Steering**

Steering Components	3
Steering Components Photos	




Inspection Report (On-Highway Dump Truck)





Inspection Report (On-Highway Dump Truck)




Inspection Report (On-Highway Dump Truck)

		
		
		
Steer Axle Condition	3	

### Inspection Report (On-Highway Dump Truck)




Steer Axle Photos	
	

### Wheels & Tires




Wheels & Hub Condition	3
Wheels & Hub Photos	






### Inspection Report (On-Highway Dump Truck)

	
	
	
<b>Tire Brand</b>	(Front) Yokohama (Rear) generic recap
<b>Tire Size</b>	(Front) 315/80R/22.5 (Rear) 11R22.5
<b>Front Left Tire - Ratio Remaining</b>	30%




### Inspection Report (On-Highway Dump Truck)

Front Left Tire Photos	
Front Right Tire - Ratio Remaining	30%
Front Right Tire Photos	
	
Rear Right Tire - Ratio Remaining	30%

**Inspection Report (On-Highway Dump Truck)**

<p>Rear Right Tire Photos</p>		
		
		
<p>Rear Left Tire - Ratio Remaining</p>	<p>10%</p>	

## Inspection Report (On-Highway Dump Truck)

<p>Rear Left Tire Photos</p>	
	
	

### Brake Components


<p>Brake Shoe Thickness</p>	<p>10%</p>
-----------------------------	------------

### Inspection Report (On-Highway Dump Truck)

Brake Shoe Photos



### Inspection Report (On-Highway Dump Truck)



### Overall Chassis Condition



Overall Chassis	3
-----------------	---

## Inspection Report (On-Highway Dump Truck)

Overall Chassis & Undercarriage  
Photos



## Inspection Report (On-Highway Dump Truck)

		
		
<b>Additional Axles</b>	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.	

### Addition Axle Inspection

#### Additional Axle

<b>Instructions</b>	Check the condition of additional axle(s), wheels & tires. Note any damage or wear. Take photos.
<b>Axle Description &amp; Position</b>	Rear Dump Body Mounted Drop Down
<b>Steerable?</b>	No
<b>Drop Axle?</b>	Yes
<b>Super Dump?</b>	Yes
<b>Weight Rating</b>	12,000 Lbs.
<b>Axle Condition</b>	3 - Normal Wear & Tear



### Inspection Report (On-Highway Dump Truck)

Axle Condition Photos



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



**Inspection Report (On-Highway Dump Truck)**




**Wheels & Tires**

3 - Normal Wear & Tear

**Wheels & Tires Photos**




## Inspection Report (On-Highway Dump Truck)

		
Tire Brand	Maxisteel	
Tire Size	11R22.5	
Left Tire(s) Ratio Remaining	70%	
Right Tire(s) Ratio Remaining	70%	

### Additional Inspection Points

#### On Highway - Dump Truck

#### Additional Inspection Points: Dump Body, Tailgate, Support & Tarp

Dump Body Make & Material	Rogue	
Dump Body Length (ft and inches)	15'	
Dump Body Height (ft and inches)	5'3	
Bed Body	3 - Normal Wear & Tear	
Bed Body Photos		

Inspection Report (On-Highway Dump Truck)





### Inspection Report (On-Highway Dump Truck)






Inspection Report (On-Highway Dump Truck)



Inspection Report (On-Highway Dump Truck)



### Inspection Report (On-Highway Dump Truck)




		
<b>Tailgate</b>	3 - Normal Wear & Tear	
<b>Tailgate Photos</b>		
		
<b>Tailgate Latch</b>	3 - Normal Wear & Tear	

### Inspection Report (On-Highway Dump Truck)




Tailgate Latch Photos





**Inspection Report (On-Highway Dump Truck)**

		
		
		
<p><b>Support Frame</b></p>	<p>3 - Normal Wear &amp; Tear</p>	

### Inspection Report (On-Highway Dump Truck)

Support Frame Photos	
	
Hinge Points	3 - Normal Wear & Tear
Hinge Point Photos	

## Inspection Report (On-Highway Dump Truck)

	
Tarp	3 - Normal Wear & Tear
Tarp Photos	

### Additional Inspection Points: Dump Hydraulics

Hydraulics	Check the condition of the hydraulics. Check lines, hoses, fittings, leaks, function, etc. Note any damage or wear. Take photos.
Hydraulic Tank	3 - Normal Wear & Tear
Hoses	3 - Normal Wear & Tear
Hydraulic Cylinders	3 - Normal Wear & Tear
Cylinder Pins and Bushings	3 - Normal Wear & Tear
Hydraulic Function	3 - Normal Wear & Tear
Comments	Hydraulic cylinder operating well

### Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Engine	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Overall Functional Test Comments	Truck fires right up, and travels great. Hydraulic dump bed lift and retract function works great. 3rd axle works well. Tarp functions normal.



## Inspection Report (On-Highway Dump Truck)

Operating Video	<a href="#">Click to Download</a>
-----------------	-----------------------------------

### Inspection Summary

#### Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	This truck is well maintained by a professional, experienced shop that does not cut corners. All their trucks are treated the same and it shows. Very few issues found.
What Needs Work	Few cosmetic issues with clearcoat. Tires need to be replaced soon and some brake shoes getting low.
Date/Time	11-15-2022