

Location: Tim Maus Paving
Menifee, CA

TRUCK AND EQUIPMENT CONSULTING LLC – DUMP TRUCK / TRACTOR

Date
 (Y/M/D) 11/21/2022

Inspector
 Initials T.T.

(Basic Information)	
(Make)	International
(Model)	ProStar Plus N13 6X4 / LF687 day cab
(Serial Number)	3HSDJSNR7EN797547
(Year of Manufacturing)	2014 (built 7/2013)
(Color)	White / Gray
(Mileage/Hours)	255,731 miles / 12,959 Hrs
(Engine)	Navistar N13 12.4L 475Hp I6 TurboDiesel
(Transmission)	Eaton Fuller 10 Spd Manual
(Origin)	Mexico

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

Specification and Dimensions	
Class Rating/GVWR	GVWR =54,000 lbs Class 8 = 33,001+ lbs
Wheelbase / Cab	Wheelbase =209 in
Dump Bed	s/n 11062046 Houston Truck Fabrication 14 Ft (11/6/2015)
Tire Size	Dynatrac/Kaspan Hankook/Roadmaster 295/75R22.5
Front Axle	Front =Meritor MFS14 14,000 lbs
Rear Axle	Rear = Meritor MT40 20,000x2 = 40,000 lbs
Rear Ratio	3:55 rear
Fuel Capacity	x (2) 70 gal tanks Total 140 gal
DOT	CALIF DMV Thru 4/2023
Air Brake	Air Brake yes
Other	Power Tarp, Ditch Gate (manual), Trailer Hitch A/C (working), APSCO Floor Mount Dump Controls

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)		X				Level Stance, Good grille+chrome bumper, Good panel gaps, No damage
	(General Appearance-Rear)		X				Good appearance tailgate, rear bed+hydraulics, straight panels
	(General Appearance-Right)		X	X			Good panel gaps+ fitment Side panel surface cosmetics dump body sides
	(General Appearance-Left)		X	X			Good panel gaps+ fitment Side panel surface cosmetics dump body sides
	(General Appearance-Upper)		X				Good appearance upper surfaces, cab roof, upper dump panels, hood
	(Major / Minor Surface Rust)		X				No Rust Damage
	(Body Panels / Covers – Rust Damage / Cancer)		X				No Panel Damage No Rust Damage or Cancer seen
	(Visible Weld Repairs / Stress Cracks)		X				No weld repairs or patch repairs seen No cracks
	(Glass Condition)		X				Good Glass
	(Chassis / Undercarriage Damage)		X				Good appearance frame rails, chassis+crossmembers Dry No damages
OPERATOR'S COCKPIT	(Operator Cabin)		X				Complete, Solid Floors, Straight panels, Good Appearance No damage
	(Operator Controls and Switches)		X				Complete Good Appearance and Functionality
	(Odometer Activity)		X				Working
	(Other Gauge Activity)		X				Good appearance driver displays+gauges No error or service codes
	(Door / Canopy Latches)		X				Good function
	(Safety – Horn / First Aid Kit)		X				Working
	(Operator Seat Condition)		X				Both Seats Good Condition
	(Other)		X				Accessories working Good function
ENGINE	(Oil Color / Fluid Appearance)		X				Good Clean Oil Appearance
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		X				Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color – White / Blue / Black / Clear)		X				Clear at start up Clear at Operating Temperature
	(Oil Leaks)		X				None seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		X				No smoke issues No Blow By seen
	(Coolant Color / Fluid Appearance)		X				Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		X				No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)		X				None seen
	(Overall Engine Appearance Clean / Wet / Dry)		X				Dry appearance No damage or rust seen
	(Other)		X				

ELECTRICAL	(Lighting System Condition)	X				Working
	(Reverse Alarm / Backup Signal)	X				Working
	(Battery Condition)	X				Good Appearance
	(Other Electric Device Condition)	X				No loose or dangling wires seen
TIRES DUMP BODY	TRACTOR TIRES	X				Front Tires = B
	TRAILER TIRES X2	X				X2 Mid Axle Tires Good = B
	DUMP BODY X2	X				X2 Rear Axle Tires Good = B
	OTHER	X	X			Chrome Center Caps dented, Multiple Tire brands + treads
TRANSMISSION	(Clutch Noise / Function)	X				Good clutch function No noise or chatter
	(Transmission Noise / Function)	X				Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	X				Good Shifter function
	(Other Remarks)	X				Good Tranmssion Function
DIFFERENTIAL	(Rear Diff - Noises ?)	X				No Rear Diff Noises heard
B R A K E S	(Foot Brake)	X				Good
	(AIR BRAKE)	X				Working
	(Parking Brake)	X				Good function
DUMP and HYDRAULICS	LIFT + DUMP	X				Good Dump Lift and Height No Noise or vibration Good Performance
	HYDRAULICS	X				Good Hydraulic function No noises Smooth performance
	PUMP PERFORMANCE	X				Good
	CONTROLS	X				Controls Good response
OPERATION	FORWARD & REVERSE	X				Good Forward and Reverse
	STEERING + BRAKES	X				Good Steering and Brakes
	ENGINE	X				Engine Good Response
	CONTROLS	X				Controls Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	X				Good dry appearance engine, hydraulics, components No rust or damage
	COMMENTS	X	X			Some surface cosmetics on dump front+side panels wheel center caps
	OVERALL PERFORMANCE INSPECTION	X				Good Driving Performance Good engine, steering, brakes,forward+reverse
	COMMENTS	X				Power Tarp good function. Dump body good hydraulic function, No codes

OVERALL EXTERIOR RATING: B/B- QUALITY: B
OVERALL INTERIOR RATING: B SAFETY: B
OVERALL PERFORMANCE: B FUNCTIONALITY: B
OVERALL GRADE EVALUATION: B
FLUID SAMPLE REQUEST (Y/N) n OIL n COOLANT n

TIRES
*A:Remaining Ratio 90% or more
*B:Remaining Ratio 70% or more
*C:Remaining Ratio 50% or more
*D:Remaining Ratio 20% or more
*E:Remaining Ratio 20% or less