


Inspection Report (Skid Steer)

General Info

Year	2017
Make	Bobcat
Model	T 450
Serial Number	AUVP13415
Hour Meter Reading	2,811
Previous Application (e.g., earth moving, mining, demolition, etc)	Demolition Work

Dimensions

Measurement Guide	
A. Length (ft and inches)	10'7" (with bucket attached)
B. Width (ft and inches)	4'7"
C. Height (ft and inches)	6'6"
D. Attachment Width (ft and inches)	60"
Operational Weight (lbs)	6,150 LBS.

Features and Configuration

Control Station Type	Canopy
Bucket	Yes
Bucket Specs	60"
Additional Attachment(s)?	No
Auxiliary Hydraulics	Yes
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	Yes
Telematics	No

OMM Specifications

OMM Specifications

Detail Specifications	Take photos of the detailed spec pages included in the operator's manual
-----------------------	--

Inspection Report (Skid Steer)

Exterior Walkaround Photos

Exterior 360 Walkaround

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)



General Appearance Inspection Points

General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage

Inspection Report (Skid Steer)

Front Photos



Inspection Report (Skid Steer)

		
Rear	3 - Normal Wear & Tear	
Rear Condition	No visible damage, Other (see comments)	
Rear Photos		
		

Inspection Report (Skid Steer)

		
		
Left	3 - Normal Wear & Tear	
Left Condition	No visible damage, Other (see comments)	
Left Photos		

Inspection Report (Skid Steer)

	
	
	
Right	3 - Normal Wear & Tear
Right Condition	No visible damage

Inspection Report (Skid Steer)

Right Photos



Inspection Report (Skid Steer)

	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage
Upper Photos	
	
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment

Inspection Report (Skid Steer)

Body Panels Photos	
	
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Doors / Canopy Latches Photos	
Steps / Ladders	3 - Normal Wear & Tear
Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound, Other (see comments)
Comments	Front step broken

Inspection Report (Skid Steer)

Steps / Ladders Photos	
	
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Handrail Photos	
Glass Condition	3 - Normal Wear & Tear
Glass Condition Notes	Glass intact, no visible damage

Inspection Report (Skid Steer)

Glass Condition Photos	
	
Mirrors	0
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	One or more exterior lights are non-operational, Other (see comments)
Comments	Rear left side light inop. (Missing)
Lighting System Photos	

Inspection Report (Skid Steer)



Control Station Inspection Points

Control Station

Serial Number Plate Photo	
Operator Cabin Overall	3 - Normal Wear & Tear
Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling

Inspection Report (Skid Steer)

Operator Cabin Photos	
	
	
Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Condition	Seat(s) in good condition, no stains or tears in upholstery, Seat(s) have minor surface staining or small tears
Comments	Small tear on bottom part of seat

Inspection Report (Skid Steer)

Operator's Seat & Arm Rests Photos	
Seat Belt	3 - Normal Wear & Tear
Seat Belt Condition	Seat belt secures properly. Belt is intact and in good condition
Seat Belt Photos	
Cabin Lights	0
Safety Lock Out / Stop	3 - Normal Wear & Tear
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional
Safety Lock Out / Stop Photos	
Controls & Switches	3 - Normal Wear & Tear
Controls & Switches Condition	All switches are installed and functional

Inspection Report (Skid Steer)

Controls & Switches Photos



Inspection Report (Skid Steer)

		
Hour Meter Activity	3 - Normal Wear & Tear	
Hour Meter Condition	Hour meter is functional and in good condition	
Hour Meter Activity Photos		
Other Gauge Activity	3 - Normal Wear & Tear	
Other Gauge Condition	All cockpit gauges are functional and in good condition	
Other Gauge Activity Photos		

Inspection Report (Skid Steer)

	
Heater & A/C	0
Fans / Vents	0
Travel Alarm	1 - Service Required
Travel Alarm Condition	System is configured but not operating correctly
Horn	2 - Above Average Wear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

Engine Inspection Points

Engine

Engine Type (Make, Model, Cylinders, Hp)	Bobcat D24NAP - 4 Cyl - 61HP -
Emissions Tier	Tier 4F
Engine Serial Number	6076064
Engine Fuel Type	Diesel
Engine Photos	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced
Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks

Inspection Report (Skid Steer)

Radiator Photos	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension
Belt Photos	
	

Inspection Report (Skid Steer)

		
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Hose Photos		
		

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

	
	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard

Inspection Report (Skid Steer)

Water Pump Photos	
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated
DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Dusty & dry
Overall Engine Comments	Overall engine in well maintained condition.

Drivetrain Inspection Points

Drivetrain

Inspection Report (Compact Track Loader)

Roller Frames Photos



Inspection Report (Compact Track Loader)

	
<p>Track Belt</p>	<p>3 - Normal Wear & Tear</p>
<p>Track Belt Photos</p>	
	

Inspection Report (Compact Track Loader)



Rubber Belt Drive Lugs

3 - Normal Wear & Tear


Rubber Belt Drive Lugs Photos



Inspection Report (Compact Track Loader)

		
		
Track Tensioners	3 - Normal Wear & Tear	
Front Idlers	3 - Normal Wear & Tear	
Rear Idlers	3 - Normal Wear & Tear	
Rear Idlers Photos		

Inspection Report (Compact Track Loader)

		
		
<p>Track Rollers</p>	<p>3 - Normal Wear & Tear</p>	
<p>Track Rollers Photos</p>		
		

Inspection Report (Compact Track Loader)

		
<p>Sprockets</p>	<p>3 - Normal Wear & Tear</p>	
<p>Sprockets Photos</p>		
		

Inspection Report (Skid Steer)

Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Drive Motor Photos	 
Hydrostatic Parking Brake	3 - Normal Wear & Tear
Hydrostatic Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall besides tracks being worn (below 20% track tread left) the powertrain/drivetrain works well. Hydrostatic systems sounds healthy and undercarriage has normal wear and tear.

Chassis Inspection Points

Frame	3 - Normal Wear & Tear
Stance	3 - Normal Wear & Tear
Wheels & Tires	3 - Normal Wear & Tear
Lift Arm	3 - Normal Wear & Tear

Inspection Report (Skid Steer)

Lift Arm Photos



Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

		
		
		
Chassis to Arm Pins	3 - Normal Wear & Tear	
Quick Coupler	3 - Normal Wear & Tear	

Inspection Report (Skid Steer)

Quick Coupler Photos



Inspection Report (Skid Steer)

		
		
Quick Coupler to Arms Pins	3 - Normal Wear & Tear	
Overall Chassis	3 - Normal Wear & Tear	
Overall Chassis Comments	Overall chassis in good condition. Machine well maintained and no major obvious problems with chassis observed.	

Hydraulics Overall Inspection Points

Hydraulics Overall

Wet or Damp Hydraulic Lines / Fittings	No
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition

Inspection Report (Skid Steer)

Appearance of Hydraulic Lines /
Fittings Photos



Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

	
	
	
Unusual Noises (Hydraulic Pump)	No
Hydraulic Pump Notes	No unusual noises heard during operation
External Controls / Levers	3
External Controls / Levers Condition	Good function & condition of hydraulic controls

Inspection Report (Skid Steer)

External Controls / Levers Photos	
	

Hydraulics Cylinders Inspection Points

Lift Cylinder	Check the lift cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Lift Cylinder: Mounting Pin	3
Lift Cylinder: Oil Leaks	No
Comments	Left side lift cylinder has residual oil buildup (possible cylinder reseal may be needed soon)
Lift Cylinder Photos	

Inspection Report (Skid Steer)

		
		
		
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Bucket Cylinder: Mounting Pin	3	
Bucket Cylinder: Oil Leaks	No	

Inspection Report (Skid Steer)

Bucket Cylinder Photos



Inspection Report (Skid Steer)

	
Steering Cylinder	Check the steering cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Steering Cylinder: Mounting Pin	0

Bucket Inspection Points

Bucket Condition	3 - Normal Wear & Tear
Bucket Photos	

Inspection Report (Skid Steer)



Inspection Report (Skid Steer)

Bucket Edge / Deflectors	3 - Normal Wear & Tear
--------------------------	------------------------

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Turning	3 - Normal Wear & Tear
Lift / Tilt	3 - Normal Wear & Tear
Bucket Functionality	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall, machine functions well. All implements work well and Hydraulics sound healthy. Engine sounds strong and well maintained.
Operating Video	Click to Download

Inspection Summary

Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Machine is in good condition all the way around. All powertrain components healthy and no major active leaks observed. Engine compartment in good shape. Hydraulic compartment also in good shape.
What Needs Work	Minor seepage leaks may be coming from hydraulic lines underneath cab. Pressure wash recommended to find out if small leak present underneath cab. Tracks need to be replaced soon. Left side cylinder should be clean and tested to see if small leak exist.
Date/Time	11-17-2022