


Inspection Report (Mini Excavator)

General Info

Year	2015
Make	Kubota
Model	U25
Serial Number	50812
Hour Meter Reading	1,827
Previous Application (e.g., earth moving, mining, demolition, etc)	Equipment Rental

Dimensions

Measurement Guide	
A. Length (ft and inches)	13'7"
B. Width (ft and inches)	4'11"
C. Height (ft and inches)	7'11"
Operational Weight (lbs)	5,625 LBS.

Features and Configuration

Control Station Type	Canopy
Bucket	No
Blade	Yes
Additional Attachment(s)	No
Hydraulic Coupler	No
Auxiliary Hydraulics	Yes
Hydraulic Thumb	No
Heat	No
A/C	No
Radio	No
Backup Camera	No
OMM (Operator & Maintenance Manual)	No
Telematics	No

Exterior Walkaround Photos

Exterior 360 Walkaround

Inspection Report (Mini Excavator)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)



General Appearance Inspection Points

General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage, Other (see comments)
Comments	Normal wear and tear scuff marks

Inspection Report (Mini Excavator)

Front Photos



Inspection Report (Mini Excavator)

	
	
	
Rear	2 - Above Average Wear
Rear Condition	No visible damage, Other (see comments)
Comments	Normal wear and tear scuff marks

Inspection Report (Mini Excavator)

Rear Photos



Inspection Report (Mini Excavator)

	
	
Left	3 - Normal Wear & Tear
Left Condition	No visible damage, Other (see comments)
Comments	Normal wear and tear scuff marks
Left Photos	

Inspection Report (Mini Excavator)

		
		
Right	3 - Normal Wear & Tear	
Right Condition	No visible damage, Other (see comments)	
Comments	Normal wear and tear scuff marks	
Right Photos		

Inspection Report (Mini Excavator)

	
	
	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage

Inspection Report (Mini Excavator)

Upper Photos	
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	Other (see comments), Visible chipped paint or dents
Body Panels Photos	
	
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage

Inspection Report (Mini Excavator)

Doors / Canopy Latches Photos	 <p>A close-up photograph of a blue metal door latch. To the right of the latch is a warning label with a triangle and exclamation mark icon. The text on the label includes 'CAUTION', 'STOP POSITION', 'CABLE ADJUST', and 'TO AVOID PERSONAL INJURY'. Below this, it says 'Do not open engine hood before stopping engine. Only when engine is stopped by key, open hood and push the stop lever back and hold until the engine stops.' There are also some partially visible instructions like 'STOP 5' and 'STOP 6'.</p>	
	 <p>A close-up photograph of a red metal door latch. The latch is a black, cylindrical component with a keyhole-like opening, mounted on a red-painted metal surface.</p>	
	 <p>A close-up photograph of a blue metal door latch. To the right of the latch is a warning label with a triangle and exclamation mark icon. The text on the label includes 'CAUTION', 'STOP POSITION', 'CABLE ADJUST', and 'TO AVOID PERSONAL INJURY'. Below this, it says 'Do not open engine hood before stopping engine. Only when engine is stopped by key, open hood and push the stop lever back and hold until the engine stops.' There are also some partially visible instructions like 'STOP 5' and 'STOP 6'.</p>	
Steps / Ladders	0	
Handrails	3 - Normal Wear & Tear	
Handrails Condition	Handrails are fully intact and appear structurally sound	

Inspection Report (Mini Excavator)

Handrail Photos	
Glass Condition	0
Mirrors	0
Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational
Lighting System Photos	

Control Station Inspection Points

Control Station

Serial Number Plate Photo	
Operator Cabin Overall	3 - Normal Wear & Tear

Inspection Report (Mini Excavator)

Operator Cabin Overall Condition	Good cabin appearance, solid floors, panels, and ceiling
Operator Cabin Photos	
	
	

Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)

	
	
	
Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Operator's Seat & Arm Rests Condition	Seat(s) is damaged due to sun exposure; fading, cracking observed, Seat(s) has major surface staining or tears

Inspection Report (Mini Excavator)

<p>Operator's Seat & Arm Rests Photos</p>	
	
	
<p>Seat Belt</p>	<p>3 - Normal Wear & Tear</p>
<p>Seat Belt Condition</p>	<p>Seat belt secures properly. Belt is intact and in good condition</p>

Inspection Report (Mini Excavator)

Seat Belt Photos		
Cabin Lights	0	
Safety Lock Out / Stop	3 - Normal Wear & Tear	
Safety Lock Out / Stop Condition	Safety lock out device is present, in good condition, and functional	
Safety Lock Out / Stop Photos		
Controls & Switches	3 - Normal Wear & Tear	
Controls & Switches Condition	All switches are installed and functional	
Controls & Switches Photos		

Inspection Report (Mini Excavator)

	
	
	
Hour Meter Activity	3 - Normal Wear & Tear
Hour Meter Condition	Hour meter is functional and in good condition

Inspection Report (Mini Excavator)

Hour Meter Activity Photos	
Other Gauge Activity	3 - Normal Wear & Tear
Other Gauge Condition	All cockpit gauges are functional and in good condition
Other Gauge Activity Photos	
Heater & A/C	0
Fans / Vents	0
Travel Alarm	2 - Above Average Wear
Travel Alarm Condition	System is configured but not operating correctly
Comments	May be disconnected
Horn	3 - Normal Wear & Tear
Horn Condition	Horn is installed and functioning as expected
Backup Camera	0
Fire Extinguisher	0
First Aid Kit	0

Engine Inspection Points

Engine	
Engine Type (Make, Model, Cylinders, Hp)	Kubota - 1.1L - 3 Cyl. - 20HP
Emissions Tier	Tier 4F

Inspection Report (Mini Excavator)

Engine Serial Number	N/A
Engine Fuel Type	Diesel
Engine Photos	
	
	


Inspection Report (Mini Excavator)

	
	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Like new, recently replaced, Other (see comments)
Comments	Minor corrosion buildup on positive terminal

Inspection Report (Mini Excavator)

Battery Condition Photos		
Radiator	3 - Normal Wear & Tear	
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks	
Radiator Photos		
		

Inspection Report (Mini Excavator)

		
Belts	3 - Normal Wear & Tear	
Belt Condition	Belts appear in good condition & alignment with proper tension	
Belt Photos		
Hoses	3 - Normal Wear & Tear	
Hose Condition	Firm, pliant hoses with no signs of wear or leaks	
Hose Photos		

Inspection Report (Mini Excavator)

	
	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear

Inspection Report (Mini Excavator)

Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	No
Requires DEF (Diesel Exhaust Fluid)	No
Overall Engine Appearance	Clean & dry
Overall Engine Comments	Overall engine well maintained and no active leaks seen.

Drivetrain Inspection Points

Drivetrain

Hydrostatic Transmission?	Yes
2 Speed?	Yes
Hydrostatic Drive Configuration	Split Transmission
Drive Motors	2 - Above Average Wear
Drive Motor Photos	 

Inspection Report (Mini Excavator)

		
		
Hydrostatic Parking Brake	3 - Normal Wear & Tear	
Hydrostatic Parking Brake Condition	Good brake function	
Overall Drivetrain Comments	Overall machine tracks forward and in reverse normally. Two speed functions well.	

Chassis Inspection Points

Boom Condition	3 - Normal Wear & Tear	
Boom Photos		

Inspection Report (Mini Excavator)



Stick Condition

3 - Normal Wear & Tear

Inspection Report (Mini Excavator)

Stick Photos



Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)



Boom Base Pin & Bushings

3 - Normal Wear & Tear

**Boom Base Pin & Bushings
Photos**




Inspection Report (Mini Excavator)



Boom to Stick Pin & Bushings

3 - Normal Wear & Tear

Inspection Report (Mini Excavator)

<p>Boom to Stick Pin & Bushings Photos</p>	
	
	
<p>Stick to Bucket Pin & Bushings</p>	<p>3 - Normal Wear & Tear</p>

Inspection Report (Mini Excavator)

<p>Stick to Bucket Pin & Bushings Photos</p>	
	
<p>Turntable Bearing</p>	<p>3 - Normal Wear & Tear</p>
<p>Turntable Bearing Photos</p>	

Inspection Report (Mini Excavator)

		
<p>Bottom Covers</p>	<p>3 - Normal Wear & Tear</p>	
<p>Comments</p>	<p>Small dent front lower panel</p>	
<p>Bottom Covers Photos</p>		
		

Inspection Report (Mini Excavator)

	
	
Overall Chassis	3 - Normal Wear & Tear
Overall Chassis Comments	Overall machines chassis in good condition with no obvious major repairs needed.

Undercarriage Inspection Points

Rubber Track Undercarriage

Roller Frames	3 - Normal Wear & Tear
Roller Frames Photos	

Inspection Report (Mini Excavator)

		
		
		
<p>Track Belt</p>	<p>3 - Normal Wear & Tear</p>	

Inspection Report (Mini Excavator)

Track Belt Photos



Inspection Report (Mini Excavator)



Rubber Belt Drive Lugs

3 - Normal Wear & Tear

Inspection Report (Mini Excavator)

Rubber Belt Drive Lugs Photos



Inspection Report (Mini Excavator)

		
Track Tensioners	3 - Normal Wear & Tear	
Comments	Tracks holding tension	
Front Idlers	3 - Normal Wear & Tear	
Front Idlers Photos		
		

Inspection Report (Mini Excavator)

	
	
Rear Idlers	0
Track Rollers	3 - Normal Wear & Tear
Track Rollers Photos	

Inspection Report (Mini Excavator)




Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)

		
<p>Sprockets</p>	<p>3 - Normal Wear & Tear</p>	
<p>Sprockets Photos</p>		
		

Inspection Report (Mini Excavator)



Hydraulics Overall Inspection Points

Hydraulics Overall	
Wet or Damp Hydraulic Lines / Fittings	Yes
Appearance of Hydraulic Lines / Fittings	3
Hydraulic Lines / Fittings Condition	Hydraulic lines & fittings are clean and in good condition
Appearance of Hydraulic Lines / Fittings Photos	

Inspection Report (Mini Excavator)




Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)



Inspection Report (Mini Excavator)

		
Unusual Noises (Hydraulic Pump)	No	
Hydraulic Pump Notes	No unusual noises heard during operation	
External Controls / Levers	3	
External Controls / Levers Condition	Good function & condition of hydraulic controls	
External Controls / Levers Photos		
		

Inspection Report (Mini Excavator)



Hydraulics Cylinders Inspection Points

Boom Cylinder	Check the boom cylinder. Note any wear, pitting, discoloration, etc. Take photos.
Boom Cylinder: Mounting Pin	3
Boom Cylinder: Oil Leaks	No



Inspection Report (Mini Excavator)

		
		
Stick Cylinder	Check the stick cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Stick Cylinder: Mounting Pin	3	
Stick Cylinder: Oil Leaks	No	
Stick Cylinder Photos		

Inspection Report (Mini Excavator)

		
Bucket Cylinder	Check the bucket cylinder. Note any wear, pitting, discoloration, etc. Take photos.	
Bucket Cylinder: Mounting Pin	3	
Bucket Cylinder: Oil Leaks	No	
Bucket Cylinder Photos		
		

Inspection Report (Mini Excavator)

	
	
	
Blade	Check the blade. Note any wear, pitting, discoloration, etc. Take photos.
Blade	3

Inspection Report (Mini Excavator)

Blade Photos		
		
		

Blade Inspection Points

Blade Condition	0
-----------------	---

Additional Attachment Inspection Points

Additional Attachment(s)

Additional Attachments

Attachment Type	Bucket quick coupler
Attachment Condition	3 - Normal Wear & Tear

Inspection Report (Mini Excavator)

Attachment Photos	
	

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Swing Table Rotation	3 - Normal Wear & Tear
Boom Lift / Angle / Tilt	3 - Normal Wear & Tear
Blade Functionality	3 - Normal Wear & Tear
Overall Functional Test Comments	Overall all functions operate as expected. Machine travels good both in forward and reverse. Hydraulics work well and engine fires right up.
Operating Video	Click to Download

Overall Assessment

Overall Assessment	
Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3



Inspection Report (Mini Excavator)

What's Great About the Machine	Overall machine functions well. All implements tight and well lubricated at pins. Powertrain works and sounds healthy. No active leaks found & no obvious major repairs required.
What Needs Work	Minor dent bottom front left panel. Possible seepage at hydraulic hoses coming from hydraulic pump. (No active leaks). No bucket with machine.
Date/Time	11-29-2022