

Inspection Report (On-Highway Flatbed Truck)

General Info

Year	2013
Make	Ford
Model	F750
Serial Number	3FRWF7FG1DV019792
Truck Odometer Reading	29,140
Current Inspection / State Cert / DOT	N/A
Previous Application (e.g., earth moving, mining, demolition, etc)	General Construction

Dimensions

Dimensions	Please enter in or verify (if pre-populated) the following dimensions.
Length (ft and inches)	N/A
Width (ft and inches)	N/A
Height (ft and inches)	N/A
Wheelbase (ft and inches)	N/A
GVWR (lbs)	26,000



Features and Configuration

Features	Enter in and/or verify the following information regarding the features of this equipment.
Heat	Yes
A/C	Yes
Radio	Yes
Backup Camera	No
Cruise Control	Yes
PTO	Yes
Engine Brake	Yes
Differential Lock	No
OMM (Operator & Maintenance Manual)	No
Telematics	No
Auxiliary Engine	No
Liftgate	No

Exterior 360 Walkaround

Exterior 360 Walkaround

Inspection Report (On-Highway Flatbed Truck)

Instructions	<p>Take photos of the exterior of the piece of equipment. Capture a full 360 degree walk around and all major components.</p> <p>Must have shots to capture:</p> <ul style="list-style-type: none"> - Front - 45 degree corner shot of left front - 45 degree corner shot of right front - Left side - Right side - Rear - 45 degree corner shot of left rear - 45 degree corner shot of right rear <p>Tips for good photos:</p> <ul style="list-style-type: none"> - Move the equipment into a open area without any visual distractions or other equipment in the background
Exterior Walkaround Photos	
	

Inspection Report (On-Highway Flatbed Truck)




Inspection Report (On-Highway Flatbed Truck)






General Appearance Inspection Points




General Appearance

Front	3 - Normal Wear & Tear
Front Condition	No visible damage
Front Photos	




Inspection Report (On-Highway Flatbed Truck)

		
		
Rear	3 - Normal Wear & Tear	
Rear Condition	No visible damage	
Rear Photos		




Inspection Report (On-Highway Flatbed Truck)

	
	
<p>Left</p>	<p>3 - Normal Wear & Tear</p>
<p>Left Condition</p>	<p>No visible damage</p>
<p>Left Photos</p>	




Inspection Report (On-Highway Flatbed Truck)

	
	
	
<p>Right</p>	<p>3 - Normal Wear & Tear</p>
<p>Right Condition</p>	<p>No visible damage</p>




Inspection Report (On-Highway Flatbed Truck)

Right Photos	
	
	
Upper	3 - Normal Wear & Tear
Upper Condition	No visible damage
Body Panels (Any Rust Damage?)	3 - Normal Wear & Tear
Body Panel Condition	No visible damage, good paint condition and panel fitment
Doors / Canopy Latches	3 - Normal Wear & Tear
Doors / Canopy Latches Condition	No visible damage
Steps / Ladders	3 - Normal Wear & Tear

Inspection Report (On-Highway Flatbed Truck)

Steps / Ladders Condition	Steps/ladders are fully intact and appear structurally sound
Handrails	3 - Normal Wear & Tear
Handrails Condition	Handrails are fully intact and appear structurally sound
Glass Condition	3 - Normal Wear & Tear
Glass Condition Notes	Glass intact, no visible damage
Glass Condition Photos	
Mirrors	3 - Normal Wear & Tear
Mirror Condition Notes	Mirrors present and intact, no visible damage
Mirrors Photos	
	

Inspection Report (On-Highway Flatbed Truck)

Lighting System	3 - Normal Wear & Tear
Lighting System Condition	No visible damage, lighting system is operational
Lighting System Photos	
	
	

Cab Inspection Points

On Highway - Cab

Operator Cabin	3 - Normal Wear & Tear
----------------	------------------------

Inspection Report (On-Highway Flatbed Truck)

Operator Cabin Photos





Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)






Inspection Report (On-Highway Flatbed Truck)

	
	
Operator's Seat & Arm Rests	3 - Normal Wear & Tear
Seat Belt	3 - Normal Wear & Tear
Cabin Lights	3 - Normal Wear & Tear
Controls & Switches	3 - Normal Wear & Tear
Odometer Activity	3 - Normal Wear & Tear
Other Gauge Activity	3 - Normal Wear & Tear
Heater & A/C	3 - Normal Wear & Tear
Fans / Vents	3 - Normal Wear & Tear
Horn	3 - Normal Wear & Tear
Reverse Alarm / Backup Signal	3 - Normal Wear & Tear
Backup Camera	0
Other Electronic Devices	0
Fire Extinguisher	0
First Aid Kit	0



Engine Inspection Points

Engine



Inspection Report (On-Highway Flatbed Truck)

Engine Type (Make, Model, Cylinders, Hp)	Cummins - ISB 6.7L - 6CYL. - 325HP
Emissions Tier	Tier 4F
Engine Serial Number	73579781
Engine Fuel Type	Diesel
Engine Photos	
	
	




Inspection Report (On-Highway Flatbed Truck)

	
	
Blow-by (Visual Observation Check)	No
Unusual Noises (Upon Start-up, Idle, Shutdown)	No
Unusual Noise Notes	No unusual noises heard
Engine Smoke (Upon Start-up, Idle, Shutdown)	No
Engine Smoke Notes	No engine smoke issues observed
Engine Exhaust Color	Clear
Battery	3 - Normal Wear & Tear
Battery Condition	Dusty & dirty appearance



Inspection Report (On-Highway Flatbed Truck)

Battery Condition Photos	
Radiator	3 - Normal Wear & Tear
Radiator Condition	Radiator fins & components appear to be in good working order, no signs of damage or leaks
Radiator Photos	
Belts	3 - Normal Wear & Tear
Belt Condition	Belts appear in good condition & alignment with proper tension



Inspection Report (On-Highway Flatbed Truck)

Belt Photos	
Hoses	3 - Normal Wear & Tear
Hose Condition	Firm, pliant hoses with no signs of wear or leaks
Hose Photos	
	

Inspection Report (On-Highway Flatbed Truck)

	
	
Water Pump	3 - Normal Wear & Tear
Water Pump Condition	No unusual pump noises heard
Cooling System Leaks	No
Coolant Color / Appearance	3 - Normal Wear & Tear
Coolant Color/Appearance Notes	Normal Translucent appearance, no visual signs of contamination
Oil Leaks	No
Oil Color / Appearance	3 - Normal Wear & Tear
Oil Color / Appearance Notes	Clean oil appearance, no signs of cross contamination, Appropriate oil level
Fuel Leaks	No
Equipped with DPF (Diesel Particulate Filter)	Yes
DPF Condition	3 - Normal Wear & Tear
DPF Condition Notes	Filter housing is intact with no signs of damage or malfunction, DPF indicator is not illuminated

Inspection Report (On-Highway Flatbed Truck)


DPF Photos	
Requires DEF (Diesel Exhaust Fluid)	Yes
DEF Tank	3 - Normal Wear & Tear
DEF Tank Condition	Area around DEF tank cap is clean, fluid is clear & appears free of contaminants
DEF Tank Photos	

Inspection Report (On-Highway Flatbed Truck)




		
Overall Engine Appearance	Clean & dry	
Overall Engine Comments	Overall engine well maintained, sounds healthy and no obvious major problems seen.	

Drivetrain Inspection Points




Drivetrain

Transmission Info (Make/Model)	Allison- 6 Speed - Auto Trans.	
Drive Type	4X2	
Overdrive	Yes	
Transmission	3 - Normal Wear & Tear	
Transmission Condition	No unusual noises or vibrations	
Transmission Condition Photos		

Inspection Report (On-Highway Flatbed Truck)

		
		
		
Clutch	0	
Shift Lever	3 - Normal Wear & Tear	
Shift Lever Condition	Good forward and reverse function	
Differential	Check condition of the differential(s). Take photos and notes as relevant.	
Rear Differential	3 - Normal Wear & Tear	
Rear Differential Condition	Dry housing appearance, no unusual noises heard during operation	

Inspection Report (On-Highway Flatbed Truck)

Rear Differential Photos	
	
	
Front Differential	0
Brake System Type	Air Brakes
Air Brakes Build Correct Pressure	Yes
Air Brake System Leaks	Yes
Comments	Major air leak at seat suspension
Air Brake Hose Condition	3 - Normal Wear & Tear

Inspection Report (On-Highway Flatbed Truck)




Air Brake System Photos



Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)




	
	
Foot Brake	3 - Normal Wear & Tear
Foot Brake Condition	Good brake function
Foot Brake Photos	
Engine Brake Configuration	2 Position
Engine Brake	3 - Normal Wear & Tear
Parking Brake	3 - Normal Wear & Tear
Parking Brake Condition	Good brake function
Overall Drivetrain Comments	Overall drivetrain looks solid. No issues seen with major components. Air leak under driver seat observed.

Inspection Report (On-Highway Flatbed Truck)

Chassis & Axle Inspection Points

Chassis & Tires

Frame

Frame Condition	3
Comments	Frame extended and double layered for extra strength .
Frame Photos	
	
	

Inspection Report (On-Highway Flatbed Truck)





Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)




Suspension

Suspension	3
Suspension Photos	
	


Inspection Report (On-Highway Flatbed Truck)



Inspection Report (On-Highway Flatbed Truck)






Steering

Steering Components	3
Steering Components Photos	



Inspection Report (On-Highway Flatbed Truck)




Inspection Report (On-Highway Flatbed Truck)

		
		
		
Steer Axle Condition	3	




Inspection Report (On-Highway Flatbed Truck)

Steer Axle Photos		
		



Wheels & Tires

Wheels & Hub Condition	3
Comments	No oil seal leaks observed from inside rim area
Wheel Seal Leaks	No
Tire Brand	Sumitomo (Front) Michelin (Rear)
Tire Size	275/70R/22.5 (Front & Rear)
Front Left Tire - Ratio Remaining	70%
Front Left Tire Photos	

Inspection Report (On-Highway Flatbed Truck)

	
Front Right Tire - Ratio Remaining	70%
Front Right Tire Photos	
Rear Right Tire - Ratio Remaining	70%
Rear Right Tire Photos	


Inspection Report (On-Highway Flatbed Truck)

		
Rear Left Tire - Ratio Remaining	70%	
Rear Left Tire Photos		

Brake Components

Brake Shoe Thickness	90%	
Comments	Unable to see entire brake shoe (dust cover in place) basing shoe thickness from miles	

Overall Chassis Condition

Overall Chassis	3	
Overall Chassis Comments	Overall chassis in solid condition with no major issues observed.	
Overall Chassis & Undercarriage Photos		

Inspection Report (On-Highway Flatbed Truck)




Inspection Report (On-Highway Flatbed Truck)

	
Additional Axles	Check the condition of all other axles. Specify the position and type of axle. Note any damage or wear. Take photos.

Additional Inspection Points

On-Highway Flatbed Truck

Flatbed Additional Inspection Points

Flatbed Body	Check the condition of the flat bed body. Note any damage or wear. Take photos.
Bed Details (Deck Type, Additional Features)	Bed make N/A
Flatbed Length (ft and inches)	N/A
Flatbed Width (ft and inches)	N/A
Flatbed Body	3
Flatbed Body Photos	

Inspection Report (On-Highway Flatbed Truck)



Tailgate Latch	0
Support Frame	3

Functional Test

Forward & Reverse	3 - Normal Wear & Tear
Steering	3 - Normal Wear & Tear
Engine	3 - Normal Wear & Tear
Controls	3 - Normal Wear & Tear
Overall Functional Test Comments	Truck fired right up and traveled well in forward and reverse. Truck was tested in small parking lot and therefore limited to high speeds or up shifting.

Inspection Summary

Overall Assessment

Exterior Rating	3
Interior Rating	3
Safety Rating	3
Quality Rating	3
Functionality Rating	3
Overall Rating	3
What's Great About the Machine	Machine exterior cab well taken care of and in good shape cosmetically. Cab interior also in nice condition. Truck has very low miles for its year and has plenty of work life left. Rear flatbed has been added with proper structural fabricated frame. (With ramps) Powertrain looks to be well maintained.
What Needs Work	Some rear running lamps inoperable. Major air leak observed in cab underneath driver seat area.
Date/Time	12-08-2022