

Location: Karen Merck  
Plano, TX

**TRUCK AND EQUIPMENT CONSULTING LLC – SEMI TRUCK / TRACTOR**

Date  
 (Y/M/D) 12/28/2022

Inspector  
 Initials A.B.

(Basic Information)	
(Make)	Peterbilt
(Model)	379 6X4
(Serial Number)	1XP5D49X75D847596
(Year of Manufacturing)	2005
(Color)	White
(Mileage/Hours)	514,376.5 miles / 665.3 Hrs
(Engine)	s/n ES79060349 Cummins ISX I6 12.0L 525 Hp TurboDiesel
(Transmission)	Fuller 18 Spd Manual
(Origin)	TX, USA

- A (Near to Brand New or Excellent Condition)  
 B (A little Wear and Good Condition)  
 C (Fair Workable Condition for Hour Meter Reading)  
 D (Workable but minor repair is required)  
 E (Workable but major repair is required)

Specification and Dimensions	
Class Rating/GVWR	GVWR =56,000 lbs Class 8 = 33,001+ lbs
Wheelbase / Cab	Long Wheelbase = 244 in
Chassis Weight	18,049 lbs
Tire Size	Lanvigator 295/75R22.5
Front Axle	Front = Dana Spicer E1202W = 12,000 lbs
Rear Axle	Rear = Dana Spicer DSS40P X2 = 44,000 lbs
Rear Ratio	4:33
Fuel Capacity	2 x 150 gal tanks = Total 300 gal
DOT	CALIF 2019
Air Brake	Air Brake w/Engine Brake switches
Other	63 inch roof, Custom LED Lights, Custom Chrome Stacks Chrome Simulators, Custom Chrome deck trim

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)		X				Level Stance, Good grille+chrome, Good hood gaps, bumper, No damage
	(General Appearance-Rear)		X				Good appearance 5th Wheel crossmembers+hydraulics, straight panels
	(General Appearance-Right )		X				Good Right Side panel gaps+ fitment No dings or paint cosmetics V.Clean
	(General Appearance-Left )		X				Good Left Side panel gaps+ fitment No dings or paint cosmetics V.Clean
	(General Appearance-Upper )		X				Good appearance upper surfaces, cab roof, hood, 5th wheel deck
	(Major / Minor Surface Rust)		X				No Rust
	(Body Panels / Covers – Rust Damage / Cancer)		X				No Panel Damage No Rust Damage or Cancer seen
	(Visible Weld Repairs / Stress Cracks)		X				No weld repairs or patch repairs seen No cracks
	(Glass Condition)		X				Good Glass
	(Chassis / Undercarriage Damage)		X				Good appearance frame rails, chassis+crossmembers Dry No damage
OPERATOR'S COCKPIT	(Operator Cabin)		X	X			Solid Floors, Clean+straight Some open holes missing buttons dash panel
	(Operator Controls and Switches)		X				Complete Good Appearance and Functionality
	(Odometer Activity)		X				Working
	(Other Gauge Activity)			X	X		Good driver displays+gauge function CHECK ENGINE + ABS SERVICE LIT
	(Door / Canopy Latches)		X				Good function
	(Safety – Horn / First Aid Kit)		X				Working
	(Operator Seat Condition)		X				Both Seats Good Condition
	(Other)		X	X			A/C + Accessories working Fifth wheel lock button light broken out
ENGINE	(Oil Color / Fluid Appearance )		X				Good Clean Oil Appearance
	(Noise Upon Startup / Noise Upon Idle / Noise Upon Shut Down)		X				Easy start No unusual noises Smooth Idle
	(Engine Exhaust Color – White / Blue / Black / Clear)		X				Clear at start up Clear at Operating Temperature
	(Oil Leaks )		X				None seen
	(Engine Smoke Upon Startup / Upon Idle / Upon Shut Down)		X				No smoke issues No Blow By seen
	(Coolant Color / Fluid Appearance )		X				Normal appearance
	(Water Pump Noises / Damp Hoses / Coolant Leaks)		X				No pump noises No coolant leaks seen
	(Coolant Leaks from Radiator)		X				None seen
	(Overall Engine Appearance Clean / Wet / Dry)		X				Dry appearance No damage or rust seen
	(Other)			X	X		Windshield Washer Fluid Bottle broken + damaged

ELECTRICAL	(Lighting System Condition)	X				Working
	(Reverse Alarm / Backup Signal)	X				Working
	(Battery Condition)	X				Good Appearance
	(Other Electric Device Condition)	X				No loose or dangling wires seen
TIRES DUMP BODY	FRONT TIRES+RIMS	X				Front Tires = B / B+
	REAR TIRES+RIMS X2	X				X2 Mid Axle Tires Good = B / B+
	BACK TIRES+RIMS X2	X				X2 Rear Axle Tires Good = B / B+
	OTHER	X				Hubs Clean+Dry appearance Good Chrome No dings or dents
TRANSMISSION	(Clutch Noise / Function)	X				Good clutch function No noise or chatter
	(Transmission Noise / Function)	X				Good Transmission function Forward and Reverse
	(Shift Lever Condition & Function)	X				Good Shifter function
	( Other Remarks)	X				Good Tranmssion Function
DIFFERENTIAL	(Rear Diff - Noises ?)	X				No Rear Diff Noises heard
B R A K E S	(Foot Brake)	X				Good
	(AIR BRAKE)	X				Working
	(Parking Brake)	X				Good function
OPERATION	FORWARD & REVERSE	X				Good Forward and Reverse
	STEERING + BRAKES	X				Good Steering and Brakes
	ENGINE	X				Engine Good Response
	CONTROLS	X				Controls Good Function and Response
RATINGS	OVERALL VISUAL INSPECTION	X				Good dry appearance engine, hydraulics, components No rust or damage
	COMMENTS	X	X			Very clean+straight body+chrome Washer bottle broken Dash cosmetics
	OVERALL PERFORMANCE INSPECTION	X				Good Driving Performance Good engine, steering, brakes,forward+reverse
	COMMENTS	X	X			Check Engine Light and ABS Service light lit

OVERALL EXTERIOR RATING:   B        QUALITY:   B/B-  

OVERALL INTERIOR RATING:   B/B-        SAFETY:   B  

OVERALL PERFORMANCE:   B        FUNCTIONALITY:   B  

OVERALL GRADE EVALUATION: **B / B-**

FLUID SAMPLE REQUEST (Y/N)   n   OIL   n   COOLANT   n  

#### TIRES

\*A:Remaining Ratio      90% or more  
 \*B:Remaining Ratio      70% or more  
 \*C:Remaining Ratio      50% or more  
 \*D:Remaining Ratio      20% or more  
 \*E:Remaining Ratio      20% or less