

Location: Karen Merck
Plano, TX

TRUCK AND EQUIPMENT CONSULTING LLC – SEMI TRAILER CHECKLIST

Date (Y/M/D) 12/28/2022
 Inspector Initials A.B.

(Basic Information)	
(Make)	Great Dane
(Model)	Model GPLSAR-245-102
(Serial Number) S/N Plate Missing off title	1GRDM02251M055502
(Year of Manufacturing)	2001 (built 11/2000)
(Color)	Black
(Type)	Flatbed Single Deck
(Dimensions)	Length =45 Ft x Width =102 in
(Coupler)	48 inch

Specification and Dimensions	
Tie downs	Sliding winch load tie downs
Wheels / Tires	Steel Unimount Wheels
Axle Type	Orig Sliding Bogie/Fixed Tandem (set ahead)
King Pin	30 in
Landing Legs	yes
GVWR	76,000 lbs
GAWR	20,000 lbs
Tires	Goodyear/Blacklion 295/75R tires 22.5 x 8.5 rims
Suspension	Air Ride
No of Axles	Closed 2 Axles
Other	Combo Steel + Aluminum Construction 1 locking tool box, 1 storage box

- A (Near to Brand New or Excellent Condition)
- B (A little Wear and Good Condition)
- C (Fair Workable Condition for Hour Meter Reading)
- D (Workable but minor repair is required)
- E (Workable but major repair is required)

		(Check List)					(Remarks)
		A	B	C	D	E	
GENERAL APPEARANCE	(General Appearance-Front)		X	X			Some surface rust + precancer on front panel
	(General Appearance-Rear)						Unable to access rear section Unit parked unable to stage for full access
	(General Appearance-Right)		X	X			Some minor dents and bent trim Cosmetic only
	(General Appearance-Left)		X	X			Some minor dents and bent trim Cosmetic only
	(General Appearance-Upper)		X	X			Wood deck surface Above Average 1 or 2 boards show wear+tear
	(Major / Minor Surface Rust)		X	X			Some surface rust + precancer on front panel
	(Ladders + Walkways)						N/A
	(Lights - Front+Rear)						Unable to access rear section Unit parked unable to stage for full access
PLATFORM APPEARANCE	(Cabinets / Fenders / Splash Guards)		X	X			Tool box some surface cosmetics access door strapped closed
	(Front Section)						3 machines stored on deck unable to fully inspect deck surface
	(Rear Section)						3 machines stored on deck unable to fully inspect deck surface
	(Right Side Section)						3 machines stored on deck unable to fully inspect deck surface
HITCH +SIDE FITTINGS	(Front Appearance)		X				Good appearance No damage seen
	(Rear Appearance)		X				Good appearance No damage seen
	(Right Side Appearance)		X				Good appearance No damage seen
	(Left Side Appearance)		X				Good appearance No damage seen
CHASSIS	(Front Frame Appearance)		X				Good appearance No damage seen
	(Rear Frame Appearance)		X				Good appearance No damage seen
	(Right Frame Appearance)		X				Good appearance No damage seen
	(Left Frame Appearance)		X				Good appearance No damage seen
SUSPENSION	(Air Bag Appearance)		X				Good appearance No damage seen
	(Front Axle)		X				Good appearance No damage seen
	(Rear Axle)		X				Good appearance No damage seen
	(Rust / Overall appearance)		X				No rust seen on suspension or chassis components
WHEELS+ TIRES	(Right Front Wheel Hub+Tire)		X				Tires = B Good appearance Hubs = B Dry No dings or dents
	(Left Front Wheel Hub +Tire)		X				Tires = B Good appearance Hubs = B Dry No dings or dents
	(Right Rear Wheel Hub+Tire)		X				Tires = B Good appearance Hubs = B Dry No dings or dents
	(Left Rear Wheel Hub+Tire)		X				Tires = B Good appearance Hubs = B Dry No dings or dents
PERMITS	AS POSTED						N/A
	AS POSTED						N/A
LANDING LEGS	(Appearance)		X				Landing Legs Good appearance Some minor surface rust cosmetic only
	(Other)		X				Landing Legs Good appearance Some minor surface rust cosmetic only
OTHER	WINCHES						N/A
	HYDRAULICS						N/A
	CONTROLS+SWITCHES						N/A
	OTHER			X			Serial Number Plate Missing
RATINGS	OVERALL VISUAL INSPECTION		X				Some minor surface rust, dents and bent trim Cosmetic wear+tear
	COMMENTS		X	X			Some worn+splintered deck boards, front panel rusty, s/n missing
	OVERALL CHASSIS + FRAME VISUAL INSPECTION						Unable to access rear section Unit parked unable to stage for full access
	COMMENTS						Unable to evaluate mobility, brakes, rear lights, suspension Parked only

OVERALL EXTERIOR RATING: B-/C+/Incomplete
 OVERALL PLATFORM: B-/C+/Incomplete
 OVERALL TIRES+HUBS: B

QUALITY: B-/C+/Incomplete
 SAFETY: B / Incomplete
 CHASSIS+FRAME: B / Incomplete

SHIPPING DIMENSIONS:
 Length: 45 Ft
 Width: 102 inch

OVERALL GRADE EVALUATION: B- / C+ / Incomplete